



Environmental Resources Group

28003 Center Oaks Court • Suite 106 • Wixom, MI • 48393
Phone: 248-773-7986 • Fax: 248-924-3108

August 8, 2013

Mr. Richard Higgins
Norstar Development USA, L.P.
733 Broadway
Albany, New York 12207

**Re: Lead Based Paint Inspection and Risk Assessment
Hikone
2702-2760 Hikone Road, Ann Arbor, Michigan
ERG Project 1128.003**

Dear Mr. Higgins,

Environmental Resources Group, LLC (ERG) has completed the Lead Based Paint Inspection and Risk Assessment (LBP I/RA) for the referenced property in Ann Arbor, Michigan.

ERG contracted American Environmental Consultants (AEC) to perform the work. The LBP I/RA was performed on May 20-22, 2013 by a State of Michigan Certified Lead Inspector/Risk Assessor in general accordance with Michigan Department of Community Health (MDCH) and HUD Guidelines.

The results of the LBP I/RA indicated that no Lead Based Paint or Lead Hazards were identified.

Please refer to the attached AEC report for survey details and analytical results.

Thank you for the opportunity to provide this service to you. If you have any questions, please contact us at 248-773-7986.

Sincerely,
ENVIRONMENTAL RESOURCES GROUP, LLC

Andrew J. Foerg, CPG
Senior Project Manager

Enclosures

LEAD BASED PAINT INSPECTION AND RISK ASSESSMENT

FOR THE PROPERTY LOCATED AT

Hikone
2724 Hikone Rd
Ann Arbor, Michigan 48108

PREPARED FOR

Environmental Resources Group LLC.
28003 Center Oaks Court, Suite 106
Wixom, Michigan 48393

PERFORMED BY

Matthew Rodgers
American Environmental Consultants, LLC
12838 Gavel
Detroit, MI 48227
313-491-2600

PROJECT NUMBER

1459-13006

DATE

5/20-5/22/2013

TABLE OF CONTENTS

1. GENERAL PROVISIONS

- 1.1 INTRODUCTION
- 1.2 PURPOSE
- 1.3 SITE DESCRIPTION
- 1.4 REPORT SUMMARY

2. BACKGROUND

- 2.1 HEALTH EFFECTS
- 2.2 SOURCES OF LEAD
- 2.3 SIMPLE METHODS TO REDUCE LEAD HAZARDS

3. SAMPLING PROCEDURES

- 3.1 LABORATORY
- 3.2 DIRECT-READING ANALYSIS
- 3.3 SURFACE TESTING (PAINT CHIP SAMPLING)
- 3.4 SOIL SAMPLING
- 3.5 DUST WIPE SAMPLING

4. RESULTS

- 4.1 VISUAL INSPECTION
- 4.2 REGULATORY STANDARDS
- 4.3 ANALYTICAL RESULTS
- 4.4 LEAD-BASED PAINT
- 4.5 PAINT CHIP RESULTS
- 4.6 SOIL SAMPLE RESULTS
- 4.7 DUST WIPE RESULTS

5. CONCLUSIONS AND RECOMMENDATIONS

- 5.1 EXISTING LEAD-BASED PAINT HAZARDS
- 5.2 POTENTIAL LEAD-BASED PAINT HAZARDS
- 5.3 LEAD SOIL HAZARDS
- 5.4 LEAD DUST HAZARDS
- 5.5 LEAD BASED PAINT CONTROL OPTIONS
- 5.6 ON-GOING MONITORING SCHEDULE (REEVALUATION AND OWNER VISUAL SURVEY)
- 5.7 COST ESTIMATE
- 5.8 RECOMMENDATIONS FOR FUTURE OPERATIONS AND MAINTENANCE

6. ADDITIONAL RESOURCES

- 6.1 CONTACTS
- 6.2 PUBLICATIONS

APPENDICES

FLOOR PLAN AND SITE LOCATION MAP.....	APPENDIX A
HUD FORMS 5.0 & 5.1.....	APPENDIX B
XRF FIELD DATA SHEET.....	APPENDIX C
PAINT CHIP LABORATORY RESULTS.....	APPENDIX D
OTHER SAMPLE LABORATORY RESULTS.....	APPENDIX E
RISK ASSESSMENT REPORT.....	APPENDIX F
LEAD IN YOUR HOME: A PARENTS REFERENCE GUIDE, INTERIM CONTROLS.....	APPENDIX G

1. GENERAL PROVISIONS

1.1 INTRODUCTION

Matthew Rodgers, of American Environmental Consultants (AEC), LLC, conducted a lead-based paint inspection and risk assessment at Hikone located at 2724 Hikone in Ann Arbor, Michigan on May 20th – May 22nd of 2013. Mr. Rodgers is a certified Lead Inspector and Risk Assessor through the Michigan Department of Community Health, Certification Number P-04247. This property is owned by The Ann Arbor Housing Commission which is located at 727 Miller Ave. in Ann Arbor, Michigan and can be reached at 734-794-6720.

1.2 PURPOSE

The purpose of the risk assessment was to determine the location, type, and severity of existing or potential health hazards at the property associated with exposures to lead and to develop recommendations in response to those hazards. The complex is scheduled for rehabilitation.

The following report details the results of the assessment. The findings of this report will be forwarded to the property owner. The findings of this report must be provided to any purchaser of this property under Federal Law (24 CFR part 35 and 40 CFR part 745) before they become obligated under sales contract. Sellers are also required to distribute an educational pamphlet approved by the Environmental Protection Agency (EPA), entitled *Protect Your from Family Lead in Your Home*, and include standard warning language in their sales contracts to ensure that parents have the information they need to protect their children from lead-based paint hazards. For more information regarding your obligations under federal lead based paint regulations, contact 800-424-LEAD (5323).

1.3 SITE DESCRIPTION

The subject property is owned by The Ann Arbor Housing Commission and is located at 2724 Hikone Rd. in Ann Arbor, Michigan. The subject property consists of 4 6-unit buildings and 1 5-unit building with a community building attached. A total of 18 living units and community building were tested. The general construction material of the building is wood frame. The exterior of the building has wood and aluminum siding. The subject property was built in 1970. See Appendix A for site location and floor plan maps.

1.4 REPORT SUMMARY

**No lead based paint was identified.
No lead based paint hazards were identified.**

Lead-based paint does not necessarily represent a health hazard based solely on its existence in a dwelling. Hazards are based on human exposures to lead-based paint, dust, soil, and water.

2. BACKGROUND

2.1 HEALTH AFFECTS OF LEAD EXPOSURE

Lead is a soft metal, naturally occurring in the earth's crust. It has been widely used in consumer products since 6500 B.C. It has been determined; however, that lead has no useful purpose in the human body and acts as a toxin. It takes the place of essential minerals such as calcium, potassium, and iron, which are all vital to the construction and repair of bones, organs and blood. Lead exposures have become a major health concern.

Children, due to their smaller body mass and higher metabolism, are affected by lead exposures much more severely than adults. They ingest lead through daily hand-to-mouth activities and may develop severe attention deficit disorders, irreversible brain injury and aggressive behaviors. The symptoms of lead poisoning often mimic other afflictions such as flu, colic or general malaise. It is important to have your young children's blood tested for lead burden.

2.2 SOURCES OF LEAD

Since lead is ingested by routine daily activities such as eating, playing, and working, it is important to understand the sources of lead exposures. The most common places to find lead in building settings are interior and exterior paint and contaminated soil or dust. Lead-based paint is most hazardous when it is chipping, peeling, cracking, chalking, applied to friction or impact surfaces of components such as doors, windows, and floors. The abrasive action of painted surfaces rubbing together causes lead-containing paints to be ground into a fine dust. Lead dust can also be created from decaying vinyl mini blinds. Lead dust then settles on furniture, play areas, and children's toys, where children are exposed during regular activities.

Several other sources of lead in a building include lead dust brought into the building from occupational exposures, water pipes, fixtures and joints, decorative china, leaded crystal, fishing lures and sinkers, firearms ammunition, wine bottles and cosmetics. Some hobbies may also contribute to lead contamination within the building. Exposure to all sources should be minimized or eliminated.

2.3 SIMPLE METHODS TO REDUCE LEAD HAZARDS

The simplest way to reduce lead hazards is through regular washing of hands, toys, and horizontal surfaces in the building with a liquid hand soap or dish soap and water. It is highly recommended that disposable cleaning materials be used to wash the surface, so as to not re-contaminate them with a used mop or cloth.

Other ways of reducing lead hazards within the building include taking shoes off before entering living areas, letting water run prior to drinking or cooking, covering exposed soil with plant materials, and vacuuming with a High Efficiency Particulate Air (HEPA) filtered vacuum.

3. SAMPLING PROCEDURES

3.1 LABORATORY

Samples for paint, dust, and soil, where applicable, were analyzed by Accurate Analytical Testing located at 12950 Haggerty Road in Belleville, Michigan 48111. The phone number is 734-699-LABS. The laboratory participates in the Environmental Lead Laboratory Accreditation Program (ELLAP) quality control rounds and are recognized and approved by the National Lead Laboratory Accreditation Program.

3.2 DIRECT-READING ANALYSIS

During this assessment, direct-reading analyses for lead content of painted surfaces were performed using a Niton X-ray fluorescence analyzer Serial Number 21503, by Matthew Rodgers (P-04247), a trained operator. The unit was calibrated according to the manufacturer's procedures on May 20th – May 22nd of 2013 and operated in accordance with the Performance Characteristic Sheet.

XRF technology utilizes low-level radiation to induce energy in lead atoms within a painted surface, which the XRF unit is able to analyze. The analyzer then displays the direct-reading results in milligrams of lead per square centimeter of surface area tested (mg/cm^2) and are able to determine if lead based paint is present. Lead-based paint (LBP) is defined by state and federal regulations as surface coatings which contain $1.0 \text{ mg}/\text{cm}^2$ of lead, or greater.

For risk assessments, all deteriorated painted surfaces are tested if the surface is determined to be in poor condition or poses a potential hazard and has a distinct painting

history [Michigan Rule No. 325.9916(4)] or is paint on an accessible, friction or impact surface [MCL 333.5458(3)].

3.3 SURFACE TESTING (PAINT CHIP SAMPLING)

Paint chip samples, when collected, are analyzed for lead content, as deemed appropriate by the investigator, usually where the XRF results are inconclusive. Paint chip samples where processed in the following manner:

- The surface coatings were scored with a clean sampling tool and a material sample collected, carefully removing all layers, excluding any substrate material.
- The coating materials were placed into a labeled airtight container, indicating site identification and sample location.
- The sample area and tools were cleaned with a damp cloth and the sample location repaired.
- Samples were submitted for analysis to an EPA approved laboratory. Results are reported in percent lead by weight (% by wt.).

3.4 SOIL SAMPLING

Soil samples, when collected, are from the building drip line, from bare soil areas and play areas within the boundaries of the property. Samples may be composited from several locations, from the upper ½ inches of soil and were analyzed by an EPA-approved laboratory. Results are reported in parts per million of sampled soil (ppm).

3.5 DUST WIPE SAMPLING

Dust wipe samples, when collected, were collected according to HUD Guidelines and Michigan Lead Hazard Remediation Program (LHRP) requirements in each area where a child, 6 or under, may come in contact with lead-contaminated dust currently or at any time in the future regardless of who presently resides there. Sample collection protocol is as follows:

- An area located on the surface to be sampled was measured (between 1.0 ft² and 2 ft²) and marked.
- A single approved sampling wipe (disposable towelette) was opened with a gloved hand and wiped across the sampling area in a series of S patterns. Composite dust wipe samples are prohibited in Michigan.
- The wipe was then placed into an airtight container labeled with the site location identification, sample location and size of area sampled.

- Samples were analyzed by an EPA- approved laboratory, and results were reported in micrograms per square foot ($\mu\text{g}/\text{ft}^2$).

4. RESULTS

4.1 VISUAL INSPECTION

The condition of the building on the date of the survey was good.

4.2 REGULATORY STANDARDS

EPA guidelines and HUD guidelines define lead-based paint and LBP hazard as:

Paint (XRF)	equal to or exceeding 1.0 milligrams of lead per square centimeter of sampled surface area (mg/cm^2)
Paint (chip sample)	equal to or exceeding 0.5% lead by dry weight or 5000 parts of lead per million parts of sampled material (ppm)
Hazardous lead-based paint	Lead-based paint that is deteriorated, or present in chewable, friction or impact surfaces
Bare soil (play areas)	equal to or exceeding 400 parts per million (ppm) lead
Bare soil (other)	equal to or exceeding 1200 ppm lead
Dust hazard (floors)	equal to or exceeding 40 micrograms per square foot of sampled surface area ($\mu\text{g}/\text{ft}^2$)
Dust hazard (window sill)	equal to or exceeding 250 $\mu\text{g}/\text{ft}^2$
Dust Hazard (window trough)	EPA: No level defined; Michigan LHRP: 400 $\mu\text{g}/\text{ft}^2$ lead

4.3 ANALYTICAL RESULTS

Detailed descriptions of all sample results, including laboratory results are located as follows:

- Appendix C for XRF analyses
- Appendix D for paint chips
- Appendix E for all other media sample results

4.4 LEAD-BASED PAINT

A lead-based paint inspection summary is located in Appendix C. The table describes the location, color and condition along with the content of lead and the substrate the paint is on. Paint that has a lead content of greater than 1.0 mg/cm^2 is highlighted and marked as

Positive in the results column. If the paint is less than 1.0 mg/cm² then the paint is considered to be not lead-based paint and is marked with a Negative in the results column.

No lead based paint identified.

4.5 PAINT CHIP RESULTS

Paint chip samples are taken usually of paint that cannot be directly read by the XRF method. Lead-based paint in paint chip analysis is analyzed by Flame Atomic Absorption (AA) Method AOAC 5.009(974.02). Regulations state that paint is lead-based if the paint has a quantity of lead greater than or equal to 0.5% dry weight.

No paint chip samples were taken at the time of the inspection.

4.6 SOIL SAMPLE RESULTS

The soil samples are composited from areas defined as play areas and non-play areas. Bare soil areas are noted in Appendix A. Soil samples are composited from various locations and taken to the lab for analysis by NIOSH Method 6010. Soils from play areas that have a lead concentration greater than or equal to 400 ppm and soils from non-play areas that have a lead concentration greater than or equal to 1200 ppm are deemed lead containing.

The soil samples collected at the Hikone were taken from the B-side of building E open soil, the open soil between building E and D, open soil on the D side of building E, open soil near basketball court, open soil in front of 2718, inside chicken wire garden and also the open soil between garden beds.

Sample Number	Sample Location	Side	Area/Type	Results
S-1	B-side of BLD-E open soil	B	Open	17.28 ppm
S-2	Open soil between BLD-E and D	N/A	Open	14.99 ppm
S-3	Open soil on D-side BLD-E	N/A	Open	19.00 ppm

S-4	Open soil near basketball court	N/A	Open	19.44 ppm
S-5	Open soil in front of 2718	N/A	Open	18.70 ppm
S-6	Inside chicken wire garden	N/A	Open	16.84 ppm
S-7	Open soil between wooden garden beds	N/A	Open	18.59 ppm

The soil samples collected at Hikone were taken from the B-side of building E open soil, the open soil between building E and D, open soil on the D side of building E, open soil near basketball court, open soil in front of 2718, inside chicken wire garden and also the open soil between garden beds had lead levels below the applicable EPA/HUD Standards.

4.7 WIPE SAMPLE RESULTS

Wipes taken during the inspection were taken to the laboratory to be analyzed by NIOSH 7105 Method which expresses lead concentrations in micrograms per square foot ($\mu\text{g}/\text{ft}^2$) of sampled area. The lead in dust on the floor that is equal to or exceeding $40 \mu\text{g}/\text{ft}^2$ is lead containing. Lead in dust on window sills that equal to or exceed $250 \mu\text{g}/\text{ft}^2$ is lead containing. Lead in dust in window troughs is lead containing if the lead concentration is $400 \mu\text{g}/\text{ft}^2$.

There was a minimum of 12 wipe samples taken in each of the 18 units tested and also in the community building at the Hikone property.

Unit	Sample Number	Sample Location	Wall	Component	Results
2706	W-1	Living room	N/A	Floor	$< 10 \mu\text{g}/\text{ft}^2$
2706	W-2	Living room	C	Window sill	$< 15.00 \mu\text{g}/\text{ft}^2$
2706	W-3	Kitchen	N/A	Floor	$< 10 \mu\text{g}/\text{ft}^2$
2706	W-4	Kitchen	A	Window trough	$< 15.00 \mu\text{g}/\text{ft}^2$

2706	W-5	B 1	N/A	Floor	< 10 µg/ft ²
2706	W-6	B 1	A	Window sill	< 15.00 µg/ft ²
2706	W-7	B 2	N/A	Floor	< 10 µg/ft ²
2706	W-8	B 2	B	Window trough	< 15.00 µg/ft ²
2706	W-9	B 3	N/A	Floor	< 10 µg/ft ²
2706	W-10	B 3	C	Window sill	< 15.00 µg/ft ²
2706	W-11	Bath	N/A	Floor	< 10 µg/ft ²
2706	W-12	Base	N/A	Floor	< 10 µg/ft ²
2706	FB	Field Blank	N/A	N/A	N/D
2708	W-1	Living room	N/A	Floor	< 10 µg/ft ²
2708	W-2	Living room	C	Window sill	< 15.00 µg/ft ²
2708	W-3	Kitchen	N/A	Floor	< 10 µg/ft ²
2708	W-4	Kitchen	A	Window trough	< 15.00 µg/ft ²
2708	W-5	B 1	N/A	Floor	< 10 µg/ft ²
2708	W-6	B 1	A	Window sill	< 15.00 µg/ft ²
2708	W-7	B 2	N/A	Floor	< 10 µg/ft ²
2708	W-8	B 2	B	Window trough	< 15.00 µg/ft ²
2708	W-9	B 3	N/A	Floor	< 10 µg/ft ²
2708	W-10	B 3	C	Window sill	< 15.00 µg/ft ²
2708	W-11	B 4	N/A	Floor	< 10 µg/ft ²
2708	W-12	B 4	D	Window sill	< 15.00 µg/ft ²

2708	FB	Field Blank	N/A	N/A	N/D
2710	W-1	Living room	N/A	Floor	< 10 µg/ft ²
2710	W-2	Living room	C	Window sill	< 15.00 µg/ft ²
2710	W-3	Kitchen	N/A	Floor	< 10 µg/ft ²
2710	W-4	Kitchen	A	Window trough	< 15.00 µg/ft ²
2710	W-5	B 1	N/A	Floor	< 10 µg/ft ²
2710	W-6	B 1	A	Window sill	< 15.00 µg/ft ²
2710	W-7	B 2	N/A	Floor	< 10 µg/ft ²
2710	W-8	B 2	B	Window trough	< 15.00 µg/ft ²
2710	W-9	2 nd floor hallway	N/A	Floor	< 10 µg/ft ²
2710	W-10	2 nd floor stairs	N/A	Floor	< 10 µg/ft ²
2710	W-11	Base	N/A	Floor	< 10 µg/ft ²
2710	W-12	Bath	N/A	Floor	< 10 µg/ft ²
2710	FB	Field Blank	N/A	N/A	N/D
2718	W-1	Living room	N/A	Floor	< 10 µg/ft ²
2718	W-2	Living room	C	Window sill	< 15.00 µg/ft ²
2718	W-3	Kitchen	N/A	Floor	< 10 µg/ft ²
2718	W-4	Kitchen	A	Window trough	< 15.00 µg/ft ²
2718	W-5	B 1	N/A	Floor	< 10 µg/ft ²
2718	W-6	B 1	A	Window sill	< 15.00 µg/ft ²
2718	W-7	B 2	N/A	Floor	< 10 µg/ft ²

2718	W-8	B 2	B	Window trough	< 15.00 µg/ft ²
2718	W-9	B 3	N/A	Floor	< 10 µg/ft ²
2718	W-10	B 3	C	Window sill	< 15.00 µg/ft ²
2718	W-11	B 4	N/A	Floor	< 10 µg/ft ²
2718	W-12	B 4	D	Window sill	< 15.00 µg/ft ²
2718	FB	Field Blank	N/A	N/A	N/D
2720	W-1	Living room	N/A	Floor	< 10 µg/ft ²
2720	W-2	Living room	C	Window sill	< 15.00 µg/ft ²
2720	W-3	Kitchen	N/A	Floor	< 10 µg/ft ²
2720	W-4	Kitchen	A	Window trough	< 15.00 µg/ft ²
2720	W-5	B 1	N/A	Floor	< 10 µg/ft ²
2720	W-6	B 1	A	Window sill	< 15.00 µg/ft ²
2720	W-7	B 2	N/A	Floor	< 10 µg/ft ²
2720	W-8	B 2	B	Window trough	< 15.00 µg/ft ²
2720	W-9	B 3	N/A	Floor	< 10 µg/ft ²
2720	W-10	B 3	C	Window sill	< 15.00 µg/ft ²
2720	W-11	Bath	N/A	Floor	< 10 µg/ft ²
2720	W-12	Base	N/A	Floor	< 10 µg/ft ²
2720	FB	Field Blank	N/A	N/A	N/D
2726	W-1	Living room	N/A	Floor	< 10 µg/ft ²
2726	W-2	Living room	C	Window sill	< 15.00 µg/ft ²

2726	W-3	Kitchen	N/A	Floor	< 10 µg/ft ²
2726	W-4	Kitchen	A	Window trough	< 15.00 µg/ft ²
2726	W-5	B 1	N/A	Floor	< 10 µg/ft ²
2726	W-6	B 1	A	Window sill	< 15.00 µg/ft ²
2726	W-7	B 2	N/A	Floor	< 10 µg/ft ²
2726	W-8	B 2	B	Window trough	< 15.00 µg/ft ²
2726	W-9	B 3	N/A	Floor	< 10 µg/ft ²
2726	W-10	B 3	C	Window sill	< 15.00 µg/ft ²
2726	W-11	Bath	N/A	Floor	< 10 µg/ft ²
2726	W-12	Base	N/A	Floor	< 10 µg/ft ²
2726	FB	Field Blank	N/A	N/A	N/D
2728	W-1	Living room	N/A	Floor	< 10 µg/ft ²
2728	W-2	Living room	C	Window sill	< 15.00 µg/ft ²
2728	W-3	Kitchen	N/A	Floor	< 10 µg/ft ²
2728	W-4	Kitchen	A	Window trough	< 15.00 µg/ft ²
2728	W-5	B 1	N/A	Floor	< 10 µg/ft ²
2728	W-6	B 1	A	Window sill	< 15.00 µg/ft ²
2728	W-7	B 2	N/A	Floor	< 10 µg/ft ²
2728	W-8	B 2	B	Window trough	< 15.00 µg/ft ²
2728	W-9	2 nd floor hallway	N/A	Floor	< 10 µg/ft ²
2728	W-10	2 nd floor stairs	N/A	Floor	< 10 µg/ft ²

2728	W-11	Base	N/A	Floor	< 10 µg/ft ²
2728	W-12	Bath	N/A	Floor	< 10 µg/ft ²
2728	FB	Field Blank	N/A	N/A	N/D
2730	W-1	Living room	N/A	Floor	< 10 µg/ft ²
2730	W-2	Living room	C	Window sill	< 15.00 µg/ft ²
2730	W-3	Kitchen	N/A	Floor	< 10 µg/ft ²
2730	W-4	Kitchen	A	Window trough	< 15.00 µg/ft ²
2730	W-5	B 1	N/A	Floor	< 10 µg/ft ²
2730	W-6	B 1	A	Window sill	< 15.00 µg/ft ²
2730	W-7	B 2	N/A	Floor	< 10 µg/ft ²
2730	W-8	B 2	B	Window trough	< 15.00 µg/ft ²
2730	W-9	B 3	N/A	Floor	< 10 µg/ft ²
2730	W-10	B 3	C	Window sill	< 15.00 µg/ft ²
2730	W-11	B 4	N/A	Floor	< 10 µg/ft ²
2730	W-12	B 4	D	Window sill	< 15.00 µg/ft ²
2730	FB	Field Blank	N/A	N/A	N/D
2732	W-1	Living room	N/A	Floor	< 10 µg/ft ²
2732	W-2	Living room	C	Window sill	< 15.00 µg/ft ²
2732	W-3	Kitchen	N/A	Floor	< 10 µg/ft ²
2732	W-4	Kitchen	A	Window trough	< 15.00 µg/ft ²
2732	W-5	B 1	N/A	Floor	< 10 µg/ft ²

2732	W-6	B 1	A	Window sill	< 15.00 µg/ft ²
2732	W-7	B 2	N/A	Floor	< 10 µg/ft ²
2732	W-8	B 2	B	Window trough	< 15.00 µg/ft ²
2732	W-9	B 3	N/A	Floor	< 10 µg/ft ²
2732	W-10	B 3	C	Window sill	< 15.00 µg/ft ²
2732	W-11	Bath	N/A	Floor	< 10 µg/ft ²
2732	W-12	Base	N/A	Floor	< 10 µg/ft ²
2742	W-1	Living room	N/A	Floor	< 10 µg/ft ²
2742	W-2	Living room	C	Window sill	< 15.00 µg/ft ²
2742	W-3	Kitchen	N/A	Floor	< 10 µg/ft ²
2742	W-4	Kitchen	A	Window trough	< 15.00 µg/ft ²
2742	W-5	B 1	N/A	Floor	< 10 µg/ft ²
2742	W-6	B 1	A	Window sill	< 15.00 µg/ft ²
2742	W-7	B 2	N/A	Floor	< 10 µg/ft ²
2742	W-8	B 2	B	Window trough	< 15.00 µg/ft ²
2742	W-9	B 3	N/A	Floor	< 10 µg/ft ²
2742	W-10	B 3	C	Window sill	< 15.00 µg/ft ²
2742	W-11	Bath	N/A	Floor	< 10 µg/ft ²
2742	W-12	Base	N/A	Floor	< 10 µg/ft ²
2742	FB	Field Blank	N/A	N/A	N/D
2748	W-1	Living room	N/A	Floor	< 10 µg/ft ²

2748	W-2	Living room	C	Window sill	< 15.00 µg/ft ²
2748	W-3	Kitchen	N/A	Floor	< 10 µg/ft ²
2748	W-4	Kitchen	A	Window trough	< 15.00 µg/ft ²
2748	W-5	B 1	N/A	Floor	< 10 µg/ft ²
2748	W-6	B 1	A	Window sill	< 15.00 µg/ft ²
2748	W-7	B 2	N/A	Floor	< 10 µg/ft ²
2748	W-8	B 2	B	Window trough	< 15.00 µg/ft ²
2748	W-9	B 3	N/A	Floor	< 10 µg/ft ²
2748	W-10	B 3	C	Window sill	< 15.00 µg/ft ²
2748	W-11	Bath	N/A	Floor	< 10 µg/ft ²
2748	W-12	Base	N/A	Floor	< 10 µg/ft ²
2748	FB	Field Blank	N/A	N/A	N/D
2750	W-1	Living room	N/A	Floor	< 10 µg/ft ²
2750	W-2	Living room	C	Window sill	< 15.00 µg/ft ²
2750	W-3	Kitchen	N/A	Floor	< 10 µg/ft ²
2750	W-4	Kitchen	A	Window trough	< 15.00 µg/ft ²
2750	W-5	B 1	N/A	Floor	< 10 µg/ft ²
2750	W-6	B 1	A	Window sill	< 15.00 µg/ft ²
2750	W-7	B 2	N/A	Floor	< 10 µg/ft ²
2750	W-8	B 2	B	Window trough	< 15.00 µg/ft ²
2750	W-9	B 3	N/A	Floor	< 10 µg/ft ²

2750	W-10	B 3	C	Window sill	< 15.00 µg/ft ²
2750	W-11	Bath	N/A	Floor	< 10 µg/ft ²
2750	W-12	Base	N/A	Floor	< 10 µg/ft ²
2750	FB	Field Blank	N/A	N/A	N/D
2752	W-1	Living room	N/A	Floor	< 10 µg/ft ²
2752	W-2	Living room	C	Window sill	< 15.00 µg/ft ²
2752	W-3	Kitchen	N/A	Floor	< 10 µg/ft ²
2752	W-4	Kitchen	A	Window trough	< 15.00 µg/ft ²
2752	W-5	B 1	N/A	Floor	< 10 µg/ft ²
2752	W-6	B 1	A	Window sill	< 15.00 µg/ft ²
2752	W-7	B 2	N/A	Floor	< 10 µg/ft ²
2752	W-8	B 2	B	Window trough	< 15.00 µg/ft ²
2752	W-9	2 nd floor hallway	N/A	Floor	< 10 µg/ft ²
2752	W-10	2 nd floor stairs	N/A	Floor	< 10 µg/ft ²
2752	W-11	Base	N/A	Floor	< 10 µg/ft ²
2752	W-12	Bath	N/A	Floor	< 10 µg/ft ²
2752	FB	Field Blank	N/A	N/A	N/D
2754	W-1	Living room	N/A	Floor	< 10 µg/ft ²
2754	W-2	Living room	C	Window sill	< 15.00 µg/ft ²
2754	W-3	Kitchen	N/A	Floor	< 10 µg/ft ²
2754	W-4	Kitchen	A	Window trough	< 15.00 µg/ft ²

2754	W-5	B 1	N/A	Floor	< 10 µg/ft ²
2754	W-6	B 1	A	Window sill	< 15.00 µg/ft ²
2754	W-7	B 2	N/A	Floor	< 10 µg/ft ²
2754	W-8	B 2	B	Window trough	< 15.00 µg/ft ²
2754	W-9	B 3	N/A	Floor	< 10 µg/ft ²
2754	W-10	B 3	C	Window sill	< 15.00 µg/ft ²
2754	W-11	B 4	N/A	Floor	< 10 µg/ft ²
2754	W-12	B 4	D	Window sill	< 15.00 µg/ft ²
2754	FB	Field Blank	N/A	N/A	N/D
2756	W-1	Living room	N/A	Floor	< 10 µg/ft ²
2756	W-2	Living room	C	Window sill	< 15.00 µg/ft ²
2756	W-3	Kitchen	N/A	Floor	< 10 µg/ft ²
2756	W-4	Kitchen	A	Window trough	< 15.00 µg/ft ²
2756	W-5	B 1	N/A	Floor	< 10 µg/ft ²
2756	W-6	B 1	A	Window sill	< 15.00 µg/ft ²
2756	W-7	B 2	N/A	Floor	< 10 µg/ft ²
2756	W-8	B 2	B	Window trough	< 15.00 µg/ft ²
2756	W-9	B 3	N/A	Floor	< 10 µg/ft ²
2756	W-10	B 3	C	Window sill	< 15.00 µg/ft ²
2756	W-11	Bath	N/A	Floor	< 10 µg/ft ²
2756	W-12	Base	N/A	Floor	< 10 µg/ft ²

2756	FB	Field Blank	N/A	N/A	N/D
2760	W-1	Living room	N/A	Floor	< 10 µg/ft ²
2760	W-2	Living room	C	Window sill	< 15.00 µg/ft ²
2760	W-3	Kitchen	N/A	Floor	< 10 µg/ft ²
2760	W-4	Kitchen	A	Window trough	< 15.00 µg/ft ²
2760	W-5	B 1	N/A	Floor	< 10 µg/ft ²
2760	W-6	B 1	A	Window sill	< 15.00 µg/ft ²
2760	W-7	B 2	N/A	Floor	< 10 µg/ft ²
2760	W-8	B 2	B	Window trough	< 15.00 µg/ft ²
2760	W-9	B 3	N/A	Floor	< 10 µg/ft ²
2760	W-10	B 3	C	Window sill	< 15.00 µg/ft ²
2760	W-11	Bath	N/A	Floor	< 10 µg/ft ²
2760	W-12	Base	N/A	Floor	< 10 µg/ft ²
2760	FB	Field Blank	N/A	N/A	N/D
Community	W-1	Kitchen	N/A	Floor	< 10 µg/ft ²
Community	W-2	Kitchen	A	Window sill	< 15.00 µg/ft ²
Community	W-3	Computer	N/A	Floor	< 10 µg/ft ²
Community	W-4	Computer	C	Window trough	< 15.00 µg/ft ²
Community	W-5	Class	N/A	Floor	< 10 µg/ft ²
Community	W-6	Class	C	Window sill	< 15.00 µg/ft ²
Community	W-7	Office	N/A	Floor	< 10 µg/ft ²

Community	W-8	Office	C	Window trough	< 15.00 $\mu\text{g}/\text{ft}^2$
Community	W-9	Pantry	N/A	Floor	< 10 $\mu\text{g}/\text{ft}^2$
Community	W-10	2 nd floor hall	N/A	Floor	< 10 $\mu\text{g}/\text{ft}^2$
Community	W-11	2 nd floor room	N/A	Floor	< 10 $\mu\text{g}/\text{ft}^2$
Community	W-12	Rest room	N/A	Floor	< 10 $\mu\text{g}/\text{ft}^2$
Community	FB	Field Blank	N/A	Floor	N/D

No lead in dust hazards were identified.

5. CONCLUSIONS AND RECOMMENDATIONS

5.1 EXISTING LEAD-BASED PAINT HAZARDS

A lead-based paint hazard is defined by the EPA as: any condition that causes exposure to lead from dust, soil or lead based paint that is on chewable, friction or impacted surfaces. The following lead-based paint hazards have been identified as a result of this assessment:

No existing lead-based paint hazards were identified.

5.2 POTENTIAL LEAD BASED PAINT HAZARDS

A lead-based paint hazard is defined by the EPA as: any condition that causes exposure to lead from dust, soil or lead based paint that is on chewable, friction or impacted surfaces. The following lead-based paint potential hazards have been identified as a result of this assessment:

No potential lead-based paint hazards were identified.

5.3 LEAD SOIL HAZARDS

No lead in soil hazards were identified.

5.4 LEAD DUST HAZARD

A lead dust hazard is any lead dust in an occupied space with elevated levels of 40 $\mu\text{g}/\text{ft}^2$ on floors, 250 $\mu\text{g}/\text{ft}^2$ on window sills, and 400 $\mu\text{g}/\text{ft}^2$ on window trough.

No lead in dust hazards were identified.

5.4 LEAD HAZARD CONTROL OPTIONS

No hazard control options needed at this time due to no lead based paint or lead hazards being identified.

Lead hazard control may consist of either or a combination of abatement and interim controls. Abatement options are designed to permanently eliminate a lead-based paint hazard. Examples include removal of paint, dust, soil or painted components and permanent enclosure or encapsulation of painted surfaces. Interim controls are designed to temporarily reduce human exposure to hazards. Examples include specialized cleaning, maintenance, repairs, painting, temporary containment, and ongoing monitoring of hazards and potential hazards.

The lead-based paint hazards and lead hazard control options recommendations are consolidated in Appendix F. Also an excerpt from the *Lead in Your Home: A Parents Reference Guide*, about interim controls that residents can take immediately to reduce lead hazards is located in Appendix G.

5.5 ON-GOING MONITORING SCHEDULE (REEVALUATION AND OWNER VISUAL SURVEY)

A Reevaluation is a follow-up limited risk assessment to determine the effectiveness of implemented hazard controls, and whether new hazards have developed. The reevaluation must be performed by a licensed risk assessor and will be implemented in order to discover:

- The presence of leaded dust above applicable standards
- Newly deteriorated known or suspected lead-based paint
- Deteriorated or failed interim controls, encapsulants or enclosure treatments
- New bare soil with lead levels above applicable standards

An Owner Visual Survey is an annual task performed by an owner or owner's representative which will be implemented in order to discover:

- New deterioration on known lead-based paint surfaces
- Deterioration or failed interim controls, encapsulants or enclosure treatments

- Structural problems which may compromise the integrity of any known or suspected lead-based paint

The Reevaluation and Owner Visual Survey schedules are determined by taking into consideration the risk assessment evaluation results (leaded dust, soil and paint findings) and the actions taken (abatement and interim controls). This information is then used with guidance found in the Standard Reevaluation Schedule (HUD Table 6.1) to determine when these activities should take place.

5.5 COST ESTIMATE

HUD and EPA regulations require the risk assessor to provide cost estimates for possible work to be completed. Below find a rough estimate of cost associated with lead control/abatement activities.

• Encapsulation	\$ 3.50 sq. ft
• Wet Plane Friction Surface	\$ 2.75 sq. ft
• Wet Plane Impact Points	\$ 2.50 sq. ft
• Wet Scrape and Repaint	\$ 2.00 sq. ft
• Window Replacement	\$ 500 each
• Dust Removal-Clean Up	\$ 3.50 sq. ft
• Enclosure Wood	\$ 4.00 sq. ft
• Enclosure Metal	\$ 5.00 sq. ft
• Enclosure Drywall	\$ 2.50 sq. ft
• Floor Replacement	\$ 750.00 each
• Soil Abatement	\$ 10.00 sq. ft
• Component Replacement	5 times material cost

5.7 RECOMMENDATIONS FOR FUTURE OPERATIONS AND MAINTENANCE

The future disturbance of lead painted surfaces may cause new additional lead hazards. Homeowners, Building managers and landlords are expected to follow “lead safe work practices” anytime that a lead painted surface is disturbed. This meaning very little dust is generated, not burning lead painted items, cleaning up thoroughly after work, etc.

In order to provide guidance for the owners, managers and landlords when conducting renovation, maintenance or potential future disturbance of painted surfaces, they should refer to an excellent manual developed by HUD titled “Lead Paint Safety: A Field Guide for Painting, Home Maintenance, and Renovation Work” This manual can be found for

free on the internet at <http://www.hud.gov/offices/lead/training/LBPguide.pdf>. Please download a copy of this manual before disturbing any painted surfaces within the residence. If access to the internet is not available, you may order a copy at 1800-424-5323.

If you have any questions not answered by this manual, please contact our office at (313) 491-2600.

6. ADDITIONAL RESOURCES

For further information regarding lead-based paint hazards and poisoning prevention, consult the following resources:

6.1 CONTACTS

National Lead Information Center	800-424-LEAD (5323)
U.S. Department of Housing and Urban Development	888-532-3547 (LEADLIST)
Michigan Lead Hazard Remediation Program	866-691-LEAD (5323)

6.2 PUBLICATIONS


Lead in Your Home: A Parent's Reference Guide
U.S. Environmental Protection Agency

Protect Your Family From Lead in Your Home
U.S. Environmental Protection Agency

Lead Paint Safety: A Field Guide for Painting, Home Maintenance, and Renovation Work

U.S. Department of Housing and Urban Development.

The information contained in this report is a true and accurate representation of the lead-based paint conditions at the subject property at the time of assessment, based on the professional judgment of:




Matthew Rodgers
MI Certified Lead Inspector/Risk Assessor
Number: P-04247

7/23/13.
Date


Appendix A

FLOOR PLAN AND SITE LOCATION MAP


Typical 2 bedroom unit




Typical 3 bedroom unit



Typical 4 bedroom unit




Typical Building layout



Property Map

C

Hikone



Soil Samples- S

APPENDIX B

HUD FORMS 5.0 & 5.1

**RESIDENT QUESTIONNAIRE
BUILDING CONDITION CHECKLIST**

PROPERTY:	Hikone
UNIT NO.:	Community - BID
OWNER:	Ann Arbor Housing Commission
DATE:	5/22/13

HUD FORM 5.1

BUILDING CONDITION CHECKLIST

LHRP Rule No. 325.8916 (2)

Risk Assessor: Matthew K Rodgers
P-04247

CONDITION KEY	YES	NO
Roof missing parts of surfaces: tiles, boards, etc. COMMENTS:		X
Roof has holes or large cracks COMMENTS:		X
Gutters/downspouts broken COMMENTS:		X
Chimney masonry cracked, bricks loose or missing, obviously out of plumb COMMENTS:		X
Exter/inter walls have obvious large cracks/ holes requiring more than routine painting COMMENTS:		X
Exterior siding missing boards or shingles COMMENTS:		X
Water stains on interior walls or ceilings COMMENTS:		X
Plaster walls deteriorated COMMENTS:		X
Two or more windows or doors broken, missing or boarded up COMMENTS:		X
Porch or steps have major elements broken, missing, or boarded up COMMENTS:		X
Foundation has major cracks, missing material, structural leans or visibly unsound COMMENTS:		X
TOTAL		11

TOTAL: IF THERE ARE TWO OR MORE CHECKS IN THE YES COLUMN, THE DWELLING IS CONSIDERED TO BE IN POOR CONDITION FOR THE PURPOSES OF A RISK ASSESSMENT. HOWEVER, CONSIDER ALL SPECIFIC CONDITIONS AND EXTENUATING CIRCUMSTANCES BEFORE DETERMINING FINAL CONDITION OR APPROPRIATENESS OF A LEAD HAZARD SCREEN.

PROPERTY:	Hikone
UNIT NO.:	2760
OWNER:	Ann Arbor Housing Commission
DATE:	5/22/13

HUD FORM 5.1

BUILDING CONDITION CHECKLIST

LHRP Rule No. 325.8916 (2)

Risk Assessor: Matthew K. Rodgers
P-04247

CONDITION KEY	YES	NO
Roof missing parts of surfaces: tiles, boards, etc. COMMENTS:		X
Roof has holes or large cracks COMMENTS:		X
Gutters/downspouts broken COMMENTS:		X
Chimney masonry cracked, bricks loose or missing, obviously out of plumb COMMENTS:		X
Exterior walls have obvious large cracks/holes requiring more than routine painting COMMENTS:		X
Exterior siding missing boards or shingles COMMENTS:		X
Water stains on interior walls or ceilings COMMENTS:		X
Plaster walls deteriorated COMMENTS:		X
Two or more windows or doors broken, missing or boarded up COMMENTS:		X
Porch or steps have major elements broken, missing, or boarded up COMMENTS:		X
Foundation has major cracks, missing material, structural beams or visibly unsound COMMENTS:		X
TOTAL		11

TOTAL: IF THERE ARE TWO OR MORE CHECKS IN THE YES COLUMN, THE DWELLING IS CONSIDERED TO BE IN POOR CONDITION FOR THE PURPOSES OF A RISK ASSESSMENT. HOWEVER, CONSIDER ALL SPECIFIC CONDITIONS AND EXTENUATING CIRCUMSTANCES BEFORE DETERMINING FINAL CONDITION OR APPROPRIATENESS OF A LEAD HAZARD SCREEN.

PROPERTY:	Hikone
UNIT NO.:	2756
OWNER:	Ann Arbor Housing Commission
DATE:	5/22/13

HUD FORM 5.1
BUILDING CONDITION CHECKLIST
LHRP Rule No. 325.0916 (2)
Risk Assessor: Matthew K Rodgers
P-04247

CONDITION KEY	YES	NO
Roof missing parts of surfaces: tiles, boards, etc. COMMENTS:		X
Roof has holes or large cracks COMMENTS:		X
Gutters/downspouts broken COMMENTS:		X
Chimney masonry cracked, bricks loose or missing, obviously out of plumb COMMENTS:		X
Exterior walls have obvious large cracks/ holes requiring more than routine painting COMMENTS:		X
Exterior siding missing boards or shingles COMMENTS:		X
Water stains on interior walls or ceilings COMMENTS:		X
Plaster walls deteriorated COMMENTS:		X
Two or more windows or doors broken, missing or boarded up COMMENTS:		X
Porch or steps have major elements broken, missing, or boarded up COMMENTS:		X
Foundation has major cracks, missing material, structural beams or visibly unsound COMMENTS:		X
TOTAL		11

TOTAL: IF THERE ARE TWO OR MORE CHECKS IN THE YES COLUMN, THE DWELLING IS CONSIDERED TO BE IN POOR CONDITION FOR THE PURPOSES OF A RISK ASSESSMENT. HOWEVER, CONSIDER ALL SPECIFIC CONDITIONS AND EXTENUATING CIRCUMSTANCES BEFORE DETERMINING FINAL CONDITION OR APPROPRIATENESS OF A LEAD HAZARD SCREEN.

PROPERTY:	Hikone
UNIT NO.:	2750
OWNER:	Ann Arbor Housing Commission
DATE:	5/22/13

HUD FORM 5.1

BUILDING CONDITION CHECKLIST

LHRP Rule No. 325.8916 (2)

Risk Assessor: Matthew K. Rodgers
P-04247

CONDITION KEY	YES	NO
Roof missing parts of surfaces: tiles, boards, etc. COMMENTS:		X
Roof has holes or large cracks COMMENTS:		X
Gutters/downspouts broken COMMENTS:		X
Chimney masonry cracked, bricks loose or missing, obviously out of plumb COMMENTS:		X
Exterior walls have obvious large cracks/holes requiring more than routine painting COMMENTS:		X
Exterior siding missing boards or shingles COMMENTS:		X
Water stains on interior walls or ceilings COMMENTS:		X
Plaster walls deteriorated COMMENTS:		X
Two or more windows or doors broken, missing or boarded up COMMENTS:		X
Porch or steps have major elements broken, missing, or boarded up COMMENTS:		X
Foundation has major cracks, missing material, structural leans or visibly unsound COMMENTS:		X
TOTAL		11

TOTAL: IF THERE ARE TWO OR MORE CHECKS IN THE YES COLUMN, THE DWELLING IS CONSIDERED TO BE IN POOR CONDITION FOR THE PURPOSES OF A RISK ASSESSMENT. HOWEVER, CONSIDER ALL SPECIFIC CONDITIONS AND EXTENUATING CIRCUMSTANCES BEFORE DETERMINING FINAL CONDITION OR APPROPRIATENESS OF A LEAD HAZARD SCREEN.

PROPERTY:	Hikone
UNIT NO.:	2752
OWNER:	Ann Arbor Housing Commission
DATE:	5/22/13

HUD FORM 5.1

BUILDING CONDITION CHECKLIST

LHRP Rule No. 325.9916 (2)

Risk Assessor: Matthew K Rodgers

P-04247

CONDITION KEY	YES	NO
Roof missing parts of surfaces: tiles, boards, etc. COMMENTS:		X
Roof has holes or large cracks COMMENTS:		X
Gutters/downspouts broken COMMENTS:		X
Chimney masonry cracked, bricks loose or missing, obviously out of plumb COMMENTS:		X
Exterior walls have obvious large cracks/ holes requiring more than routine painting COMMENTS:		X
Exterior siding missing boards or shingles COMMENTS:		X
Water stains on interior walls or ceilings COMMENTS:		X
Plaster walls deteriorated COMMENTS:		X
Two or more windows or doors broken, missing or boarded up COMMENTS:		X
Porch or steps have major elements broken, missing, or boarded up COMMENTS:		X
Foundation has major cracks, missing material, structural leans or visibly unsound COMMENTS:		X
TOTAL		11

TOTAL: IF THERE ARE TWO OR MORE CHECKS IN THE YES COLUMN, THE DWELLING IS CONSIDERED TO BE IN POOR CONDITION FOR THE PURPOSES OF A RISK ASSESSMENT. HOWEVER, CONSIDER ALL SPECIFIC CONDITIONS AND EXTENUATING CIRCUMSTANCES BEFORE DETERMINING FINAL CONDITION OR APPROPRIATENESS OF A LEAD HAZARD SCREEN.

PROPERTY:	Hikone
UNIT NO.:	2754
OWNER:	Ann Arbor Housing Commission
DATE:	5/22/13

HUD FORM 5.1

BUILDING CONDITION CHECKLIST

LHRP Rule No. 325.8916 (2)

Risk Assessor: Matthew K Rodgers
P-04247

CONDITION KEY	YES	NO
Roof missing parts of surfaces: tiles, boards, etc. COMMENTS:		X
Roof has holes or large cracks COMMENTS:		X
Gutters/downspouts broken COMMENTS:		X
Chimney masonry cracked, bricks loose or missing, obviously out of plumb COMMENTS:		X
Exterior walls have obvious large cracks/ holes requiring more than routine painting COMMENTS:		X
Exterior siding missing boards or shingles COMMENTS:		X
Water stains on interior walls or ceilings COMMENTS:		X
Plaster walls deteriorated COMMENTS:		X
Two or more windows or doors broken, missing or boarded up COMMENTS:		X
Porch or steps have major elements broken, missing, or boarded up COMMENTS:		X
Foundation has major cracks, missing material, structural beams or visibly unsound COMMENTS:		X
TOTAL		11

TOTAL: IF THERE ARE TWO OR MORE CHECKS IN THE YES COLUMN, THE DWELLING IS CONSIDERED TO BE IN POOR CONDITION FOR THE PURPOSES OF A RISK ASSESSMENT. HOWEVER, CONSIDER ALL SPECIFIC CONDITIONS AND EXTENUATING CIRCUMSTANCES BEFORE DETERMINING FINAL CONDITION OR APPROPRIATENESS OF A LEAD HAZARD SCREEN.

PROPERTY:	Hikone
UNIT NO.:	2710
OWNER:	Ann Arbor Housing Commission
DATE:	5/20/13

HUD FORM 5.1
BUILDING CONDITION CHECKLIST
LHRP Rule No. 325.8916 (2)
Risk Assessor: Matthew K Rodgers
P-04247

CONDITION KEY	YES	NO
Roof missing parts of surfaces: tiles, boards, etc. COMMENTS:		X
Roof has holes or large cracks COMMENTS:		X
Gutters/downspouts broken COMMENTS:		X
Chimney masonry cracked, bricks loose or missing, obviously out of plumb COMMENTS:		X
Exterior walls have obvious large cracks/ holes requiring more than routine painting COMMENTS:		X
Exterior siding missing boards or shingles COMMENTS:		X
Water stains on interior walls or ceilings COMMENTS:		X
Plaster walls deteriorated COMMENTS:		X
Two or more windows or doors broken, missing or boarded up COMMENTS:		X
Porch or steps have major elements broken, missing, or boarded up COMMENTS:		X
Foundation has major cracks, missing material, structural beams or visibly unsound COMMENTS:		X
TOTAL		11

TOTAL: IF THERE ARE TWO OR MORE CHECKS IN THE YES COLUMN, THE DWELLING IS CONSIDERED TO BE IN POOR CONDITION FOR THE PURPOSES OF A RISK ASSESSMENT. HOWEVER, CONSIDER ALL SPECIFIC CONDITIONS AND EXTENUATING CIRCUMSTANCES BEFORE DETERMINING FINAL CONDITION OR APPROPRIATENESS OF A LEAD HAZARD SCREEN.

PROPERTY:	Hikone
UNIT NO.:	2708
OWNER:	Ann Arbor Housing Commission
DATE:	5/20/13

HUD FORM 5.1

BUILDING CONDITION CHECKLIST

LHRP Rule No. 325.8916 (2)

Risk Assessor: Matthew K Rodgers
P-04247

CONDITION KEY	YES	NO
Roof missing parts of surfaces: tiles, boards, etc. COMMENTS:		X
Roof has holes or large cracks COMMENTS:		X
Gutters/downspouts broken COMMENTS:		X
Chimney masonry cracked, bricks loose or missing, obviously out of plumb COMMENTS:		X
Exterior walls have obvious large cracks/ holes requiring more than routine painting COMMENTS:		X
Exterior siding missing boards or shingles COMMENTS:		X
Water stains on interior walls or ceilings COMMENTS:		X
Plaster walls deteriorated COMMENTS:		X
Two or more windows or doors broken, missing or boarded up COMMENTS:		X
Porch or steps have major elements broken, missing, or boarded up COMMENTS:		X
Foundation has major cracks, missing material, structural beams or visibly unsound COMMENTS:		X
TOTAL		11

TOTAL: IF THERE ARE TWO OR MORE CHECKS IN THE YES COLUMN, THE DWELLING IS CONSIDERED TO BE IN POOR CONDITION FOR THE PURPOSES OF A RISK ASSESSMENT. HOWEVER, CONSIDER ALL SPECIFIC CONDITIONS AND EXTENUATING CIRCUMSTANCES BEFORE DETERMINING FINAL CONDITION OR APPROPRIATENESS OF A LEAD HAZARD SCREEN.

PROPERTY:	Hikone
UNIT NO.:	2706
OWNER:	Ann Arbor Housing Commission
DATE:	5/20/13

HUD FORM 5.1
BUILDING CONDITION CHECKLIST
LHRP Rule No. 325.8916 (2)
Risk Assessor: Matthew K Rodgers
P-04247

CONDITION KEY	YES	NO
Roof missing parts of surfaces: tiles, boards, etc. COMMENTS:		X
Roof has holes or large cracks COMMENTS:		X
Gutters/downspouts broken COMMENTS:		X
Chimney masonry cracked, bricks loose or missing, obviously out of plumb COMMENTS:		X
Exterior walls have obvious large cracks/ holes requiring more than routine painting COMMENTS:		X
Exterior siding missing boards or shingles COMMENTS:		X
Water stains on interior walls or ceilings COMMENTS:		X
Plaster walls deteriorated COMMENTS:		X
Two or more windows or doors broken, missing or boarded up COMMENTS:		X
Porch or steps have major elements broken, missing, or boarded up COMMENTS:		X
Foundation has major cracks, missing material, structural beams or visibly unsound COMMENTS:		X
TOTAL		11

TOTAL: IF THERE ARE TWO OR MORE CHECKS IN THE YES COLUMN, THE DWELLING IS CONSIDERED TO BE IN POOR CONDITION FOR THE PURPOSES OF A RISK ASSESSMENT. HOWEVER, CONSIDER ALL SPECIFIC CONDITIONS AND EXTENUATING CIRCUMSTANCES BEFORE DETERMINING FINAL CONDITION OR APPROPRIATENESS OF A LEAD HAZARD SCREEN.

PROPERTY:	Hikone
UNIT NO.:	2720
OWNER:	Ann Arbor Housing Commission
DATE:	5/20/13

HUD FORM 5.1
 BUILDING CONDITION CHECKLIST
 LHRP Rule No. 325.8916 (2)
 Risk Assessor: Matthew K Rodgers
 P-04247

CONDITION KEY	YES	NO
Roof missing parts of surfaces: tiles, boards, etc. COMMENTS:		X
Roof has holes or large cracks COMMENTS:		X
Gutters/downspouts broken COMMENTS:		X
Chimney masonry cracked, bricks loose or missing, obviously out of plumb COMMENTS:		X
Exterior walls have obvious large cracks/ holes requiring more than routine painting COMMENTS:		X
Exterior siding missing boards or shingles COMMENTS:		X
Water stains on interior walls or ceilings COMMENTS:		X
Plaster walls deteriorated COMMENTS:		X
Two or more windows or doors broken, missing or boarded up COMMENTS:		X
Porch or steps have major elements broken, missing, or boarded up COMMENTS:		X
Foundation has major cracks, missing material, structural beams or visibly unsound COMMENTS:		X
TOTAL		11

TOTAL: IF THERE ARE TWO OR MORE CHECKS IN THE YES COLUMN, THE DWELLING IS CONSIDERED TO BE IN POOR CONDITION FOR THE PURPOSES OF A RISK ASSESSMENT. HOWEVER, CONSIDER ALL SPECIFIC CONDITIONS AND EXTENUATING CIRCUMSTANCES BEFORE DETERMINING FINAL CONDITION OR APPROPRIATENESS OF A LEAD HAZARD SCREEN.

PROPERTY:	Hikone
UNIT NO.:	2718
OWNER:	Ann Arbor Housing Commission
DATE:	5/20/13

HUD FORM 5.1
 BUILDING CONDITION CHECKLIST
 LHRP Rule No. 325.8916 (2)
 Risk Assessor: Matthew K Rodgers
 P-04247

CONDITION KEY	YES	NO
Roof missing parts of surfaces: tiles, boards, etc. COMMENTS:		X
Roof has holes or large cracks COMMENTS:		X
Gutters/downspouts broken COMMENTS:		X
Chimney masonry cracked, bricks loose or missing, obviously out of plumb COMMENTS:		X
Exterior walls have obvious large cracks/ holes requiring more than routine painting COMMENTS:		X
Exterior siding missing boards or shingles COMMENTS:		X
Water stains on interior walls or ceilings COMMENTS:		X
Plaster walls deteriorated COMMENTS:		X
Two or more windows or doors broken, missing or boarded up COMMENTS:		X
Porch or steps have major elements broken, missing, or boarded up COMMENTS:		X
Foundation has major cracks, missing material, structural leans or visibly unsound COMMENTS:		X
TOTAL		11

TOTAL: IF THERE ARE TWO OR MORE CHECKS IN THE YES COLUMN, THE DWELLING IS CONSIDERED TO BE IN POOR CONDITION FOR THE PURPOSES OF A RISK ASSESSMENT. HOWEVER, CONSIDER ALL SPECIFIC CONDITIONS AND EXTENUATING CIRCUMSTANCES BEFORE DETERMINING FINAL CONDITION OR APPROPRIATENESS OF A LEAD HAZARD SCREEN.

PROPERTY:	Hikone
UNIT NO.:	2722
OWNER:	Ann Arbor Housing Commission
DATE:	5/20/13

HUD FORM 5.1
BUILDING CONDITION CHECKLIST
LHRP Rule No. 325.8916 (2)
Risk Assessor: Matthew K Rodgers
P-04247

CONDITION KEY	YES	NO
Roof missing parts of surfaces: tiles, boards, etc. COMMENTS:		X
Roof has holes or large cracks COMMENTS:		X
Gutters/downspouts broken COMMENTS:		X
Chimney masonry cracked, bricks loose or missing, obviously out of plumb COMMENTS:		X
Exterior walls have obvious large cracks/ holes requiring more than routine painting COMMENTS:		X
Exterior siding missing boards or shingles COMMENTS:		X
Water stains on interior walls or ceilings COMMENTS:		X
Plaster walls deteriorated COMMENTS:		X
Two or more windows or doors broken, missing or boarded up COMMENTS:		X
Porch or steps have major elements broken, missing, or boarded up COMMENTS:		X
Foundation has major cracks, missing material, structural beams or visibly unsound COMMENTS:		X
TOTAL		11

TOTAL: IF THERE ARE TWO OR MORE CHECKS IN THE YES COLUMN, THE DWELING IS CONSIDERED TO BE IN POOR CONDITION FOR THE PURPOSES OF A RISK ASSESSMENT. HOWEVER, CONSIDER ALL SPECIFIC CONDITIONS AND EXTENUATING CIRCUMSTANCES BEFORE DETERMINING FINAL CONDITION OR APPROPRIATENESS OF A LEAD HAZARD SCREEN.

PROPERTY:	Hikone
UNIT NO.:	2726
OWNER:	Ann Arbor Housing Commission
DATE:	5/21/13

HUD FORM 5.1

BUILDING CONDITION CHECKLIST

LHRP Rule No. 325.8916 (2)

Risk Assessor: Matthew K Rodgers
P-04247

CONDITION KEY	YES	NO
Roof missing parts of surfaces: tiles, boards, etc. COMMENTS:		X
Roof has holes or large cracks COMMENTS:		X
Gutters/downspouts broken COMMENTS:		X
Chimney masonry cracked, bricks loose or missing, obviously out of plumb COMMENTS:		X
Exterior walls have obvious large cracks/ holes requiring more than routine painting COMMENTS:		X
Exterior siding missing boards or shingles COMMENTS:		X
Water stains on interior walls or ceilings COMMENTS:		X
Plaster walls deteriorated COMMENTS:		X
Two or more windows or doors broken, missing or boarded up COMMENTS:		X
Porch or steps have major elements broken, missing, or boarded up COMMENTS:		X
Foundation has major cracks, missing material, structural leans or visibly unsound COMMENTS:		X
TOTAL		11

TOTAL: IF THERE ARE TWO OR MORE CHECKS IN THE YES COLUMN, THE DWELLING IS CONSIDERED TO BE IN POOR CONDITION FOR THE PURPOSES OF A RISK ASSESSMENT. HOWEVER, CONSIDER ALL SPECIFIC CONDITIONS AND EXTENUATING CIRCUMSTANCES BEFORE DETERMINING FINAL CONDITION OR APPROPRIATENESS OF A LEAD HAZARD SCREEN.

PROPERTY:	Hikone
UNIT NO.:	2728
OWNER:	Ann Arbor Housing Commission
DATE:	5/21/13

HUD FORM 5.1
BUILDING CONDITION CHECKLIST
LHRP Rule No. 325.8916 (2)
Risk Assessor: Matthew K Rodgers
P-04247

CONDITION KEY	YES	NO
Roof missing parts of surfaces: tiles, boards, etc. COMMENTS:		X
Roof has holes or large cracks COMMENTS:		X
Gutters/downspouts broken COMMENTS:		X
Chimney masonry cracked, bricks loose or missing, obviously out of plumb COMMENTS:		X
Exterior walls have obvious large cracks/ holes requiring more than routine painting COMMENTS:		X
Exterior siding missing boards or shingles COMMENTS:		X
Water stains on interior walls or ceilings COMMENTS:		X
Plaster walls deteriorated COMMENTS:		X
Two or more windows or doors broken, missing or boarded up COMMENTS:		X
Porch or steps have major elements broken, missing, or boarded up COMMENTS:		X
Foundation has major cracks, missing material, structural leans or visibly unsound COMMENTS:		X
TOTAL		11

TOTAL: IF THERE ARE TWO OR MORE CHECKS IN THE YES COLUMN, THE DWELING IS CONSIDERED TO BE IN POOR CONDITION FOR THE PURPOSES OF A RISK ASSESSMENT. HOWEVER, CONSIDER ALL SPECIFIC CONDITIONS AND EXTENUATING CIRCUMSTANCES BEFORE DETERMINING FINAL CONDITION OR APPROPRIATENESS OF A LEAD HAZARD SCREEN.

PROPERTY:	Hikone
UNIT NO.:	2730
OWNER:	Ann Arbor Housing Commission
DATE:	5/21/13

HUD FORM 5.1
BUILDING CONDITION CHECKLIST
LHRP Rule No. 325.8916 (2)
Risk Assessor: Matthew K Rodgers
P-04247

CONDITION KEY	YES	NO
Roof missing parts of surfaces: tiles, boards, etc. COMMENTS:		X
Roof has holes or large cracks COMMENTS:		X
Gutters/downspouts broken COMMENTS:		X
Chimney masonry cracked, bricks loose or missing, obviously out of plumb COMMENTS:		X
Exterior walls have obvious large cracks/ holes requiring more than routine painting COMMENTS:		X
Exterior siding missing boards or shingles COMMENTS:		X
Water stains on interior walls or ceilings COMMENTS:		X
Plaster walls deteriorated COMMENTS:		X
Two or more windows or doors broken, missing or boarded up COMMENTS:		X
Porch or steps have major elements broken, missing, or boarded up COMMENTS:		X
Foundation has major cracks, missing material, structural leans or visibly unsound COMMENTS:		X
TOTAL		11

TOTAL: IF THERE ARE TWO OR MORE CHECKS IN THE YES COLUMN, THE DWELING IS CONSIDERED TO BE IN POOR CONDITION FOR THE PURPOSES OF A RISK ASSESSMENT. HOWEVER, CONSIDER ALL SPECIFIC CONDITIONS AND EXTENUATING CIRCUMSTANCES BEFORE DETERMINING FINAL CONDITION OR APPROPRIATENESS OF A LEAD HAZARD SCREEN.

PROPERTY:	Hikone
UNIT NO.:	2732
OWNER:	Ann Arbor Housing Commission
DATE:	5/21/13

HUD FORM 5.1
BUILDING CONDITION CHECKLIST
LHRP Rule No. 325.8916 (2)
Risk Assessor: Matthew K Rodgers
P-04247

CONDITION KEY	YES	NO
Roof missing parts of surfaces: tiles, boards, etc. COMMENTS:		X
Roof has holes or large cracks COMMENTS:		X
Gutters/downspouts broken COMMENTS:		X
Chimney masonry cracked, bricks loose or missing, obviously out of plumb COMMENTS:		X
Exterior walls have obvious large cracks/ holes requiring more than routine painting COMMENTS:		X
Exterior siding missing boards or shingles COMMENTS:		X
Water stains on interior walls or ceilings COMMENTS:		X
Plaster walls deteriorated COMMENTS:		X
Two or more windows or doors broken, missing or boarded up COMMENTS:		X
Porch or steps have major elements broken, missing, or boarded up COMMENTS:		X
Foundation has major cracks, missing material, structural leans or visibly unsound COMMENTS:		X
TOTAL		11

TOTAL: IF THERE ARE TWO OR MORE CHECKS IN THE YES COLUMN, THE DWELLING IS CONSIDERED TO BE IN POOR CONDITION FOR THE PURPOSES OF A RISK ASSESSMENT. HOWEVER, CONSIDER ALL SPECIFIC CONDITIONS AND EXTENUATING CIRCUMSTANCES BEFORE DETERMINING FINAL CONDITION OR APPROPRIATENESS OF A LEAD HAZARD SCREEN.

PROPERTY:	Hikone
UNIT NO.:	2742
OWNER:	Ann Arbor Housing Commission
DATE:	5/21/13

HUD FORM 5.1

BUILDING CONDITION CHECKLIST

LHRP Rule No. 325.9916 (2)

Risk Assessor: Matthew K Rodgers
P-04247

CONDITION KEY	YES	NO
Roof missing parts of surfaces: tiles, boards, etc. COMMENTS:		X
Roof has holes or large cracks COMMENTS:		X
Gutters/downspouts broken COMMENTS:		X
Chimney masonry cracked, bricks loose or missing, obviously out of plumb COMMENTS:		X
Exter/inter walls have obvious large cracks/ holes requiring more than routine painting COMMENTS:		X
Exterior siding missing boards or shingles COMMENTS:		X
Water stains on interior walls or ceilings COMMENTS:		X
Plaster walls deteriorated COMMENTS:		X
Two or more windows or doors broken, missing or boarded up COMMENTS:		X
Porch or steps have major elements broken, missing, or boarded up COMMENTS:		X
Foundation has major cracks, missing material, structural leans or visibly unsound COMMENTS:		X
TOTAL		11

TOTAL: IF THERE ARE TWO OR MORE CHECKS IN THE YES COLUMN, THE DWELLING IS CONSIDERED TO BE IN POOR CONDITION FOR THE PURPOSES OF A RISK ASSESSMENT. HOWEVER, CONSIDER ALL SPECIFIC CONDITIONS AND EXTENUATING CIRCUMSTANCES BEFORE DETERMINING FINAL CONDITION OR APPROPRIATENESS OF A LEAD HAZARD SCREEN.

PROPERTY:	Hikone
UNIT NO.:	2748
OWNER:	Ann Arbor Housing Commission
DATE:	5/21/13

HUD FORM 5.1
BUILDING CONDITION CHECKLIST
LHRP Rule No. 325.0916 (2)
Risk Assessor: Matthew K Rodgers
P-04247

CONDITION KEY	YES	NO
Roof missing parts of surfaces: tiles, boards, etc. COMMENTS:		X
Roof has holes or large cracks COMMENTS:		X
Gutters/downspouts broken COMMENTS:		X
Chimney masonry cracked, bricks loose or missing, obviously out of plumb COMMENTS:		X
Exterior walls have obvious large cracks/ holes requiring more than routine painting COMMENTS:		X
Exterior siding missing boards or shingles COMMENTS:		X
Water stains on interior walls or ceilings COMMENTS:		X
Plaster walls deteriorated COMMENTS:		X
Two or more windows or doors broken, missing or boarded up COMMENTS:		X
Porch or steps have major elements broken, missing, or boarded up COMMENTS:		X
Foundation has major cracks, missing material, structural leans or visibly unsound COMMENTS:		X
TOTAL		11

TOTAL: IF THERE ARE TWO OR MORE CHECKS IN THE YES COLUMN, THE DWELLING IS CONSIDERED TO BE IN POOR CONDITION FOR THE PURPOSES OF A RISK ASSESSMENT. HOWEVER, CONSIDER ALL SPECIFIC CONDITIONS AND EXTENUATING CIRCUMSTANCES BEFORE DETERMINING FINAL CONDITION OR APPROPRIATENESS OF A LEAD HAZARD SCREEN.

APPENDIX C

XRF FIELD DATA SHEET

Reading	Time	Units	Component	Substrate	Side	Condition	Color	Site	Inspector	Floor	Room	Results	Depth	Action	PbC	PbC Error
1118	5/20/13	mg/cm ²	cal									Positive	1.06	1	1	0.1
1119	5/20/13	mg/cm ²	cal									Negative	1.02	1	0.9	0.1
1120	5/20/13	mg/cm ²	cal									Positive	1.08	1	1	0.1
1121	5/20/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2710 m.r		FIRST	LIVING ROOM	Negative	1	1	0	0.02
1122	5/20/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2710 m.r		FIRST	LIVING ROOM	Negative	1	1	0	0.02
1123	5/20/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2710 m.r		FIRST	LIVING ROOM	Negative	1.14	1	0	0.02
1124	5/20/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2710 m.r		FIRST	LIVING ROOM	Negative	4.45	1	0.02	0.08
1125	5/20/13	mg/cm ²	CEILING	DRYWALL	A	INTACT	WHITE	2710 m.r		FIRST	LIVING ROOM	Negative	1	1	0	0.02
1126	5/20/13	mg/cm ²	BASEBOARD	WOOD	A	INTACT	WHITE	2710 m.r		FIRST	LIVING ROOM	Negative	6.53	1	0.04	0.13
1127	5/20/13	mg/cm ²	WINDOW t	WOOD	C	INTACT	WHITE	2710 m.r		FIRST	LIVING ROOM	Negative	1.83	1	0.01	0.04
1128	5/20/13	mg/cm ²	WINDOW s	WOOD	C	INTACT	WHITE	2710 m.r		FIRST	LIVING ROOM	Negative	1	1	0	0.03
1129	5/20/13	mg/cm ²	DOOR	WOOD	C	INTACT	BLUE	2710 m.r		FIRST	LIVING ROOM	Negative	1.01	1	0.08	0.09
1130	5/20/13	mg/cm ²	DOOR t	WOOD	C	INTACT	BLUE	2710 m.r		FIRST	LIVING ROOM	Negative	1	1	0	0.02
1131	5/20/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2710 m.r		FIRST	BEDROOM 1	Negative	1.25	1	0	0.02
1132	5/20/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2710 m.r		FIRST	BEDROOM 1	Negative	1	1	0	0.02
1133	5/20/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2710 m.r		FIRST	BEDROOM 1	Negative	1	1	0	0.02
1134	5/20/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2710 m.r		FIRST	BEDROOM 1	Negative	1.37	1	0	0.02
1135	5/20/13	mg/cm ²	CEILING	DRYWALL	D	INTACT	WHITE	2710 m.r		FIRST	BEDROOM 1	Negative	1	1	0	0.02
1136	5/20/13	mg/cm ²	BASEBOARD	WOOD	A	INTACT	WHITE	2710 m.r		FIRST	BEDROOM 1	Negative	1	1	0	0.02
1137	5/20/13	mg/cm ²	WINDOW t	WOOD	A	INTACT	WHITE	2710 m.r		FIRST	BEDROOM 1	Negative	1	1	0	0.02
1138	5/20/13	mg/cm ²	WINDOW s	WOOD	A	INTACT	WHITE	2710 m.r		FIRST	BEDROOM 1	Negative	1	1	0	0.02
1139	5/20/13	mg/cm ²	DOOR	WOOD	C	INTACT	WHITE	2710 m.r		FIRST	BEDROOM 1	Negative	1	1	0	0.02
1140	5/20/13	mg/cm ²	DOOR J	WOOD	C	INTACT	WHITE	2710 m.r		FIRST	BEDROOM 1	Negative	1	1	0.01	0.02
1141	5/20/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2710 m.r		FIRST	BEDROOM 2	Negative	1.02	1	0	0.02
1142	5/20/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2710 m.r		FIRST	BEDROOM 2	Negative	1	1	0	0.02
1143	5/20/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2710 m.r		FIRST	BEDROOM 2	Negative	2.23	1	0.01	0.04
1144	5/20/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2710 m.r		FIRST	BEDROOM 2	Negative	1	1	0	0.02
1145	5/20/13	mg/cm ²	CEILING	DRYWALL	D	INTACT	WHITE	2710 m.r		FIRST	BEDROOM 2	Negative	2.53	1	0.01	0.04
1146	5/20/13	mg/cm ²	BASEBOARD	WOOD	A	INTACT	WHITE	2710 m.r		FIRST	BEDROOM 2	Negative	3.34	1	0.01	0.05
1147	5/20/13	mg/cm ²	WINDOW t	WOOD	A	INTACT	WHITE	2710 m.r		FIRST	BEDROOM 2	Negative	1.97	1	0.01	0.03
1148	5/20/13	mg/cm ²	WINDOW s	WOOD	A	INTACT	WHITE	2710 m.r		FIRST	BEDROOM 2	Negative	1	1	0	0.02
1149	5/20/13	mg/cm ²	DOOR	WOOD	C	INTACT	WHITE	2710 m.r		FIRST	BEDROOM 2	Negative	1	1	0	0.03
1150	5/20/13	mg/cm ²	DOOR t	WOOD	C	INTACT	WHITE	2710 m.r		FIRST	BEDROOM 2	Negative	2.65	1	0.02	0.08
1151	5/20/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2710 m.r		FIRST	BATHROOM	Negative	2.78	1	0.02	0.08
1152	5/20/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2710 m.r		FIRST	BATHROOM	Negative	2.38	1	0.01	0.05
1153	5/20/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2710 m.r		FIRST	BATHROOM	Negative	1.48	1	0	0.02
1154	5/20/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2710 m.r		FIRST	BATHROOM	Negative	1.43	1	0.01	0.03
1155	5/20/13	mg/cm ²	CEILING	DRYWALL	D	INTACT	WHITE	2710 m.r		FIRST	BATHROOM	Negative	3.25	1	0.03	0.1
1156	5/20/13	mg/cm ²	TRIM	WOOD	D	INTACT	WHITE	2710 m.r		FIRST	BATHROOM	Negative	1	1	0	0.02
1157	5/20/13	mg/cm ²	DOOR	WOOD	D	INTACT	WHITE	2710 m.r		FIRST	BATHROOM	Negative	1	1	0	0.03
1158	5/20/13	mg/cm ²	DOOR t	WOOD	D	INTACT	WHITE	2710 m.r		FIRST	BATHROOM	Negative	2.88	1	0.02	0.11
1159	5/20/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2710 m.r		FIRST	KITCHEN	Negative	7.47	1	0.04	0.09
1160	5/20/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2710 m.r		FIRST	KITCHEN	Negative	2.2	1	0	0.03
1161	5/20/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2710 m.r		FIRST	KITCHEN	Negative	2.49	1	0.01	0.05
1162	5/20/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2710 m.r		FIRST	KITCHEN	Negative	2.41	1	0.01	0.03

1163	5/20/13	mg/cm^2	WALL	DRYWALL	A	INTACT	WHITE	2708	m.r	FIRST	KITCHEN	Negative	1	1	0	0.02
1164	5/20/13	mg/cm^2	WALL	DRYWALL	B	INTACT	WHITE	2708	m.r	FIRST	KITCHEN	Negative	4.49	1	0.01	0.06
1165	5/20/13	mg/cm^2	WALL	DRYWALL	C	INTACT	WHITE	2708	m.r	FIRST	KITCHEN	Negative	1.81	1	0	0.02
1166	5/20/13	mg/cm^2	WALL	DRYWALL	D	INTACT	WHITE	2708	m.r	FIRST	KITCHEN	Negative	1	1	0	0.02
1167	5/20/13	mg/cm^2	CEILING	DRYWALL	D	INTACT	WHITE	2708	m.r	FIRST	KITCHEN	Negative	1	1	0	0.02
1168	5/20/13	mg/cm^2	BASEBOARD	DRYWALL	D	INTACT	WHITE	2708	m.r	FIRST	KITCHEN	Negative	2.49	1	0	0.02
1169	5/20/13	mg/cm^2	DOOR	WOOD	A	INTACT	WHITE	2708	m.r	FIRST	KITCHEN	Negative	1	1	0.3	0.32
1170	5/20/13	mg/cm^2	DOOR	WOOD	A	INTACT	WHITE	2708	m.r	FIRST	KITCHEN	Negative	1	1	0	0.02
1171	5/20/13	mg/cm^2	WALL	DRYWALL	A	INTACT	WHITE	2708	m.r	FIRST	LIVING ROOM	Negative	1	1	0	0.02
1172	5/20/13	mg/cm^2	WALL	DRYWALL	B	INTACT	WHITE	2708	m.r	FIRST	LIVING ROOM	Negative	1.14	1	0	0.02
1173	5/20/13	mg/cm^2	WALL	DRYWALL	C	INTACT	WHITE	2708	m.r	FIRST	LIVING ROOM	Negative	6.53	1	0.02	0.1
1174	5/20/13	mg/cm^2	WALL	DRYWALL	D	INTACT	WHITE	2708	m.r	FIRST	LIVING ROOM	Negative	1	1	0	0.02
1175	5/20/13	mg/cm^2	DOOR	WOOD	A	INTACT	WHITE	2708	m.r	FIRST	LIVING ROOM	Negative	1.25	1	0.11	0.12
1176	5/20/13	mg/cm^2	DOOR t	WOOD	A	INTACT	WHITE	2708	m.r	FIRST	LIVING ROOM	Negative	1	1	0	0.02
1177	5/20/13	mg/cm^2	WINDOW t	WOOD	A	INTACT	WHITE	2708	m.r	FIRST	LIVING ROOM	Negative	1	1	0	0.02
1178	5/20/13	mg/cm^2	WINDOW s	WOOD	A	INTACT	WHITE	2708	m.r	FIRST	LIVING ROOM	Negative	1	1	0	0.02
1179	5/20/13	mg/cm^2	WALL	DRYWALL	A	INTACT	WHITE	2708	m.r	FIRST	BATHROOM	Negative	6.79	1	0.06	0.1
1180	5/20/13	mg/cm^2	WALL	DRYWALL	B	INTACT	WHITE	2708	m.r	FIRST	BATHROOM	Negative	2.79	1	0.02	0.08
1181	5/20/13	mg/cm^2	WALL	DRYWALL	C	INTACT	WHITE	2708	m.r	FIRST	BATHROOM	Negative	6.36	1	0.08	0.23
1182	5/20/13	mg/cm^2	WALL	DRYWALL	D	INTACT	WHITE	2708	m.r	FIRST	BATHROOM	Negative	1.36	1	0	0.02
1183	5/20/13	mg/cm^2	CEILING	DRYWALL	D	INTACT	WHITE	2708	m.r	FIRST	BATHROOM	Negative	1	1	0	0.02
1184	5/20/13	mg/cm^2	DOOR	WOOD	D	INTACT	WHITE	2708	m.r	FIRST	BATHROOM	Negative	1	1	0	0.03
1185	5/20/13	mg/cm^2	DOOR j	WOOD	D	INTACT	WHITE	2708	m.r	FIRST	BATHROOM	Negative	1	1	0	0.02
1186	5/20/13	mg/cm^2	WALL	DRYWALL	A	INTACT	WHITE	2708	m.r	SECOND	STAIR	Negative	1.88	1	0.01	0.03
1187	5/20/13	mg/cm^2	WALL	DRYWALL	B	INTACT	WHITE	2708	m.r	SECOND	STAIR	Negative	1	1	0	0.02
1188	5/20/13	mg/cm^2	WALL	DRYWALL	C	INTACT	WHITE	2708	m.r	SECOND	STAIR	Negative	1	1	0	0.02
1189	5/20/13	mg/cm^2	WALL	DRYWALL	D	INTACT	WHITE	2708	m.r	SECOND	STAIR	Negative	2.15	1	0.01	0.04
1190	5/20/13	mg/cm^2	CEILING	DRYWALL	D	INTACT	WHITE	2708	m.r	SECOND	STAIR	Negative	1	1	0.01	0.06
1191	5/20/13	mg/cm^2	WALL	DRYWALL	A	INTACT	WHITE	2708	m.r	SECOND	BEDROOM 1	Negative	10	1	0.06	0.93
1192	5/20/13	mg/cm^2	WALL	DRYWALL	B	INTACT	WHITE	2708	m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.02
1193	5/20/13	mg/cm^2	WALL	DRYWALL	C	INTACT	WHITE	2708	m.r	SECOND	BEDROOM 1	Negative	2.86	1	0.01	0.04
1194	5/20/13	mg/cm^2	WALL	DRYWALL	D	INTACT	WHITE	2708	m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.02
1195	5/20/13	mg/cm^2	CEILING	DRYWALL	D	INTACT	WHITE	2708	m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.02
1196	5/20/13	mg/cm^2	WINDOW t	WOOD	D	INTACT	WHITE	2708	m.r	SECOND	BEDROOM 1	Negative	2.01	1	0.01	0.03
1197	5/20/13	mg/cm^2	WINDOW s	WOOD	D	INTACT	WHITE	2708	m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.02
1198	5/20/13	mg/cm^2	DOOR	WOOD	A	INTACT	WHITE	2708	m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.02
1199	5/20/13	mg/cm^2	DOOR j	WOOD	A	INTACT	WHITE	2708	m.r	SECOND	BEDROOM 1	Negative	1.07	1	0	0.02
1200	5/20/13	mg/cm^2	WALL	DRYWALL	A	INTACT	WHITE	2708	m.r	SECOND	BEDROOM 2	Negative	1.67	1	0	0.02
1201	5/20/13	mg/cm^2	WALL	DRYWALL	B	INTACT	WHITE	2708	m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.02
1202	5/20/13	mg/cm^2	WALL	DRYWALL	C	INTACT	WHITE	2708	m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.02
1203	5/20/13	mg/cm^2	WALL	DRYWALL	D	INTACT	WHITE	2708	m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.02
1204	5/20/13	mg/cm^2	CEILING	DRYWALL	D	INTACT	WHITE	2708	m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.02
1205	5/20/13	mg/cm^2	BASEBOARD	WOOD	D	INTACT	WHITE	2708	m.r	SECOND	BEDROOM 2	Negative	2.21	1	0.01	0.05
1206	5/20/13	mg/cm^2	WINDOW t	WOOD	D	INTACT	WHITE	2708	m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.02
1207	5/20/13	mg/cm^2	WINDOW s	WOOD	D	INTACT	WHITE	2708	m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.02
1208	5/20/13	mg/cm^2	DOOR t	WOOD	C	INTACT	WHITE	2708	m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.02

1209	5/20/13	mg/cm ²	DOOR	J	WOOD	C	INTACT	WHITE	2708	m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.02
1210	5/20/13	mg/cm ²	WALL		DRYWALL	A	INTACT	WHITE	2708	m.r	SECOND	BEDROOM 3	Negative	1	1	0	0.02
1211	5/20/13	mg/cm ²	WALL		DRYWALL	C	INTACT	WHITE	2708	m.r	SECOND	BEDROOM 3	Negative	1	1	0	0.02
1212	5/20/13	mg/cm ²	WALL		DRYWALL	D	INTACT	WHITE	2708	m.r	SECOND	BEDROOM 3	Negative	1	1	0	0.02
1213	5/20/13	mg/cm ²	CEILING		DRYWALL	D	INTACT	WHITE	2708	m.r	SECOND	BEDROOM 3	Negative	5.54	1	0.03	0.12
1214	5/20/13	mg/cm ²	BASEBOARD		WOOD	D	INTACT	WHITE	2708	m.r	SECOND	BEDROOM 3	Negative	1	1	0	0.02
1215	5/20/13	mg/cm ²	WINDOW	t	WOOD	D	INTACT	WHITE	2708	m.r	SECOND	BEDROOM 3	Negative	1	1	0	0.02
1216	5/20/13	mg/cm ²	WINDOW	s	WOOD	D	INTACT	WHITE	2708	m.r	SECOND	BEDROOM 3	Negative	1	1	0	0.03
1217	5/20/13	mg/cm ²	DOOR		WOOD	A	INTACT	WHITE	2708	m.r	SECOND	BEDROOM 3	Negative	1	1	0	0.03
1218	5/20/13	mg/cm ²	DOOR	J	WOOD	A	INTACT	WHITE	2708	m.r	SECOND	BEDROOM 3	Negative	1	1	0	0.02
1219	5/20/13	mg/cm ²	WALL		DRYWALL	A	INTACT	WHITE	2708	m.r	SECOND	BEDROOM 4	Negative	2.96	1	0.01	0.05
1220	5/20/13	mg/cm ²	WALL		DRYWALL	B	INTACT	WHITE	2708	m.r	SECOND	BEDROOM 4	Negative	1	1	0	0.02
1221	5/20/13	mg/cm ²	WALL		DRYWALL	C	INTACT	WHITE	2708	m.r	SECOND	BEDROOM 4	Negative	1	1	0	0.02
1222	5/20/13	mg/cm ²	WALL		DRYWALL	D	INTACT	WHITE	2708	m.r	SECOND	BEDROOM 4	Negative	1.23	1	0	0.02
1223	5/20/13	mg/cm ²	CEILING		DRYWALL	A	INTACT	WHITE	2708	m.r	SECOND	BEDROOM 4	Negative	1	1	0	0.02
1224	5/20/13	mg/cm ²	WINDOW	t	DRYWALL	A	INTACT	WHITE	2708	m.r	SECOND	BEDROOM 4	Negative	1	1	0	0.02
1225	5/20/13	mg/cm ²	WINDOW	s	DRYWALL	A	INTACT	WHITE	2708	m.r	SECOND	BEDROOM 4	Negative	1	1	0	0.02
1226	5/20/13	mg/cm ²	DOOR		WOOD	A	INTACT	WHITE	2708	m.r	SECOND	BEDROOM 4	Negative	1	1	0	0.03
1227	5/20/13	mg/cm ²	DOOR	J	WOOD	A	INTACT	WHITE	2708	m.r	SECOND	BEDROOM 4	Negative	2.38	1	0.01	0.06
1228	5/20/13	mg/cm ²	WALL		DRYWALL	A	INTACT	WHITE	2708	m.r	SECOND	BEDROOM 4	Negative	2.79	1	0.03	0.1
1229	5/20/13	mg/cm ²	WALL		DRYWALL	B	INTACT	WHITE	2708	m.r	SECOND	BEDROOM 4	Negative	1	1	0	0.02
1230	5/20/13	mg/cm ²	WALL		DRYWALL	C	INTACT	WHITE	2708	m.r	SECOND	BEDROOM 4	Negative	1	1	0	0.02
1231	5/20/13	mg/cm ²	WALL		DRYWALL	D	INTACT	WHITE	2708	m.r	SECOND	BEDROOM 4	Negative	5.24	1	0.03	0.1
1232	5/20/13	mg/cm ²	CEILING		DRYWALL	D	INTACT	WHITE	2708	m.r	SECOND	BEDROOM 4	Negative	1.33	1	0.01	0.03
1233	5/20/13	mg/cm ²	DOOR		WOOD	A	INTACT	WHITE	2708	m.r	SECOND	BEDROOM 4	Negative	1	1	0	0.02
1234	5/20/13	mg/cm ²	DOOR	t	WOOD	A	INTACT	WHITE	2706	m.r	SECOND	BEDROOM 4	Negative	2.38	1	0.01	0.06
1235	5/20/13	mg/cm ²	WALL		DRYWALL	A	INTACT	WHITE	2706	m.r	SECOND	LIVING ROOM	Negative	1.43	1	0	0.02
1236	5/20/13	mg/cm ²	WALL		DRYWALL	B	INTACT	WHITE	2706	m.r	SECOND	LIVING ROOM	Negative	1	1	0	0.02
1237	5/20/13	mg/cm ²	WALL		DRYWALL	C	INTACT	WHITE	2706	m.r	SECOND	LIVING ROOM	Negative	1	1	0	0.02
1238	5/20/13	mg/cm ²	WALL		DRYWALL	D	INTACT	WHITE	2706	m.r	SECOND	LIVING ROOM	Negative	2.53	1	0.01	0.05
1239	5/20/13	mg/cm ²	CEILING		DRYWALL	A	INTACT	WHITE	2706	m.r	SECOND	LIVING ROOM	Negative	3.77	1	0.02	0.08
1240	5/20/13	mg/cm ²	BASEBOARD		DRYWALL	A	INTACT	WHITE	2706	m.r	SECOND	LIVING ROOM	Negative	1	1	0	0.02
1241	5/20/13	mg/cm ²	WINDOW	t	DRYWALL	A	INTACT	WHITE	2706	m.r	SECOND	LIVING ROOM	Negative	1	1	0	0.02
1242	5/20/13	mg/cm ²	WINDOW	s	DRYWALL	A	INTACT	WHITE	2706	m.r	SECOND	LIVING ROOM	Negative	1	1	0	0.02
1243	5/20/13	mg/cm ²	DOOR		WOOD	C	INTACT	WHITE	2706	m.r	SECOND	LIVING ROOM	Negative	2.54	1	0.16	0.3
1244	5/20/13	mg/cm ²	DOOR	J	WOOD	C	INTACT	WHITE	2706	m.r	SECOND	LIVING ROOM	Negative	1	1	0	0.02
1245	5/20/13	mg/cm ²	WALL		DRYWALL	A	INTACT	WHITE	2706	m.r	SECOND	LIVING ROOM	Negative	1	1	0	0.02
1246	5/20/13	mg/cm ²	WALL		DRYWALL	B	INTACT	WHITE	2706	m.r	SECOND	LIVING ROOM	Negative	1	1	0	0.02
1247	5/20/13	mg/cm ²	WALL		DRYWALL	C	INTACT	WHITE	2706	m.r	SECOND	LIVING ROOM	Negative	1	1	0	0.02
1248	5/20/13	mg/cm ²	WALL		DRYWALL	D	INTACT	WHITE	2706	m.r	SECOND	LIVING ROOM	Negative	1	1	0	0.02
1249	5/20/13	mg/cm ²	CEILING		DRYWALL	A	INTACT	WHITE	2706	m.r	SECOND	LIVING ROOM	Negative	1	1	0	0.02
1250	5/20/13	mg/cm ²	BASEBOARD		WOOD	A	INTACT	WHITE	2706	m.r	SECOND	LIVING ROOM	Negative	2.01	1	0.01	0.03
1251	5/20/13	mg/cm ²	DOOR		WOOD	A	INTACT	WHITE	2706	m.r	SECOND	LIVING ROOM	Negative	1.6	1	0.17	0.24
1252	5/20/13	mg/cm ²	DOOR	t	WOOD	A	INTACT	WHITE	2706	m.r	SECOND	LIVING ROOM	Negative	1	1	0	0.02
1253	5/20/13	mg/cm ²	WINDOW	t	WOOD	A	INTACT	WHITE	2706	m.r	SECOND	LIVING ROOM	Negative	1	1	0	0.02
1254	5/20/13	mg/cm ²	WINDOW	s	WOOD	A	INTACT	WHITE	2706	m.r	SECOND	LIVING ROOM	Negative	1	1	0	0.02

1255	5/20/13	mg/cm^2	WALL	DRYWALL	A	INTACT	WHITE	2706 m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.02
1256	5/20/13	mg/cm^2	WALL	DRYWALL	B	INTACT	WHITE	2706 m.r	SECOND	BEDROOM 1	Negative	3.86	1	0.02	0.09
1257	5/20/13	mg/cm^2	WALL	DRYWALL	C	INTACT	WHITE	2706 m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.02
1258	5/20/13	mg/cm^2	WALL	DRYWALL	D	INTACT	WHITE	2706 m.r	SECOND	BEDROOM 1	Negative	1.29	1	0	0.02
1259	5/20/13	mg/cm^2	CEILING	DRYWALL	A	INTACT	WHITE	2706 m.r	SECOND	BEDROOM 1	Negative	4.44	1	0.03	0.11
1260	5/20/13	mg/cm^2	BASEBOARD	WOOD	A	INTACT	WHITE	2706 m.r	SECOND	BEDROOM 1	Negative	1.11	1	0	0.02
1261	5/20/13	mg/cm^2	WINDOW t	WOOD	A	INTACT	WHITE	2706 m.r	SECOND	BEDROOM 1	Negative	1.65	1	0.01	0.04
1262	5/20/13	mg/cm^2	WINDOW s	WOOD	A	INTACT	WHITE	2706 m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.02
1263	5/20/13	mg/cm^2	DOOR	WOOD	C	INTACT	BLUE	2706 m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.02
1264	5/20/13	mg/cm^2	DOOR t	WOOD	C	INTACT	BLUE	2706 m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.02
1265	5/20/13	mg/cm^2	WALL	DRYWALL	A	INTACT	WHITE	2706 m.r	SECOND	BATHROOM	Negative	1.49	1	0.01	0.02
1266	5/20/13	mg/cm^2	WALL	DRYWALL	B	INTACT	WHITE	2706 m.r	SECOND	BATHROOM	Negative	2.26	1	0.01	0.04
1267	5/20/13	mg/cm^2	WALL	DRYWALL	C	INTACT	WHITE	2706 m.r	SECOND	BATHROOM	Negative	1	1	0	0.02
1268	5/20/13	mg/cm^2	WALL	DRYWALL	D	INTACT	WHITE	2706 m.r	SECOND	BATHROOM	Negative	5.2	1	0.01	0.06
1269	5/20/13	mg/cm^2	CEILING	DRYWALL	A	INTACT	WHITE	2706 m.r	SECOND	BATHROOM	Negative	1.67	1	0.01	0.03
1270	5/20/13	mg/cm^2	DOOR	WOOD	A	INTACT	WHITE	2706 m.r	SECOND	BATHROOM	Negative	1.21	1	0.01	0.04
1271	5/20/13	mg/cm^2	DOOR t	WOOD	A	INTACT	WHITE	2706 m.r	SECOND	BATHROOM	Negative	1.42	1	0.01	0.03
1272	5/20/13	mg/cm^2	WALL	DRYWALL	A	INTACT	WHITE	2706 m.r	SECOND	BEDROOM 3	Negative	2.67	1	0.01	0.04
1273	5/20/13	mg/cm^2	WALL	DRYWALL	B	INTACT	WHITE	2706 m.r	SECOND	BEDROOM 3	Negative	1.36	1	0.01	0.03
1274	5/20/13	mg/cm^2	WALL	DRYWALL	C	INTACT	WHITE	2706 m.r	SECOND	BEDROOM 3	Negative	3.11	1	0.02	0.07
1275	5/20/13	mg/cm^2	WALL	DRYWALL	D	INTACT	WHITE	2706 m.r	SECOND	BEDROOM 3	Negative	1.89	1	0.01	0.04
1276	5/20/13	mg/cm^2	CEILING	DRYWALL	D	INTACT	WHITE	2706 m.r	SECOND	BEDROOM 3	Negative	1	1	0	0.02
1277	5/20/13	mg/cm^2	BASEBOARD	WOOD	A	INTACT	WHITE	2706 m.r	SECOND	BEDROOM 3	Negative	1	1	0	0.02
1278	5/20/13	mg/cm^2	WINDOW t	WOOD	C	INTACT	WHITE	2706 m.r	SECOND	BEDROOM 3	Negative	1	1	0	0.02
1279	5/20/13	mg/cm^2	WINDOW s	WOOD	C	INTACT	WHITE	2706 m.r	SECOND	BEDROOM 3	Negative	1	1	0	0.02
1280	5/20/13	mg/cm^2	DOOR	WOOD	D	INTACT	WHITE	2706 m.r	SECOND	BEDROOM 3	Negative	1	1	0	0.02
1281	5/20/13	mg/cm^2	DOOR t	WOOD	D	INTACT	WHITE	2706 m.r	SECOND	BEDROOM 3	Negative	1	1	0	0.03
1282	5/20/13	mg/cm^2	WALL	DRYWALL	A	INTACT	WHITE	2706 m.r	SECOND	BEDROOM 2	Negative	1.01	1	0	0.02
1283	5/20/13	mg/cm^2	WALL	DRYWALL	B	INTACT	WHITE	2706 m.r	SECOND	BEDROOM 2	Negative	5.93	1	0.04	0.15
1284	5/20/13	mg/cm^2	WALL	DRYWALL	C	INTACT	WHITE	2706 m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.02
1285	5/20/13	mg/cm^2	WALL	DRYWALL	D	INTACT	WHITE	2706 m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.02
1286	5/20/13	mg/cm^2	CEILING	DRYWALL	D	INTACT	WHITE	2706 m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.02
1287	5/20/13	mg/cm^2	BASEBOARD	DRYWALL	D	INTACT	WHITE	2706 m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.02
1288	5/20/13	mg/cm^2	DOOR	WOOD	C	INTACT	WHITE	2706 m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.03
1289	5/20/13	mg/cm^2	DOOR j	WOOD	C	INTACT	WHITE	2706 m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.02
1290	5/20/13	mg/cm^2	WALL	DRYWALL	A	INTACT	WHITE	2720 m.r	FIRST	KITCHEN	Negative	1	1	0	0.02
1291	5/20/13	mg/cm^2	WALL	DRYWALL	B	INTACT	WHITE	2720 m.r	FIRST	KITCHEN	Negative	10	1	0.4	0.6
1292	5/20/13	mg/cm^2	WALL	DRYWALL	C	INTACT	WHITE	2720 m.r	FIRST	KITCHEN	Negative	9.58	1	0.4	0.6
1293	5/20/13	mg/cm^2	WALL	DRYWALL	D	INTACT	WHITE	2720 m.r	FIRST	KITCHEN	Negative	8.19	1	0.6	0.4
1294	5/20/13	mg/cm^2	CEILING	DRYWALL	A	INTACT	WHITE	2720 m.r	FIRST	KITCHEN	Negative	7.4	1	0.19	0.29
1295	5/20/13	mg/cm^2	BASEBOARD	WOOD	C	INTACT	WHITE	2720 m.r	FIRST	KITCHEN	Negative	10	1	0.6	0.4
1296	5/20/13	mg/cm^2	WINDOW t	WOOD	C	INTACT	WHITE	2720 m.r	FIRST	KITCHEN	Negative	2.56	1	0.02	0.11
1297	5/20/13	mg/cm^2	WINDOW s	WOOD	C	INTACT	WHITE	2720 m.r	FIRST	KITCHEN	Negative	1	1	0	0.02
1298	5/20/13	mg/cm^2	DOOR	WOOD	A	INTACT	WHITE	2720 m.r	FIRST	KITCHEN	Negative	2.54	1	0.4	0.4
1299	5/20/13	mg/cm^2	DOOR j	WOOD	A	INTACT	WHITE	2720 m.r	FIRST	KITCHEN	Negative	1	1	0	0.02
1300	5/20/13	mg/cm^2	WALL	CONCRETE	A	INTACT	WHITE	2720 m.r	BASEMENT	room	Negative	1	1	0	0.02

1301	5/20/13	mg/cm ²	WALL	CONCRETE	B	INTACT	WHITE	2720 m.r	BASEMENT	room	Negative	1	1	0	0.02
1302	5/20/13	mg/cm ²	WALL	CONCRETE	C	INTACT	WHITE	2720 m.r	BASEMENT	room	Negative	1	1	0	0.02
1303	5/20/13	mg/cm ²	WALL	CONCRETE	D	INTACT	WHITE	2720 m.r	BASEMENT	room	Negative	1	1	0	0.02
1304	5/20/13	mg/cm ²	FLOOR	CONCRETE	A	INTACT	WHITE	2720 m.r	BASEMENT	room	Negative	1	1	0	0.02
1305	5/20/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2720 m.r	BASEMENT	STAIR	Negative	1.63	1	0	0.02
1306	5/20/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2720 m.r	BASEMENT	STAIR	Negative	1	1	0	0.02
1307	5/20/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2720 m.r	BASEMENT	STAIR	Negative	1	1	0	0.02
1308	5/20/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2720 m.r	BASEMENT	STAIR	Negative	10	1	0.25	0.52
1309	5/20/13	mg/cm ²	TREAD	WOOD	A	INTACT	BLUE	2720 m.r	BASEMENT	STAIR	Negative	1.18	1	0.02	0.07
1310	5/20/13	mg/cm ²	RISE	WOOD	A	INTACT	BLUE	2720 m.r	BASEMENT	STAIR	Negative	2.08	1	0.05	0.15
1311	5/20/13	mg/cm ²	stringer	WOOD	A	INTACT	BLUE	2720 m.r	BASEMENT	STAIR	Negative	6.16	1	0.13	0.48
1312	5/20/13	mg/cm ²	DOOR	WOOD	A	INTACT	BLUE	2720 m.r	BASEMENT	STAIR	Negative	1	1	0	0.02
1313	5/20/13	mg/cm ²	DOOR t	WOOD	A	INTACT	BLUE	2720 m.r	BASEMENT	STAIR	Negative	1	1	0	0.02
1314	5/20/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2720 m.r	FIRST	LIVING ROOM	Negative	3.89	1	0.02	0.06
1315	5/20/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2720 m.r	FIRST	LIVING ROOM	Negative	1	1	0	0.02
1316	5/20/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2720 m.r	FIRST	LIVING ROOM	Negative	1	1	0	0.02
1317	5/20/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2720 m.r	FIRST	LIVING ROOM	Negative	1.26	1	0	0.02
1318	5/20/13	mg/cm ²	CEILING	DRYWALL	A	INTACT	WHITE	2720 m.r	FIRST	LIVING ROOM	Negative	1	1	0	0.02
1319	5/20/13	mg/cm ²	BASEBOARD	WOOD	A	INTACT	WHITE	2720 m.r	FIRST	LIVING ROOM	Negative	2.05	1	0.01	0.04
1320	5/20/13	mg/cm ²	DOOR	WOOD	A	INTACT	WHITE	2720 m.r	FIRST	LIVING ROOM	Negative	1.15	1	0.21	0.16
1321	5/20/13	mg/cm ²	DOOR T	WOOD	A	INTACT	WHITE	2720 m.r	FIRST	LIVING ROOM	Negative	1	1	0	0.02
1322	5/20/13	mg/cm ²	DOOR	WOOD	A	INTACT	WHITE	2720 m.r	FIRST	LIVING ROOM	Negative	2.14	1	0.4	0.3
1323	5/20/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2720 m.r	SECOND	STAIR	Negative	2.95	1	0.01	0.04
1324	5/20/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2720 m.r	SECOND	STAIR	Negative	1	1	0	0.02
1325	5/20/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2720 m.r	SECOND	STAIR	Negative	1	1	0	0.02
1326	5/20/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2720 m.r	SECOND	STAIR	Negative	1	1	0	0.02
1327	5/20/13	mg/cm ²	CEILING	DRYWALL	D	INTACT	WHITE	2720 m.r	SECOND	STAIR	Negative	1	1	0	0.03
1328	5/20/13	mg/cm ²	BASEBOARD	WOOD	A	INTACT	WHITE	2720 m.r	SECOND	STAIR	Negative	1	1	0	0.02
1329	5/20/13	mg/cm ²	RISE	WOOD	A	INTACT	WHITE	2720 m.r	SECOND	STAIR	Negative	1	1	0	0.02
1330	5/20/13	mg/cm ²	TREAD	WOOD	A	INTACT	WHITE	2720 m.r	SECOND	STAIR	Negative	1	1	0	0.02
1331	5/20/13	mg/cm ²	STRINGER	WOOD	A	INTACT	WHITE	2720 m.r	SECOND	STAIR	Negative	5.2	1	0.07	0.29
1332	5/20/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2720 m.r	SECOND	BEDROOM 1	Negative	1.04	1	0	0.02
1333	5/20/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2720 m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.02
1334	5/20/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2720 m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.02
1335	5/20/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2720 m.r	SECOND	BEDROOM 1	Negative	4.91	1	0.02	0.09
1336	5/20/13	mg/cm ²	CEILING	DRYWALL	A	INTACT	WHITE	2720 m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.02
1337	5/20/13	mg/cm ²	BASEBOARD	WOOD	A	INTACT	WHITE	2720 m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.02
1338	5/20/13	mg/cm ²	WINDOW t	WOOD	A	INTACT	WHITE	2720 m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.02
1339	5/20/13	mg/cm ²	WINDOW s	WOOD	A	INTACT	WHITE	2720 m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.02
1340	5/20/13	mg/cm ²	DOOR	WOOD	C	INTACT	WHITE	2720 m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.03
1341	5/20/13	mg/cm ²	DOOR j	WOOD	C	INTACT	WHITE	2720 m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.02
1342	5/20/13	mg/cm ²	WALL	DRYWALL	A	INTACT	GREEN	2720 m.r	SECOND	BATHROOM	Negative	6.57	1	0.09	0.19
1343	5/20/13	mg/cm ²	WALL	DRYWALL	B	INTACT	GREEN	2720 m.r	SECOND	BATHROOM	Negative	2.53	1	0.02	0.06
1344	5/20/13	mg/cm ²	WALL	DRYWALL	C	INTACT	GREEN	2720 m.r	SECOND	BATHROOM	Negative	5.45	1	0.04	0.13
1345	5/20/13	mg/cm ²	WALL	DRYWALL	D	INTACT	GREEN	2720 m.r	SECOND	BATHROOM	Negative	1.64	1	0.01	0.04
1346	5/20/13	mg/cm ²	CEILING	DRYWALL	D	INTACT	GREEN	2720 m.r	SECOND	BATHROOM	Negative	1	1	0	0.02

1347	5/20/13	mg/cm ²	TRIM	WOOD	A	INTACT	WHITE	2720	m.r	SECOND	BATHROOM	Negative	1	1	0	0.03
1348	5/20/13	mg/cm ²	DOOR	WOOD	B	INTACT	WHITE	2720	m.r	SECOND	BATHROOM	Negative	1	1	0	0.03
1349	5/20/13	mg/cm ²	DOORT	WOOD	B	INTACT	WHITE	2720	m.r	SECOND	BATHROOM	Negative	3.42	1	0.02	0.09
1350	5/20/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2720	m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.02
1351	5/20/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2720	m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.02
1352	5/20/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2720	m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.02
1353	5/20/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2720	m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.02
1354	5/20/13	mg/cm ²	CEILING	DRYWALL	D	INTACT	WHITE	2720	m.r	SECOND	BEDROOM 2	Negative	3.15	1	0.02	0.07
1355	5/20/13	mg/cm ²	WINDOW t	WOOD	A	INTACT	WHITE	2720	m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.02
1356	5/20/13	mg/cm ²	WINDOW s	WOOD	A	INTACT	WHITE	2720	m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.02
1357	5/20/13	mg/cm ²	DOOR	WOOD	B	INTACT	BEIGE	2720	m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.02
1358	5/20/13	mg/cm ²	DOORT	WOOD	B	INTACT	BEIGE	2720	m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.02
1359	5/20/13	mg/cm ²	WALL	DRYWALL	A	INTACT	BEIGE	2720	m.r	SECOND	BEDROOM 3	Negative	1	1	0	0.02
1360	5/20/13	mg/cm ²	WALL	DRYWALL	B	INTACT	BEIGE	2720	m.r	SECOND	BEDROOM 3	Negative	1	1	0	0.02
1361	5/20/13	mg/cm ²	WALL	DRYWALL	C	INTACT	BEIGE	2720	m.r	SECOND	BEDROOM 3	Negative	1	1	0	0.02
1362	5/20/13	mg/cm ²	WALL	DRYWALL	D	INTACT	BEIGE	2720	m.r	SECOND	BEDROOM 3	Negative	1	1	0	0.02
1363	5/20/13	mg/cm ²	CEILING	DRYWALL	D	INTACT	BEIGE	2720	m.r	SECOND	BEDROOM 3	Negative	1	1	0	0.02
1364	5/20/13	mg/cm ²	BASEBOARD	WOOD	A	INTACT	BEIGE	2720	m.r	SECOND	BEDROOM 3	Negative	1.75	1	0	0.02
1365	5/20/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2718	m.r	SECOND	KITCHEN	Negative	7.7	1	0.16	0.3
1366	5/20/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2718	m.r	SECOND	KITCHEN	Negative	7.57	1	0.13	0.15
1367	5/20/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2718	m.r	SECOND	KITCHEN	Negative	10	1	0.26	0.65
1368	5/20/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2718	m.r	SECOND	KITCHEN	Negative	2.31	1	0.05	0.08
1369	5/20/13	mg/cm ²	CEILING	DRYWALL	D	INTACT	WHITE	2718	m.r	SECOND	KITCHEN	Negative	2.13	1	0.01	0.05
1370	5/20/13	mg/cm ²	BASEBOARD	WOOD	A	INTACT	WHITE	2718	m.r	SECOND	KITCHEN	Negative	2.12	1	0.01	0.02
1371	5/20/13	mg/cm ²	DOOR	WOOD	A	INTACT	WHITE	2718	m.r	SECOND	KITCHEN	Negative	1	1	0	0.02
1372	5/20/13	mg/cm ²	DOORT	WOOD	A	INTACT	WHITE	2718	m.r	SECOND	KITCHEN	Negative	1	1	0	0.02
1373	5/20/13	mg/cm ²	WINDOW t	WOOD	A	INTACT	WHITE	2718	m.r	SECOND	KITCHEN	Negative	1	1	0	0.02
1374	5/20/13	mg/cm ²	WINDOW s	WOOD	A	INTACT	WHITE	2718	m.r	SECOND	KITCHEN	Negative	1	1	0	0.02
1375	5/20/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2718	m.r	FIRST	LIVING ROOM	Negative	1.45	1	0	0.02
1376	5/20/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2718	m.r	FIRST	LIVING ROOM	Negative	1	1	0	0.02
1377	5/20/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2718	m.r	FIRST	LIVING ROOM	Negative	1.15	1	0	0.02
1378	5/20/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2718	m.r	FIRST	LIVING ROOM	Negative	1.41	1	0	0.02
1379	5/20/13	mg/cm ²	CEILING	DRYWALL	D	INTACT	WHITE	2718	m.r	FIRST	LIVING ROOM	Negative	1	1	0	0.02
1380	5/20/13	mg/cm ²	BASEBOARD	DRYWALL	D	INTACT	WHITE	2718	m.r	FIRST	LIVING ROOM	Negative	1	1	0	0.02
1381	5/20/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2718	m.r	FIRST	BATHROOM	Negative	3.4	1	0.02	0.08
1382	5/20/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2718	m.r	FIRST	BATHROOM	Negative	3.2	1	0.02	0.07
1383	5/20/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2718	m.r	FIRST	BATHROOM	Negative	4.19	1	0.02	0.09
1384	5/20/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2718	m.r	FIRST	BATHROOM	Negative	1	1	0	0.02
1385	5/20/13	mg/cm ²	CEILING	DRYWALL	A	INTACT	WHITE	2718	m.r	FIRST	BATHROOM	Negative	2.79	1	0.01	0.06
1386	5/20/13	mg/cm ²	DOOR	WOOD	A	INTACT	WHITE	2718	m.r	FIRST	BATHROOM	Negative	1	1	0	0.02
1387	5/20/13	mg/cm ²	DOORT	WOOD	A	INTACT	WHITE	2718	m.r	FIRST	BATHROOM	Negative	1	1	0	0.02
1388	5/20/13	mg/cm ²	DOOR j	WOOD	A	INTACT	WHITE	2718	m.r	FIRST	BATHROOM	Negative	2.37	1	0.02	0.07
1389	5/20/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2718	m.r	FIRST	BEDROOM 1	Negative	1	1	0	0.02
1390	5/20/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2718	m.r	FIRST	BEDROOM 1	Negative	1	1	0	0.02
1391	5/20/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2718	m.r	FIRST	BEDROOM 1	Negative	2.73	1	0.01	0.05
1392	5/20/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2718	m.r	FIRST	BEDROOM 1	Negative	1	1	0	0.02

1393	5/20/13	mg/cm ²	CEILING	DRYWALL	D	INTACT	WHITE	2718 m.r	FIRST	BEDROOM 1	Negative	1.55	1	0	0.02
1394	5/20/13	mg/cm ²	BASEBOARD	WOOD	A	INTACT	WHITE	2718 m.r	FIRST	BEDROOM 1	Negative	1.18	1	0.01	0.03
1395	5/20/13	mg/cm ²	WINDOW t	WOOD	A	INTACT	WHITE	2718 m.r	FIRST	BEDROOM 1	Negative	1	1	0	0.02
1396	5/20/13	mg/cm ²	WINDOW s	WOOD	A	INTACT	WHITE	2718 m.r	FIRST	BEDROOM 1	Negative	1	1	0	0.02
1397	5/20/13	mg/cm ²	DOOR	WOOD	C	INTACT	WHITE	2718 m.r	FIRST	BEDROOM 1	Negative	1	1	0	0.02
1398	5/20/13	mg/cm ²	DOOR t	WOOD	C	INTACT	WHITE	2718 m.r	FIRST	BEDROOM 1	Negative	1	1	0	0.02
1399	5/20/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2718 m.r	FIRST	BEDROOM 2	Negative	1	1	0	0.02
1400	5/20/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2718 m.r	FIRST	BEDROOM 2	Negative	1	1	0	0.02
1401	5/20/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2718 m.r	FIRST	BEDROOM 2	Negative	1	1	0	0.02
1402	5/20/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2718 m.r	FIRST	BEDROOM 2	Negative	1	1	0	0.02
1403	5/20/13	mg/cm ²	CEILING	DRYWALL	D	INTACT	WHITE	2718 m.r	FIRST	BEDROOM 2	Negative	2.66	1	0.01	0.04
1404	5/20/13	mg/cm ²	BASEBOARD	WOOD	A	INTACT	WHITE	2718 m.r	FIRST	BEDROOM 2	Negative	1	1	0	0.02
1405	5/20/13	mg/cm ²	WINDOW t	WOOD	A	INTACT	WHITE	2718 m.r	FIRST	BEDROOM 2	Negative	1	1	0	0.02
1406	5/20/13	mg/cm ²	WINDOW s	WOOD	A	INTACT	WHITE	2718 m.r	FIRST	BEDROOM 2	Negative	1	1	0	0.02
1407	5/20/13	mg/cm ²	DOOR t	WOOD	A	INTACT	WHITE	2718 m.r	FIRST	BEDROOM 2	Negative	1	1	0	0.02
1408	5/20/13	mg/cm ²	DOOR j	WOOD	A	INTACT	WHITE	2718 m.r	FIRST	BEDROOM 2	Negative	5.36	1	0.06	0.2
1409	5/20/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2718 m.r	FIRST	BATHROOM	Negative	1	1	0	0.02
1410	5/20/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2718 m.r	FIRST	BATHROOM	Negative	1	1	0	0.02
1411	5/20/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2718 m.r	FIRST	BATHROOM	Negative	1	1	0	0.02
1412	5/20/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2718 m.r	FIRST	BATHROOM	Negative	1	1	0	0.02
1413	5/20/13	mg/cm ²	CEILING	DRYWALL	D	INTACT	WHITE	2718 m.r	FIRST	BATHROOM	Negative	3.36	1	0.01	0.05
1414	5/20/13	mg/cm ²	TRIM	WOOD	A	INTACT	WHITE	2718 m.r	FIRST	BATHROOM	Negative	1	1	0	0.02
1415	5/20/13	mg/cm ²	DOOR	WOOD	B	INTACT	WHITE	2718 m.r	FIRST	BATHROOM	Negative	1	1	0	0.03
1416	5/20/13	mg/cm ²	DOOR t	WOOD	B	INTACT	WHITE	2718 m.r	FIRST	BATHROOM	Negative	1.33	1	0.01	0.03
1417	5/20/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2718 m.r	FIRST	BEDROOM 3	Negative	1	1	0	0.02
1418	5/20/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2718 m.r	FIRST	BEDROOM 3	Negative	1.01	1	0.01	0.03
1419	5/20/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2718 m.r	FIRST	BEDROOM 3	Negative	1	1	0	0.02
1420	5/20/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2718 m.r	FIRST	BEDROOM 3	Negative	5.37	1	0.03	0.14
1421	5/20/13	mg/cm ²	BASEBOARD	WOOD	A	INTACT	WHITE	2718 m.r	FIRST	BEDROOM 3	Negative	2.14	1	0.01	0.05
1422	5/20/13	mg/cm ²	DOOR	WOOD	C	INTACT	WHITE	2718 m.r	FIRST	BEDROOM 3	Negative	2.4	1	0.01	0.1
1423	5/20/13	mg/cm ²	DOOR t	WOOD	C	INTACT	WHITE	2718 m.r	FIRST	BEDROOM 3	Negative	1	1	0	0.02
1424	5/20/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2718 m.r	FIRST	BEDROOM 4	Negative	1	1	0	0.02
1425	5/20/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2718 m.r	FIRST	BEDROOM 4	Negative	1	1	0	0.02
1426	5/20/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2718 m.r	FIRST	BEDROOM 4	Negative	1	1	0	0.02
1427	5/20/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2718 m.r	FIRST	BEDROOM 4	Negative	2.79	1	0.02	0.08
1428	5/20/13	mg/cm ²	CEILING	DRYWALL	D	INTACT	WHITE	2718 m.r	FIRST	BEDROOM 4	Negative	1	1	0	0.02
1429	5/20/13	mg/cm ²	BASEBOARD	DRYWALL	A	INTACT	WHITE	2718 m.r	FIRST	BEDROOM 4	Negative	1.33	1	0.01	0.02
1430	5/20/13	mg/cm ²	WINDOW t	DRYWALL	A	INTACT	WHITE	2718 m.r	FIRST	BEDROOM 4	Negative	1	1	0	0.02
1431	5/20/13	mg/cm ²	WINDOW s	DRYWALL	A	INTACT	WHITE	2718 m.r	FIRST	BEDROOM 4	Negative	1	1	0	0.02
1432	5/20/13	mg/cm ²	DOOR	WOOD	A	INTACT	WHITE	2718 m.r	FIRST	BEDROOM 4	Negative	1	1	0	0.03
1433	5/20/13	mg/cm ²	DOOR j	WOOD	A	INTACT	WHITE	2718 m.r	FIRST	BEDROOM 4	Negative	1	1	0.01	0.03
1434	5/20/13	mg/cm ²	cal								Negative	1.03	1	0.9	0.1
1435	5/20/13	mg/cm ²	cal								Negative	1	1	0.9	0.1
1436	5/20/13	mg/cm ²	cal								Positive	1.1	1	1	0.1
1437	5/21/13	cps												7.17	0
1438	5/21/13	mg/cm ²	cal								Negative	1.06	1	0.9	0.1

1439	5/21/13	mg/cm ²	cal	DRYWALL	A	INTACT	WHITE	2726	m.r	FIRST	KITCHEN	Negative	1.02	1	0.9	0.1
1440	5/21/13	mg/cm ²	cal	DRYWALL	B	INTACT	WHITE	2726	m.r	FIRST	KITCHEN	Negative	1.08	1	0.9	0.1
1441	5/21/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2726	m.r	FIRST	KITCHEN	Negative	1	1	0	0.02
1442	5/21/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2726	m.r	FIRST	KITCHEN	Negative	1	1	0	0.02
1443	5/21/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2726	m.r	FIRST	KITCHEN	Negative	1.2	1	0	0.02
1444	5/21/13	mg/cm ²	CEILING	WOOD	A	INTACT	WHITE	2726	m.r	FIRST	KITCHEN	Negative	1.49	1	0.01	0.03
1445	5/21/13	mg/cm ²	BASEBOARD	WOOD	A	INTACT	WHITE	2726	m.r	FIRST	KITCHEN	Negative	1	1	0	0.02
1446	5/21/13	mg/cm ²	WINDOW t	WOOD	A	INTACT	WHITE	2726	m.r	FIRST	KITCHEN	Negative	1	1	0	0.02
1447	5/21/13	mg/cm ²	WINDOW s	WOOD	A	INTACT	WHITE	2726	m.r	FIRST	KITCHEN	Negative	1	1	0	0.03
1448	5/21/13	mg/cm ²	DOOR	WOOD	A	INTACT	WHITE	2726	m.r	FIRST	KITCHEN	Negative	1.26	1	0.16	0.14
1449	5/21/13	mg/cm ²	DOOR j	WOOD	A	INTACT	WHITE	2726	m.r	FIRST	KITCHEN	Negative	1	1	0	0.02
1450	5/21/13	mg/cm ²	WALL	DRYWALL	A	INTACT	YELLOW	2726	m.r	FIRST	LIVING ROOM	Negative	1	1	0.01	0.02
1451	5/21/13	mg/cm ²	WALL	DRYWALL	B	INTACT	YELLOW	2726	m.r	FIRST	LIVING ROOM	Negative	1	1	0.01	0.02
1452	5/21/13	mg/cm ²	WALL	DRYWALL	C	INTACT	YELLOW	2726	m.r	FIRST	LIVING ROOM	Negative	1	1	0.01	0.02
1453	5/21/13	mg/cm ²	WALL	DRYWALL	D	INTACT	YELLOW	2726	m.r	FIRST	LIVING ROOM	Negative	1	1	0.01	0.02
1454	5/21/13	mg/cm ²	CEILING	DRYWALL	D	INTACT	YELLOW	2726	m.r	FIRST	LIVING ROOM	Negative	1	1	0.01	0.02
1455	5/21/13	mg/cm ²	WINDOW t	DRYWALL	D	INTACT	YELLOW	2726	m.r	FIRST	LIVING ROOM	Negative	1	1	0	0.02
1456	5/21/13	mg/cm ²	WINDOW s	DRYWALL	D	INTACT	YELLOW	2726	m.r	FIRST	LIVING ROOM	Negative	1	1	0	0.02
1457	5/21/13	mg/cm ²	WALL	CONCRETE	A	INTACT	WHITE	2726	m.r	BASEMENT	room	Negative	1	1	0	0.02
1458	5/21/13	mg/cm ²	WALL	CONCRETE	B	INTACT	WHITE	2726	m.r	BASEMENT	room	Negative	1	1	0	0.02
1459	5/21/13	mg/cm ²	WALL	CONCRETE	C	INTACT	WHITE	2726	m.r	BASEMENT	room	Negative	1	1	0	0.02
1460	5/21/13	mg/cm ²	WALL	CONCRETE	D	INTACT	WHITE	2726	m.r	BASEMENT	room	Negative	1	1	0	0.02
1461	5/21/13	mg/cm ²	FLOOR	CONCRETE	A	INTACT	WHITE	2726	m.r	BASEMENT	room	Negative	1	1	0	0.02
1462	5/21/13	mg/cm ²	TREAD	WOOD	A	INTACT	BLUE	2726	m.r	BASEMENT	STAIR	Negative	1.31	1	0.05	0.12
1463	5/21/13	mg/cm ²	RISER	WOOD	A	INTACT	BLUE	2726	m.r	BASEMENT	STAIR	Negative	1	1	0.03	0.07
1464	5/21/13	mg/cm ²	stringer	WOOD	A	INTACT	BLUE	2726	m.r	BASEMENT	STAIR	Negative	2.19	1	0.06	0.17
1465	5/21/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2726	m.r	BASEMENT	STAIR	Negative	1	1	0	0.02
1466	5/21/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2726	m.r	BASEMENT	STAIR	Negative	1	1	0	0.02
1467	5/21/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2726	m.r	BASEMENT	STAIR	Negative	1	1	0	0.02
1468	5/21/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2726	m.r	BASEMENT	STAIR	Negative	1	1	0	0.02
1469	5/21/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2726	m.r	BASEMENT	STAIR	Negative	1	1	0	0.02
1470	5/21/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2726	m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.02
1471	5/21/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2726	m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.02
1472	5/21/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2726	m.r	SECOND	BEDROOM 1	Negative	1.9	1	0.01	0.04
1473	5/21/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2726	m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.02
1474	5/21/13	mg/cm ²	CEILING	DRYWALL	D	INTACT	WHITE	2726	m.r	SECOND	BEDROOM 1	Negative	1.59	1	0	0.02
1475	5/21/13	mg/cm ²	BASEBOARD	PLASTER	A	INTACT	WHITE	2726	m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.02
1476	5/21/13	mg/cm ²	WINDOW t	WOOD	A	INTACT	WHITE	2726	m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.02
1477	5/21/13	mg/cm ²	WINDOW s	WOOD	A	INTACT	WHITE	2726	m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.02
1478	5/21/13	mg/cm ²	DOOR	WOOD	C	INTACT	WHITE	2726	m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.02
1479	5/21/13	mg/cm ²	DOOR j	WOOD	C	INTACT	WHITE	2726	m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.03
1480	5/21/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2726	m.r	SECOND	BEDROOM 1	Negative	1	1	0.01	0.02
1481	5/21/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2726	m.r	SECOND	BEDROOM 2	Negative	5.35	1	0.19	0.23
1482	5/21/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2726	m.r	SECOND	BEDROOM 2	Negative	6.36	1	0.24	0.29
1483	5/21/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2726	m.r	SECOND	BEDROOM 2	Negative	4.08	1	0.08	0.14
1484	5/21/13	mg/cm ²	CEILING	DRYWALL	D	INTACT	WHITE	2726	m.r	SECOND	BEDROOM 2	Negative	4.92	1	0.21	0.3
													1	1	0	0.02

1485	5/21/13 mg/cm^2	BASEBOARD	DRYWALL	D	INTACT	WHITE	2726 m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.02
1486	5/21/13 mg/cm^2	WINDOW t	DRYWALL	D	INTACT	WHITE	2726 m.r	SECOND	BEDROOM 2	Negative	4.24	1	0.12	0.21
1487	5/21/13 mg/cm^2	WINDOW s	DRYWALL	D	INTACT	WHITE	2726 m.r	SECOND	BEDROOM 2	Negative	5.33	1	0.12	0.24
1488	5/21/13 mg/cm^2	DOOR	WOOD	D	INTACT	WHITE	2726 m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.02
1489	5/21/13 mg/cm^2	DOOR t	WOOD	D	INTACT	WHITE	2726 m.r	SECOND	BEDROOM 2	Negative	2.57	1	0.02	0.07
1490	5/21/13 mg/cm^2	WALL	DRYWALL	A	INTACT	YELLOW	2726 m.r	SECOND	BATHROOM	Negative	2.96	1	0.02	0.06
1491	5/21/13 mg/cm^2	WALL	DRYWALL	B	INTACT	YELLOW	2726 m.r	SECOND	BATHROOM	Negative	1.26	1	0	0.02
1492	5/21/13 mg/cm^2	WALL	DRYWALL	C	INTACT	YELLOW	2726 m.r	SECOND	BATHROOM	Negative	1	1	0	0.02
1493	5/21/13 mg/cm^2	WALL	DRYWALL	D	INTACT	YELLOW	2726 m.r	SECOND	BATHROOM	Negative	1	1	0	0.02
1494	5/21/13 mg/cm^2	CEILING	DRYWALL	D	INTACT	YELLOW	2726 m.r	SECOND	BATHROOM	Negative	1	1	0	0.02
1495	5/21/13 mg/cm^2	DOOR	WOOD	A	INTACT	WHITE	2726 m.r	SECOND	BATHROOM	Negative	1	1	0	0.02
1496	5/21/13 mg/cm^2	DOOR t	WOOD	A	INTACT	WHITE	2726 m.r	SECOND	BATHROOM	Negative	1	1	0	0.02
1497	5/21/13 mg/cm^2	WALL	DRYWALL	A	INTACT	WHITE	2726 m.r	SECOND	BEDROOM 3	Negative	7.81	1	0.08	0.26
1498	5/21/13 mg/cm^2	WALL	DRYWALL	B	INTACT	WHITE	2726 m.r	SECOND	BEDROOM 3	Negative	7.34	1	0.22	0.4
1499	5/21/13 mg/cm^2	WALL	DRYWALL	C	INTACT	WHITE	2726 m.r	SECOND	BEDROOM 3	Negative	5.36	1	0.18	0.25
1500	5/21/13 mg/cm^2	WALL	DRYWALL	D	INTACT	WHITE	2726 m.r	SECOND	BEDROOM 3	Negative	6.22	1	0.24	0.29
1501	5/21/13 mg/cm^2	CEILING	DRYWALL	D	INTACT	WHITE	2726 m.r	SECOND	BEDROOM 3	Negative	6.69	1	0.17	0.33
1502	5/21/13 mg/cm^2	BASEBOARD	WOOD	A	INTACT	WHITE	2726 m.r	SECOND	BEDROOM 3	Negative	10	1	0.6	0.4
1503	5/21/13 mg/cm^2	DOOR	WOOD	A	INTACT	WHITE	2726 m.r	SECOND	BEDROOM 3	Negative	1	1	0	0.02
1504	5/21/13 mg/cm^2	DOOR j	WOOD	A	INTACT	WHITE	2726 m.r	SECOND	BEDROOM 3	Negative	2.85	1	0.02	0.08
1505	5/21/13 mg/cm^2	WALL	DRYWALL	A	INTACT	WHITE	2728 m.r	FIRST	KITCHEN	Negative	2.6	1	0	0.03
1506	5/21/13 mg/cm^2	WALL	DRYWALL	B	INTACT	WHITE	2728 m.r	FIRST	KITCHEN	Negative	1	1	0	0.02
1507	5/21/13 mg/cm^2	WALL	DRYWALL	C	INTACT	WHITE	2728 m.r	FIRST	KITCHEN	Negative	1.2	1	0	0.02
1508	5/21/13 mg/cm^2	WALL	DRYWALL	D	INTACT	WHITE	2728 m.r	FIRST	KITCHEN	Negative	2.48	1	0.01	0.04
1509	5/21/13 mg/cm^2	CEILING	DRYWALL	A	INTACT	WHITE	2728 m.r	FIRST	KITCHEN	Negative	1	1	0	0.02
1510	5/21/13 mg/cm^2	BASEBOARD	WOOD	A	INTACT	WHITE	2728 m.r	FIRST	KITCHEN	Negative	3.55	1	0.01	0.03
1511	5/21/13 mg/cm^2	WINDOW t	WOOD	A	INTACT	WHITE	2728 m.r	FIRST	KITCHEN	Negative	1	1	0	0.02
1512	5/21/13 mg/cm^2	WINDOW s	WOOD	A	INTACT	WHITE	2728 m.r	FIRST	KITCHEN	Negative	1	1	0	0.02
1513	5/21/13 mg/cm^2	DOOR	WOOD	A	INTACT	WHITE	2728 m.r	FIRST	KITCHEN	Negative	2.13	1	0.17	0.2
1514	5/21/13 mg/cm^2	DOOR t	WOOD	A	INTACT	WHITE	2728 m.r	FIRST	KITCHEN	Negative	1	1	0	0.02
1515	5/21/13 mg/cm^2	WALL	DRYWALL	A	INTACT	WHITE	2728 m.r	FIRST	LIVING ROOM	Negative	1	1	0	0.02
1516	5/21/13 mg/cm^2	WALL	DRYWALL	B	INTACT	WHITE	2728 m.r	FIRST	LIVING ROOM	Negative	1	1	0	0.02
1517	5/21/13 mg/cm^2	WALL	DRYWALL	C	INTACT	WHITE	2728 m.r	FIRST	LIVING ROOM	Negative	1	1	0	0.02
1518	5/21/13 mg/cm^2	WALL	DRYWALL	D	INTACT	WHITE	2728 m.r	FIRST	LIVING ROOM	Negative	1	1	0	0.02
1519	5/21/13 mg/cm^2	CEILING	DRYWALL	D	INTACT	WHITE	2728 m.r	FIRST	LIVING ROOM	Negative	1	1	0	0.02
1520	5/21/13 mg/cm^2	BASEBOARD	DRYWALL	D	INTACT	WHITE	2728 m.r	FIRST	LIVING ROOM	Negative	1	1	0	0.02
1521	5/21/13 mg/cm^2	DOOR	WOOD	C	INTACT	WHITE	2728 m.r	FIRST	LIVING ROOM	Negative	1.46	1	0.1	0.12
1522	5/21/13 mg/cm^2	DOOR t	WOOD	C	INTACT	WHITE	2728 m.r	FIRST	LIVING ROOM	Negative	1	1	0	0.02
1523	5/21/13 mg/cm^2	WALL	CONCRETE	A	INTACT	WHITE	2728 m.r	BASEMENT	room	Negative	1	1	0	0.02
1524	5/21/13 mg/cm^2	WALL	CONCRETE	B	INTACT	WHITE	2728 m.r	BASEMENT	room	Negative	1	1	0	0.02
1525	5/21/13 mg/cm^2	WALL	CONCRETE	C	INTACT	WHITE	2728 m.r	BASEMENT	room	Negative	1	1	0	0.02
1526	5/21/13 mg/cm^2	WALL	CONCRETE	D	INTACT	WHITE	2728 m.r	BASEMENT	room	Negative	1	1	0	0.02
1527	5/21/13 mg/cm^2	FLOOR	CONCRETE	A	INTACT	BLUE	2728 m.r	BASEMENT	room	Negative	1.99	1	0.01	0.02
1528	5/21/13 mg/cm^2	TREAD	WOOD	A	INTACT	BLUE	2728 m.r	BASEMENT	room	Negative	3.33	1	0.09	0.27
1529	5/21/13 mg/cm^2	RISER	WOOD	A	INTACT	BLUE	2728 m.r	BASEMENT	room	Negative	1.95	1	0.06	0.16
1530	5/21/13 mg/cm^2	stringer	WOOD	A	INTACT	BLUE	2728 m.r	BASEMENT	room	Negative	1.33	1	0.05	0.12

1531	5/21/13	mg/cm ²	WALL	WOOD	A	INTACT	WHITE	2728 m.r	BASEMENT	STAIR	Negative	1	1	0	0.02
1532	5/21/13	mg/cm ²	WALL	WOOD	B	INTACT	WHITE	2728 m.r	BASEMENT	STAIR	Negative	1	1	0	0.02
1533	5/21/13	mg/cm ²	WALL	WOOD	C	INTACT	WHITE	2728 m.r	BASEMENT	STAIR	Negative	1	1	0	0.02
1534	5/21/13	mg/cm ²	WALL	WOOD	D	INTACT	WHITE	2728 m.r	BASEMENT	STAIR	Negative	1	1	0	0.02
1535	5/21/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2728 m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.02
1536	5/21/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2728 m.r	SECOND	BEDROOM 1	Negative	4.35	1	0.03	0.11
1537	5/21/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2728 m.r	SECOND	BEDROOM 1	Negative	7.47	1	0.05	0.19
1538	5/21/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2728 m.r	SECOND	BEDROOM 1	Negative	1.01	1	0	0.02
1539	5/21/13	mg/cm ²	BASEBOARD	WOOD	A	INTACT	WHITE	2728 m.r	SECOND	BEDROOM 1	Negative	1.06	1	0	0.02
1540	5/21/13	mg/cm ²	WINDOW t	WOOD	A	INTACT	WHITE	2728 m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.02
1541	5/21/13	mg/cm ²	WINDOW s	WOOD	A	INTACT	WHITE	2728 m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.02
1542	5/21/13	mg/cm ²	DOOR	WOOD	C	INTACT	WHITE	2728 m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.03
1543	5/21/13	mg/cm ²	DOOR j	WOOD	C	INTACT	WHITE	2728 m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.02
1544	5/21/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2728 m.r	SECOND	BATHROOM	Negative	2.33	1	0.01	0.03
1545	5/21/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2728 m.r	SECOND	BATHROOM	Negative	1	1	0	0.02
1546	5/21/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2728 m.r	SECOND	BATHROOM	Negative	1	1	0	0.02
1547	5/21/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2728 m.r	SECOND	BATHROOM	Negative	1	1	0	0.02
1548	5/21/13	mg/cm ²	CEILING	DRYWALL	D	INTACT	WHITE	2728 m.r	SECOND	BATHROOM	Negative	3.4	1	0.02	0.07
1549	5/21/13	mg/cm ²	DOOR	WOOD	D	INTACT	WHITE	2728 m.r	SECOND	BATHROOM	Negative	1	1	0	0.02
1550	5/21/13	mg/cm ²	DOOR t	WOOD	A	INTACT	WHITE	2728 m.r	SECOND	BATHROOM	Negative	1	1	0	0.02
1551	5/21/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2728 m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.02
1552	5/21/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2728 m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.02
1553	5/21/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2728 m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.02
1554	5/21/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2728 m.r	SECOND	BEDROOM 2	Negative	3.01	1	0.01	0.05
1555	5/21/13	mg/cm ²	CEILING	DRYWALL	D	INTACT	WHITE	2728 m.r	SECOND	BEDROOM 2	Negative	1.14	1	0	0.03
1556	5/21/13	mg/cm ²	BASEBOARD	WOOD	A	INTACT	WHITE	2728 m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.02
1557	5/21/13	mg/cm ²	WINDOW t	WOOD	A	INTACT	WHITE	2728 m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.02
1558	5/21/13	mg/cm ²	WINDOW s	WOOD	A	INTACT	WHITE	2728 m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.02
1559	5/21/13	mg/cm ²	DOOR	WOOD	A	INTACT	WHITE	2728 m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.02
1560	5/21/13	mg/cm ²	DOOR t	WOOD	A	INTACT	WHITE	2728 m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.02
1561	5/21/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2730 m.r	SECOND	BEDROOM 2	Negative	3.98	1	0.04	0.13
1562	5/21/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2730 m.r	SECOND	KITCHEN	Negative	1	1	0	0.02
1563	5/21/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2730 m.r	SECOND	KITCHEN	Negative	1	1	0	0.02
1564	5/21/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2730 m.r	SECOND	KITCHEN	Negative	1	1	0	0.02
1565	5/21/13	mg/cm ²	CEILING	DRYWALL	A	INTACT	WHITE	2730 m.r	SECOND	KITCHEN	Negative	5.11	1	0.02	0.08
1566	5/21/13	mg/cm ²	DOOR	WOOD	A	INTACT	WHITE	2730 m.r	SECOND	KITCHEN	Negative	1	1	0	0.02
1567	5/21/13	mg/cm ²	DOOR t	WOOD	A	INTACT	WHITE	2730 m.r	SECOND	KITCHEN	Negative	1	1	0.06	0.08
1568	5/21/13	mg/cm ²	WINDOW t	WOOD	A	INTACT	WHITE	2730 m.r	SECOND	KITCHEN	Negative	1	1	0	0.02
1569	5/21/13	mg/cm ²	WINDOW s	WOOD	A	INTACT	WHITE	2730 m.r	SECOND	KITCHEN	Negative	2.12	1	0.01	0.06
1570	5/21/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2730 m.r	FIRST	KITCHEN	Negative	1	1	0	0.02
1571	5/21/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2730 m.r	FIRST	BATHROOM	Negative	1.05	1	0	0.02
1572	5/21/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2730 m.r	FIRST	BATHROOM	Negative	3.84	1	0.02	0.09
1573	5/21/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2730 m.r	FIRST	BATHROOM	Negative	1.6	1	0.01	0.03
1574	5/21/13	mg/cm ²	CEILING	DRYWALL	D	INTACT	WHITE	2730 m.r	FIRST	BATHROOM	Negative	2.33	1	0.01	0.04
1575	5/21/13	mg/cm ²	TRIM	WOOD	A	INTACT	WHITE	2730 m.r	FIRST	BATHROOM	Negative	1.8	1	0.01	0.04
1576	5/21/13	mg/cm ²	DOOR	WOOD	A	INTACT	WHITE	2730 m.r	FIRST	BATHROOM	Negative	1	1	0	0.02

1577	5/21/13	mg/cm ²	DOOR j	WOOD	A	INTACT	WHITE	2730 m.r	FIRST	BATHROOM	Negative	1	1	0	0.03
1578	5/21/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2730 m.r	FIRST	BATHROOM	Negative	1	1	0	0.02
1579	5/21/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2730 m.r	FIRST	BATHROOM	Negative	1.79	1	0	0.02
1580	5/21/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2730 m.r	FIRST	BATHROOM	Negative	1	1	0	0.02
1581	5/21/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2730 m.r	FIRST	BATHROOM	Negative	1.83	1	0.01	0.03
1582	5/21/13	mg/cm ²	CEILING	DRYWALL	D	INTACT	WHITE	2730 m.r	FIRST	BATHROOM	Negative	1	1	0	0.02
1583	5/21/13	mg/cm ²	DOOR	WOOD	C	INTACT	WHITE	2730 m.r	FIRST	BATHROOM	Negative	1.19	1	0.08	0.14
1584	5/21/13	mg/cm ²	DOOR j	WOOD	C	INTACT	WHITE	2730 m.r	FIRST	BATHROOM	Negative	1.54	1	0.01	0.05
1585	5/21/13	mg/cm ²	WINDOW t	WOOD	C	INTACT	WHITE	2730 m.r	FIRST	BATHROOM	Negative	1	1	0	0.03
1586	5/21/13	mg/cm ²	WINDOW s	WOOD	C	INTACT	WHITE	2730 m.r	FIRST	BATHROOM	Negative	1	1	0	0.02
1587	5/21/13	mg/cm ²	WALL	CONCRETE	A	INTACT	WHITE	2730 m.r	BASEMENT	room	Negative	3.6	1	0.01	0.03
1588	5/21/13	mg/cm ²	WALL	CONCRETE	B	INTACT	WHITE	2730 m.r	BASEMENT	room	Negative	1	1	0	0.02
1589	5/21/13	mg/cm ²	WALL	CONCRETE	C	INTACT	WHITE	2730 m.r	BASEMENT	room	Negative	1	1	0	0.02
1590	5/21/13	mg/cm ²	WALL	CONCRETE	D	INTACT	WHITE	2730 m.r	BASEMENT	room	Negative	1	1	0	0.02
1591	5/21/13	mg/cm ²	FLOOR	CONCRETE	A	INTACT	BLUE	2730 m.r	BASEMENT	room	Negative	1	1	0	0.02
1592	5/21/13	mg/cm ²	TREAD	WOOD	A	INTACT	BLUE	2730 m.r	BASEMENT	STAIR	Negative	1.03	1	0.02	0.06
1593	5/21/13	mg/cm ²	RISER	WOOD	A	INTACT	BLUE	2730 m.r	BASEMENT	STAIR	Negative	1.45	1	0.06	0.14
1594	5/21/13	mg/cm ²	stringer	WOOD	A	INTACT	BLUE	2730 m.r	BASEMENT	STAIR	Negative	2.11	1	0.14	0.25
1595	5/21/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2730 m.r	BASEMENT	STAIR	Negative	1	1	0	0.02
1596	5/21/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2730 m.r	BASEMENT	STAIR	Negative	1	1	0	0.02
1597	5/21/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2730 m.r	BASEMENT	STAIR	Negative	3.18	1	0.01	0.06
1598	5/21/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2730 m.r	BASEMENT	STAIR	Negative	1	1	0	0.02
1599	5/21/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2730 m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.02
1600	5/21/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2730 m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.02
1601	5/21/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2730 m.r	SECOND	BEDROOM 1	Negative	1.69	1	0.01	0.03
1602	5/21/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2730 m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.02
1603	5/21/13	mg/cm ²	BASEBOARD	WOOD	A	INTACT	WHITE	2730 m.r	SECOND	BEDROOM 1	Negative	1.04	1	0	0.02
1604	5/21/13	mg/cm ²	CEILING	DRYWALL	A	INTACT	WHITE	2730 m.r	SECOND	BEDROOM 1	Negative	1.16	1	0	0.02
1605	5/21/13	mg/cm ²	WINDOW t	WOOD	A	INTACT	WHITE	2730 m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.02
1606	5/21/13	mg/cm ²	WINDOW s	WOOD	A	INTACT	WHITE	2730 m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.02
1607	5/21/13	mg/cm ²	DOOR	WOOD	A	INTACT	WHITE	2730 m.r	SECOND	BEDROOM 1	Negative	2.55	1	0.01	0.05
1608	5/21/13	mg/cm ²	DOOR t	WOOD	A	INTACT	WHITE	2730 m.r	SECOND	BEDROOM 1	Negative	1.84	1	0	0.02
1609	5/21/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2730 m.r	SECOND	BEDROOM 2	Negative	2.72	1	0.01	0.04
1610	5/21/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2730 m.r	SECOND	BEDROOM 2	Negative	3.2	1	0.01	0.07
1611	5/21/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2730 m.r	SECOND	BEDROOM 2	Negative	1.34	1	0	0.02
1612	5/21/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2730 m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.02
1613	5/21/13	mg/cm ²	CEILING	DRYWALL	A	INTACT	WHITE	2730 m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.02
1614	5/21/13	mg/cm ²	BASEBOARD	WOOD	A	INTACT	WHITE	2730 m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.02
1615	5/21/13	mg/cm ²	WINDOW t	WOOD	A	INTACT	WHITE	2730 m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.02
1616	5/21/13	mg/cm ²	WINDOW s	WOOD	A	INTACT	WHITE	2730 m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.02
1617	5/21/13	mg/cm ²	DOOR t	WOOD	A	INTACT	WHITE	2730 m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.02
1618	5/21/13	mg/cm ²	DOOR	WOOD	A	INTACT	WHITE	2730 m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.02
1619	5/21/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2730 m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.02
1620	5/21/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2730 m.r	SECOND	BATHROOM	Negative	2.33	1	0	0.02
1621	5/21/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2730 m.r	SECOND	BATHROOM	Negative	2.94	1	0.02	0.03
1622	5/21/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2730 m.r	SECOND	BATHROOM	Negative	7.77	1	0.06	0.19

1623	5/21/13	mg/cm ²	TRIM	WOOD	D	INTACT	WHITE	2730 m.r	SECOND	BATHROOM	Negative	1	1	0	0.02
1624	5/21/13	mg/cm ²	DOOR	WOOD	A	INTACT	WHITE	2730 m.r	SECOND	BATHROOM	Negative	1	1	0	0.02
1625	5/21/13	mg/cm ²	DOOR t	WOOD	A	INTACT	WHITE	2730 m.r	SECOND	BATHROOM	Negative	1	1	0	0.02
1626	5/21/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2730 m.r	SECOND	BATHROOM	Negative	1.71	1	0.01	0.04
1627	5/21/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2730 m.r	SECOND	BATHROOM	Negative	1	1	0	0.02
1628	5/21/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2730 m.r	SECOND	BATHROOM	Negative	2.19	1	0.01	0.04
1629	5/21/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2730 m.r	SECOND	BATHROOM	Negative	1.67	1	0.01	0.03
1630	5/21/13	mg/cm ²	BASEBOARD	WOOD	A	INTACT	WHITE	2730 m.r	SECOND	BATHROOM	Negative	1	1	0	0.02
1631	5/21/13	mg/cm ²	WINDOW t	WOOD	A	INTACT	WHITE	2730 m.r	SECOND	BATHROOM	Negative	1	1	0	0.02
1632	5/21/13	mg/cm ²	WINDOW s	WOOD	A	INTACT	WHITE	2730 m.r	SECOND	BATHROOM	Negative	1	1	0	0.02
1633	5/21/13	mg/cm ²	DOOR	WOOD	C	INTACT	WHITE	2730 m.r	SECOND	BATHROOM	Negative	1	1	0	0.02
1634	5/21/13	mg/cm ²	DOOR t	WOOD	C	INTACT	WHITE	2730 m.r	SECOND	BATHROOM	Negative	1	1	0	0.02
1635	5/21/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2730 m.r	SECOND	BATHROOM	Negative	1	1	0	0.02
1636	5/21/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2730 m.r	SECOND	BATHROOM	Negative	1	1	0	0.02
1637	5/21/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2730 m.r	SECOND	BATHROOM	Negative	1.21	1	0.01	0.03
1638	5/21/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2730 m.r	SECOND	BATHROOM	Negative	1	1	0	0.02
1639	5/21/13	mg/cm ²	CEILING	DRYWALL	D	INTACT	WHITE	2730 m.r	SECOND	BATHROOM	Negative	1	1	0	0.02
1640	5/21/13	mg/cm ²	BASEBOARD	DRYWALL	A	INTACT	WHITE	2730 m.r	SECOND	BATHROOM	Negative	7.93	1	0.05	0.15
1641	5/21/13	mg/cm ²	WINDOW t	WOOD	A	INTACT	WHITE	2730 m.r	SECOND	BATHROOM	Negative	1	1	0	0.02
1642	5/21/13	mg/cm ²	WINDOW s	WOOD	A	INTACT	WHITE	2730 m.r	SECOND	BATHROOM	Negative	1	1	0	0.02
1643	5/21/13	mg/cm ²	DOOR	WOOD	C	INTACT	WHITE	2730 m.r	SECOND	BATHROOM	Negative	1	1	0	0.02
1644	5/21/13	mg/cm ²	DOOR t	WOOD	C	INTACT	WHITE	2730 m.r	SECOND	BATHROOM	Negative	1	1	0	0.02
1645	5/21/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2732 m.r	FIRST	LIVING ROOM	Negative	1	1	0	0.02
1646	5/21/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2732 m.r	FIRST	LIVING ROOM	Negative	1	1	0	0.02
1647	5/21/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2732 m.r	FIRST	LIVING ROOM	Negative	1	1	0	0.02
1648	5/21/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2732 m.r	FIRST	LIVING ROOM	Negative	1	1	0	0.02
1649	5/21/13	mg/cm ²	CEILING	DRYWALL	A	INTACT	WHITE	2732 m.r	FIRST	LIVING ROOM	Negative	1.2	1	0	0.02
1650	5/21/13	mg/cm ²	BASEBOARD	WOOD	A	INTACT	WHITE	2732 m.r	FIRST	LIVING ROOM	Negative	1	1	0	0.02
1651	5/21/13	mg/cm ²	WINDOW t	WOOD	C	INTACT	WHITE	2732 m.r	FIRST	LIVING ROOM	Negative	1.06	1	0	0.02
1652	5/21/13	mg/cm ²	WINDOW s	WOOD	C	INTACT	WHITE	2732 m.r	FIRST	LIVING ROOM	Negative	1	1	0	0.02
1653	5/21/13	mg/cm ²	DOOR	WOOD	C	INTACT	WHITE	2732 m.r	FIRST	LIVING ROOM	Negative	1	1	0	0.02
1654	5/21/13	mg/cm ²	DOOR t	WOOD	C	INTACT	WHITE	2732 m.r	FIRST	LIVING ROOM	Negative	1	1	0	0.02
1655	5/21/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2732 m.r	FIRST	LIVING ROOM	Negative	1	1	0	0.02
1656	5/21/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2732 m.r	FIRST	LIVING ROOM	Negative	1	1	0	0.02
1657	5/21/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2732 m.r	FIRST	LIVING ROOM	Negative	1	1	0	0.02
1658	5/21/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2732 m.r	FIRST	LIVING ROOM	Negative	1	1	0	0.02
1659	5/21/13	mg/cm ²	CEILING	DRYWALL	D	INTACT	WHITE	2732 m.r	FIRST	LIVING ROOM	Negative	1	1	0	0.02
1660	5/21/13	mg/cm ²	BASEBOARD	WOOD	A	INTACT	WHITE	2732 m.r	FIRST	LIVING ROOM	Negative	1	1	0	0.02
1661	5/21/13	mg/cm ²	WINDOW t	WOOD	A	INTACT	WHITE	2732 m.r	FIRST	LIVING ROOM	Negative	1	1	0	0.02
1662	5/21/13	mg/cm ²	WINDOW s	WOOD	A	INTACT	WHITE	2732 m.r	FIRST	LIVING ROOM	Negative	1	1	0	0.02
1663	5/21/13	mg/cm ²	DOOR	WOOD	A	INTACT	WHITE	2732 m.r	FIRST	LIVING ROOM	Negative	1	1	0	0.02
1664	5/21/13	mg/cm ²	DOOR t	WOOD	A	INTACT	WHITE	2732 m.r	FIRST	LIVING ROOM	Negative	1	1	0	0.02
1665	5/21/13	mg/cm ²	WALL	CONCRETE	A	INTACT	WHITE	2732 m.r	BASEMENT	room	Negative	1	1	0	0.02
1666	5/21/13	mg/cm ²	WALL	CONCRETE	B	INTACT	WHITE	2732 m.r	BASEMENT	room	Negative	1	1	0	0.02
1667	5/21/13	mg/cm ²	WALL	CONCRETE	C	INTACT	WHITE	2732 m.r	BASEMENT	room	Negative	1	1	0	0.02
1668	5/21/13	mg/cm ²	WALL	CONCRETE	D	INTACT	WHITE	2732 m.r	BASEMENT	room	Negative	1.41	1	0	0.02

1669	5/21/13	mg/cm ²	FLOOR	CONCRETE	A	INTACT	BLUE	2732 m.r	BASEMENT	room	Negative	2.14	1	0.01	0.02
1670	5/21/13	mg/cm ²	TREAD	WOOD	A	INTACT	BLUE	2732 m.r	BASEMENT	STAIR	Negative	2.3	1	0.08	0.2
1671	5/21/13	mg/cm ²	RISER	WOOD	A	INTACT	BLUE	2732 m.r	BASEMENT	STAIR	Negative	1	1	0.04	0.08
1672	5/21/13	mg/cm ²	stringer	WOOD	A	INTACT	BLUE	2732 m.r	BASEMENT	STAIR	Negative	1	1	0.03	0.08
1673	5/21/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2732 m.r	BASEMENT	STAIR	Negative	1	1	0	0.02
1674	5/21/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2732 m.r	BASEMENT	STAIR	Negative	1	1	0	0.02
1675	5/21/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2732 m.r	BASEMENT	STAIR	Negative	1	1	0	0.02
1676	5/21/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2732 m.r	BASEMENT	STAIR	Negative	1	1	0	0.02
1677	5/21/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2732 m.r	SECOND	BEDROOM 1	Negative	4.03	1	0.03	0.12
1678	5/21/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2732 m.r	SECOND	BEDROOM 1	Negative	6.86	1	0.04	0.18
1679	5/21/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2732 m.r	SECOND	BEDROOM 1	Negative	1.56	1	0	0.02
1680	5/21/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2732 m.r	SECOND	BEDROOM 1	Negative	1.69	1	0	0.02
1681	5/21/13	mg/cm ²	CEILING	DRYWALL	A	INTACT	WHITE	2732 m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.02
1682	5/21/13	mg/cm ²	BASEBOARD	WOOD	A	INTACT	WHITE	2732 m.r	SECOND	BEDROOM 1	Negative	1.56	1	0.01	0.04
1683	5/21/13	mg/cm ²	BASEBOARD	WOOD	C	INTACT	WHITE	2732 m.r	SECOND	BEDROOM 1	Negative	1.69	1	0.01	0.03
1684	5/21/13	mg/cm ²	WINDOW t	WOOD	C	INTACT	WHITE	2732 m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.02
1685	5/21/13	mg/cm ²	WINDOW s	WOOD	B	INTACT	WHITE	2732 m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.03
1686	5/21/13	mg/cm ²	DOOR	WOOD	B	INTACT	WHITE	2732 m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.02
1687	5/21/13	mg/cm ²	DOOR j	WOOD	B	INTACT	WHITE	2732 m.r	SECOND	BEDROOM 1	Negative	1.39	1	0.01	0.04
1688	5/21/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2732 m.r	SECOND	BEDROOM 2	Negative	1.47	1	0	0.02
1689	5/21/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2732 m.r	SECOND	BEDROOM 2	Negative	4.92	1	0.02	0.1
1690	5/21/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2732 m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.02
1691	5/21/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2732 m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.02
1692	5/21/13	mg/cm ²	BASEBOARD	WOOD	A	INTACT	WHITE	2732 m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.02
1693	5/21/13	mg/cm ²	DOOR	WOOD	A	INTACT	WHITE	2732 m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.02
1694	5/21/13	mg/cm ²	DOOR t	WOOD	A	INTACT	WHITE	2732 m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.03
1695	5/21/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2732 m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.02
1696	5/21/13	mg/cm ²	WALL	DRYWALL	B	INTACT	YELLOW	2732 m.r	SECOND	BATHROOM	Negative	4.36	1	0.02	0.08
1697	5/21/13	mg/cm ²	WALL	DRYWALL	B	INTACT	YELLOW	2732 m.r	SECOND	BATHROOM	Null	1	1	0	0.03
1698	5/21/13	mg/cm ²	WALL	DRYWALL	C	INTACT	YELLOW	2732 m.r	SECOND	BATHROOM	Negative	1	1	0	0.02
1699	5/21/13	mg/cm ²	WALL	DRYWALL	D	INTACT	YELLOW	2732 m.r	SECOND	BATHROOM	Negative	6.11	1	0.04	0.14
1700	5/21/13	mg/cm ²	CEILING	DRYWALL	A	INTACT	WHITE	2732 m.r	SECOND	BATHROOM	Negative	1.28	1	0.01	0.03
1701	5/21/13	mg/cm ²	TRIM	WOOD	A	INTACT	WHITE	2732 m.r	SECOND	BATHROOM	Negative	2.7	1	0.02	0.08
1702	5/21/13	mg/cm ²	DOOR	WOOD	D	INTACT	WHITE	2732 m.r	SECOND	BATHROOM	Negative	1	1	0	0.02
1703	5/21/13	mg/cm ²	DOOR t	WOOD	D	INTACT	WHITE	2732 m.r	SECOND	BATHROOM	Negative	2.51	1	0.01	0.09
1704	5/21/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2732 m.r	SECOND	BATHROOM	Negative	3.69	1	0.03	0.12
1705	5/21/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2732 m.r	SECOND	BEDROOM 3	Negative	4.86	1	0.04	0.16
1706	5/21/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2732 m.r	SECOND	BEDROOM 3	Negative	1	1	0	0.02
1707	5/21/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2732 m.r	SECOND	BEDROOM 3	Negative	1	1	0	0.02
1708	5/21/13	mg/cm ²	CEILING	WOOD	A	INTACT	WHITE	2732 m.r	SECOND	BEDROOM 3	Negative	9.9	1	-0.08	1.06
1709	5/21/13	mg/cm ²	BASEBOARD	WOOD	A	INTACT	WHITE	2732 m.r	SECOND	BEDROOM 3	Negative	1	1	0	0.02
1710	5/21/13	mg/cm ²	WINDOW t	WOOD	A	INTACT	WHITE	2732 m.r	SECOND	BEDROOM 3	Null	1	1	0	0.02
1711	5/21/13	mg/cm ²	WINDOW t	WOOD	A	INTACT	WHITE	2732 m.r	SECOND	BEDROOM 3	Negative	1	1	0	0.02
1712	5/21/13	mg/cm ²	WINDOW s	WOOD	A	INTACT	WHITE	2732 m.r	SECOND	BEDROOM 3	Negative	1	1	0	0.03
1713	5/21/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2732 m.r	SECOND	BEDROOM 3	Negative	1	1	0	0.02
1714	5/21/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2742 m.r	FIRST	LIVING ROOM	Negative	1	1	0	0.02
1715	5/21/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2742 m.r	FIRST	LIVING ROOM	Negative	1	1	0	0.02
1716	5/21/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2742 m.r	FIRST	LIVING ROOM	Negative	1.46	1	0	0.02

1715	5/21/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2742 m.r	FIRST	LIVING ROOM	Negative	1	1	0	0.02
1716	5/21/13	mg/cm ²	CEILING	DRYWALL	D	INTACT	WHITE	2742 m.r	FIRST	LIVING ROOM	Negative	1.16	1	0	0.02
1717	5/21/13	mg/cm ²	BASEBOARD	DRYWALL	A	INTACT	WHITE	2742 m.r	FIRST	LIVING ROOM	Negative	3.92	1	0.02	0.07
1718	5/21/13	mg/cm ²	DOOR	WOOD	A	INTACT	WHITE	2742 m.r	FIRST	LIVING ROOM	Negative	1	1	0	0.02
1719	5/21/13	mg/cm ²	DOOR t	WOOD	A	INTACT	WHITE	2742 m.r	FIRST	LIVING ROOM	Negative	1.1	1	0.09	0.1
1720	5/21/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2742 m.r	FIRST	KITCHEN	Negative	2.21	1	0.02	0.06
1721	5/21/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2742 m.r	FIRST	KITCHEN	Negative	1	1	0	0.02
1722	5/21/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2742 m.r	FIRST	KITCHEN	Negative	1	1	0	0.02
1723	5/21/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2742 m.r	FIRST	KITCHEN	Negative	7.89	1	0.04	0.14
1724	5/21/13	mg/cm ²	CEILING	DRYWALL	D	INTACT	WHITE	2742 m.r	FIRST	KITCHEN	Negative	2.08	1	0.01	0.02
1725	5/21/13	mg/cm ²	BASEBOARD	WOOD	A	INTACT	WHITE	2742 m.r	FIRST	KITCHEN	Negative	1	1	0	0.02
1726	5/21/13	mg/cm ²	WINDOW t	WOOD	A	INTACT	WHITE	2742 m.r	FIRST	KITCHEN	Negative	1	1	0	0.02
1727	5/21/13	mg/cm ²	WINDOW s	WOOD	A	INTACT	WHITE	2742 m.r	FIRST	KITCHEN	Negative	1.21	1	0	0.02
1728	5/21/13	mg/cm ²	DOOR	WOOD	A	INTACT	WHITE	2742 m.r	FIRST	KITCHEN	Negative	1.16	1	0.07	0.09
1729	5/21/13	mg/cm ²	DOOR t	WOOD	A	INTACT	WHITE	2742 m.r	FIRST	KITCHEN	Negative	1	1	0	0.02
1730	5/21/13	mg/cm ²	WALL	CONCRETE	A	INTACT	WHITE	2742 m.r	BASEMENT	room	Negative	1	1	0	0.02
1731	5/21/13	mg/cm ²	WALL	CONCRETE	B	INTACT	WHITE	2742 m.r	BASEMENT	room	Negative	1	1	0	0.02
1732	5/21/13	mg/cm ²	WALL	CONCRETE	C	INTACT	WHITE	2742 m.r	BASEMENT	room	Negative	1	1	0	0.02
1733	5/21/13	mg/cm ²	WALL	CONCRETE	D	INTACT	WHITE	2742 m.r	BASEMENT	room	Negative	1	1	0	0.02
1734	5/21/13	mg/cm ²	FLOOR	CONCRETE	A	INTACT	BLUE	2742 m.r	BASEMENT	room	Negative	1	1	0	0.02
1735	5/21/13	mg/cm ²	TREAD	WOOD	A	INTACT	BLUE	2742 m.r	BASEMENT	room	Negative	3.08	1	0.14	0.32
1736	5/21/13	mg/cm ²	RISER	WOOD	A	INTACT	BLUE	2742 m.r	BASEMENT	room	Negative	5.24	1	0.23	0.57
1737	5/21/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2742 m.r	BASEMENT	STAIR	Negative	3.1	1	0.01	0.05
1738	5/21/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2742 m.r	BASEMENT	STAIR	Negative	1	1	0	0.02
1739	5/21/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2742 m.r	BASEMENT	STAIR	Negative	1	1	0	0.02
1740	5/21/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2742 m.r	BASEMENT	STAIR	Negative	1	1	0	0.02
1741	5/21/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2742 m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.02
1742	5/21/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2742 m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.02
1743	5/21/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2742 m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.02
1744	5/21/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2742 m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.02
1745	5/21/13	mg/cm ²	CEILING	DRYWALL	D	INTACT	WHITE	2742 m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.02
1746	5/21/13	mg/cm ²	BASEBOARD	WOOD	A	INTACT	WHITE	2742 m.r	SECOND	BEDROOM 1	Negative	7.58	1	0.03	0.07
1747	5/21/13	mg/cm ²	WINDOW t	WOOD	A	INTACT	WHITE	2742 m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.02
1748	5/21/13	mg/cm ²	WINDOW s	WOOD	A	INTACT	WHITE	2742 m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.02
1749	5/21/13	mg/cm ²	DOOR	WOOD	C	INTACT	WHITE	2742 m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.02
1750	5/21/13	mg/cm ²	DOOR J	WOOD	C	INTACT	WHITE	2742 m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.02
1751	5/21/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2742 m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.02
1752	5/21/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2742 m.r	SECOND	BEDROOM 2	Negative	3.41	1	0.01	0.04
1753	5/21/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2742 m.r	SECOND	BEDROOM 2	Negative	1.04	1	0	0.02
1754	5/21/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2742 m.r	SECOND	BEDROOM 2	Negative	2.31	1	0.01	0.04
1755	5/21/13	mg/cm ²	CABINET	DRYWALL	A	INTACT	WHITE	2742 m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.02
1756	5/21/13	mg/cm ²	WINDOW t	DRYWALL	A	INTACT	WHITE	2742 m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.02
1757	5/21/13	mg/cm ²	WINDOW s	DRYWALL	A	INTACT	WHITE	2742 m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.02
1758	5/21/13	mg/cm ²	DOOR	WOOD	A	INTACT	WHITE	2742 m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.03
1759	5/21/13	mg/cm ²	DOOR t	WOOD	A	INTACT	WHITE	2742 m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.03
1760	5/21/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2742 m.r	SECOND	BEDROOM 3	Negative	1.29	1	0.01	0.03
												1	1	0	0.02

1761	5/21/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2742 m.r	SECOND	BEDROOM 3	Negative	1	1	0	0.02
1762	5/21/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2742 m.r	SECOND	BEDROOM 3	Negative	1	1	0	0.02
1763	5/21/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2742 m.r	SECOND	BEDROOM 3	Negative	1	1	0	0.02
1764	5/21/13	mg/cm ²	CEILING	DRYWALL	D	INTACT	WHITE	2742 m.r	SECOND	BEDROOM 3	Negative	4.93	1	0.02	0.09
1765	5/21/13	mg/cm ²	BASEBOARD	WOOD	A	INTACT	WHITE	2742 m.r	SECOND	BEDROOM 3	Negative	1	1	0	0.02
1766	5/21/13	mg/cm ²	WINDOW t	WOOD	A	INTACT	WHITE	2742 m.r	SECOND	BEDROOM 3	Negative	1	1	0	0.02
1767	5/21/13	mg/cm ²	WINDOW s	WOOD	A	INTACT	WHITE	2742 m.r	SECOND	BEDROOM 3	Negative	1	1	0	0.02
1768	5/21/13	mg/cm ²	DOOR	WOOD	C	INTACT	WHITE	2742 m.r	SECOND	BEDROOM 3	Negative	1	1	0	0.03
1769	5/21/13	mg/cm ²	DOOR t	WOOD	C	INTACT	WHITE	2742 m.r	SECOND	BEDROOM 3	Negative	1	1	0	0.02
1770	5/21/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2742 m.r	SECOND	BATHROOM	Negative	1	1	0	0.02
1771	5/21/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2742 m.r	SECOND	BATHROOM	Negative	1.55	1	0.01	0.03
1772	5/21/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2742 m.r	SECOND	BATHROOM	Negative	2.56	1	0.01	0.04
1773	5/21/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2742 m.r	SECOND	BATHROOM	Negative	1	1	0	0.02
1774	5/21/13	mg/cm ²	CEILING	DRYWALL	D	INTACT	WHITE	2742 m.r	SECOND	BATHROOM	Negative	1	1	0	0.02
1775	5/21/13	mg/cm ²	TRIM	WOOD	A	INTACT	WHITE	2742 m.r	SECOND	BATHROOM	Negative	1	1	0	0.02
1776	5/21/13	mg/cm ²	DOOR	WOOD	B	INTACT	WHITE	2742 m.r	SECOND	BATHROOM	Negative	1	1	0	0.02
1777	5/21/13	mg/cm ²	DOOR j	WOOD	B	INTACT	WHITE	2742 m.r	SECOND	BATHROOM	Negative	1	1	0	0.02
1778	5/21/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2748 m.r	SECOND	BATHROOM	Negative	1.48	1	0.01	0.04
1779	5/21/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2748 m.r	SECOND	KITCHEN	Negative	1	1	0	0.02
1780	5/21/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2748 m.r	SECOND	KITCHEN	Negative	1.59	1	0	0.02
1781	5/21/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2748 m.r	SECOND	KITCHEN	Negative	1	1	0	0.02
1782	5/21/13	mg/cm ²	CEILING	DRYWALL	D	INTACT	WHITE	2748 m.r	SECOND	KITCHEN	Negative	1	1	0	0.02
1783	5/21/13	mg/cm ²	BASEBOARD	DRYWALL	A	INTACT	WHITE	2748 m.r	SECOND	KITCHEN	Negative	1	1	0	0.02
1784	5/21/13	mg/cm ²	WINDOW t	WOOD	A	INTACT	WHITE	2748 m.r	SECOND	KITCHEN	Negative	1.59	1	0	0.02
1785	5/21/13	mg/cm ²	WINDOW s	WOOD	A	INTACT	WHITE	2748 m.r	SECOND	KITCHEN	Negative	1	1	0	0.02
1786	5/21/13	mg/cm ²	DOOR	WOOD	A	INTACT	WHITE	2748 m.r	SECOND	KITCHEN	Negative	1.5	1	0.25	0.2
1787	5/21/13	mg/cm ²	DOOR j	WOOD	A	INTACT	WHITE	2748 m.r	SECOND	KITCHEN	Negative	1	1	0	0.02
1788	5/21/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2748 m.r	SECOND	LIVING ROOM	Negative	1	1	0	0.02
1789	5/21/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2748 m.r	SECOND	LIVING ROOM	Negative	1	1	0	0.02
1790	5/21/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2748 m.r	SECOND	LIVING ROOM	Negative	2.84	1	0.01	0.04
1791	5/21/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2748 m.r	SECOND	LIVING ROOM	Negative	1	1	0	0.02
1792	5/21/13	mg/cm ²	CEILING	DRYWALL	A	INTACT	WHITE	2748 m.r	SECOND	LIVING ROOM	Negative	1	1	0	0.02
1793	5/21/13	mg/cm ²	WINDOW t	DRYWALL	A	INTACT	WHITE	2748 m.r	SECOND	LIVING ROOM	Negative	1.9	1	0	0.02
1794	5/21/13	mg/cm ²	WINDOW s	DRYWALL	A	INTACT	WHITE	2748 m.r	SECOND	LIVING ROOM	Negative	1	1	0	0.02
1795	5/21/13	mg/cm ²	WALL	CONCRETE	A	INTACT	WHITE	2748 m.r	BASEMENT	LIVING ROOM	Negative	1	1	0	0.02
1796	5/21/13	mg/cm ²	WALL	CONCRETE	B	INTACT	WHITE	2748 m.r	BASEMENT	room	Negative	1.44	1	0	0.02
1797	5/21/13	mg/cm ²	WALL	CONCRETE	C	INTACT	WHITE	2748 m.r	BASEMENT	room	Negative	1	1	0	0.02
1798	5/21/13	mg/cm ²	WALL	CONCRETE	D	INTACT	WHITE	2748 m.r	BASEMENT	room	Negative	1	1	0	0.02
1799	5/21/13	mg/cm ²	FLOOR	CONCRETE	A	INTACT	WHITE	2748 m.r	BASEMENT	room	Negative	1.63	1	0	0.02
1800	5/21/13	mg/cm ²	TREAD	WOOD	A	INTACT	BLUE	2748 m.r	BASEMENT	room	Negative	2.85	1	0.01	0.03
1801	5/21/13	mg/cm ²	RISER	WOOD	A	INTACT	BLUE	2748 m.r	BASEMENT	room	Negative	1	1	0.02	0.06
1802	5/21/13	mg/cm ²	stringer	WOOD	A	INTACT	BLUE	2748 m.r	BASEMENT	room	Negative	1.65	1	0.04	0.11
1803	5/21/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2748 m.r	BASEMENT	room	Negative	2.56	1	0.05	0.17
1804	5/21/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2748 m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.02
1805	5/21/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2748 m.r	SECOND	BEDROOM 1	Negative	5.75	1	0.03	0.12
1806	5/21/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2748 m.r	SECOND	BEDROOM 1	Negative	1.15	1	0	0.02
												2.61	1	0.01	0.04

1807	5/21/13	mg/cm ²	BASEBOARD	WOOD	A	INTACT	WHITE	2748 m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.02
1808	5/21/13	mg/cm ²	WINDOW t	WOOD	A	INTACT	WHITE	2748 m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.02
1809	5/21/13	mg/cm ²	WINDOW s	WOOD	A	INTACT	WHITE	2748 m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.02
1810	5/21/13	mg/cm ²	DOOR	WOOD	A	INTACT	WHITE	2748 m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.03
1811	5/21/13	mg/cm ²	DOOR j	WOOD	A	INTACT	WHITE	2748 m.r	SECOND	BEDROOM 1	Negative	1.18	1	0.01	0.03
1812	5/21/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2748 m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.02
1813	5/21/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2748 m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.02
1814	5/21/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2748 m.r	SECOND	BEDROOM 1	Negative	1.72	1	0.01	0.03
1815	5/21/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2748 m.r	SECOND	BEDROOM 1	Negative	1.51	1	0.01	0.02
1816	5/21/13	mg/cm ²	CEILING	DRYWALL	D	INTACT	WHITE	2748 m.r	SECOND	BEDROOM 1	Negative	1.24	1	0	0.03
1817	5/21/13	mg/cm ²	BASEBOARD	WOOD	A	INTACT	WHITE	2748 m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.02
1818	5/21/13	mg/cm ²	WINDOW t	WOOD	A	INTACT	WHITE	2748 m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.02
1819	5/21/13	mg/cm ²	DOOR	WOOD	B	INTACT	WHITE	2748 m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.03
1820	5/21/13	mg/cm ²	DOOR t	WOOD	B	INTACT	WHITE	2748 m.r	SECOND	BEDROOM 1	Negative	1.1	1	0.01	0.02
1821	5/21/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2748 m.r	SECOND	BATHROOM	Negative	1.5	1	0	0.03
1822	5/21/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2748 m.r	SECOND	BATHROOM	Negative	1.02	1	0	0.02
1823	5/21/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2748 m.r	SECOND	BATHROOM	Negative	1	1	0	0.02
1824	5/21/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2748 m.r	SECOND	BATHROOM	Negative	1	1	0	0.02
1825	5/21/13	mg/cm ²	CEILING	DRYWALL	A	INTACT	WHITE	2748 m.r	SECOND	BATHROOM	Negative	1	1	0	0.02
1826	5/21/13	mg/cm ²	TRIM	WOOD	A	INTACT	WHITE	2748 m.r	SECOND	BATHROOM	Negative	5.27	1	0.04	0.14
1827	5/21/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2748 m.r	SECOND	BATHROOM	Negative	1	1	0	0.02
1828	5/21/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2748 m.r	SECOND	BEDROOM 3	Negative	1	1	0	0.02
1829	5/21/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2748 m.r	SECOND	BEDROOM 3	Negative	1.25	1	0	0.03
1830	5/21/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2748 m.r	SECOND	BEDROOM 3	Negative	1	1	0	0.02
1831	5/21/13	mg/cm ²	CABINET	DRYWALL	D	INTACT	WHITE	2748 m.r	SECOND	BEDROOM 3	Negative	2.71	1	0.02	0.06
1832	5/21/13	mg/cm ²	BASEBOARD	WOOD	A	INTACT	WHITE	2748 m.r	SECOND	BEDROOM 3	Negative	1	1	0	0.02
1833	5/21/13	mg/cm ²	WINDOW t	WOOD	A	INTACT	WHITE	2748 m.r	SECOND	BEDROOM 3	Negative	1	1	0	0.02
1834	5/21/13	mg/cm ²	WINDOW s	WOOD	A	INTACT	WHITE	2748 m.r	SECOND	BEDROOM 3	Negative	1	1	0	0.02
1835	5/21/13	mg/cm ²	DOOR	WOOD	A	INTACT	WHITE	2748 m.r	SECOND	BEDROOM 3	Negative	1	1	0	0.03
1836	5/21/13	mg/cm ²	DOOR j	WOOD	A	INTACT	WHITE	2748 m.r	SECOND	BEDROOM 3	Negative	1	1	0	0.02
1837	5/21/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2744 m.r	SECOND	BEDROOM 3	Negative	1.6	1	0.01	0.05
1838	5/21/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2744 m.r	SECOND	BEDROOM 3	Negative	2.99	1	0.01	0.04
1839	5/21/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2744 m.r	SECOND	BEDROOM 3	Negative	1	1	0	0.02
1840	5/21/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2744 m.r	SECOND	BEDROOM 3	Negative	1	1	0	0.02
1841	5/21/13	mg/cm ²	CEILING	DRYWALL	D	INTACT	WHITE	2744 m.r	SECOND	BEDROOM 3	Negative	1	1	0	0.02
1842	5/21/13	mg/cm ²	WINDOW t	DRYWALL	D	INTACT	WHITE	2744 m.r	SECOND	BEDROOM 3	Negative	1.05	1	0	0.02
1843	5/21/13	mg/cm ²	WINDOW s	DRYWALL	D	INTACT	WHITE	2744 m.r	SECOND	BEDROOM 3	Negative	1.96	1	0.01	0.05
1844	5/21/13	mg/cm ²	WALL	WOOD	A	INTACT	WHITE	2744 m.r	SECOND	BEDROOM 3	Negative	1.12	1	0	0.02
1845	5/21/13	mg/cm ²	DOOR t	WOOD	A	INTACT	WHITE	2744 m.r	SECOND	BEDROOM 3	Negative	1.42	1	0.12	0.13
1846	5/21/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2744 m.r	SECOND	BEDROOM 3	Negative	1	1	0	0.02
1847	5/21/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2744 m.r	SECOND	LIVING ROOM	Negative	1	1	0	0.02
1848	5/21/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2744 m.r	SECOND	LIVING ROOM	Negative	1.19	1	0	0.02
1849	5/21/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2744 m.r	SECOND	LIVING ROOM	Negative	1	1	0	0.02
1850	5/21/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2744 m.r	SECOND	LIVING ROOM	Negative	2.66	1	0.01	0.05
1851	5/21/13	mg/cm ²	CEILING	DRYWALL	D	INTACT	WHITE	2744 m.r	SECOND	LIVING ROOM	Negative	1	1	0	0.02
1852	5/21/13	mg/cm ²	BASEBOARD	DRYWALL	D	INTACT	WHITE	2744 m.r	SECOND	LIVING ROOM	Negative	1	1	0	0.02
			DOOR	WOOD	A	INTACT	WHITE	2744 m.r	SECOND	LIVING ROOM	Negative	1	1	0	0.02

1853	5/21/13	mg/cm ²	DOOR t	WOOD	A	INTACT	WHITE	2744 m.r	SECOND	LIVING ROOM	Negative	1	1	0	0.02
1854	5/21/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2744 m.r	SECOND	BATHROOM	Negative	5.92	1	0.17	0.27
1855	5/21/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2744 m.r	SECOND	BATHROOM	Negative	10	1	0.3	0.69
1856	5/21/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2744 m.r	SECOND	BATHROOM	Negative	4.67	1	0.11	0.16
1857	5/21/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2744 m.r	SECOND	BATHROOM	Negative	1	1	0	0.02
1858	5/21/13	mg/cm ²	DOOR	WOOD	D	INTACT	WHITE	2744 m.r	SECOND	BATHROOM	Negative	1	1	0	0.03
1859	5/21/13	mg/cm ²	DOOR t	WOOD	D	INTACT	WHITE	2744 m.r	SECOND	BATHROOM	Negative	1	1	0	0.02
1860	5/21/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2744 m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.02
1861	5/21/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2744 m.r	SECOND	BEDROOM 1	Negative	1.41	1	0	0.02
1862	5/21/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2744 m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.02
1863	5/21/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2744 m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.02
1864	5/21/13	mg/cm ²	CEILING	DRYWALL	D	INTACT	WHITE	2744 m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.02
1865	5/21/13	mg/cm ²	BASEBOARD	DRYWALL	A	INTACT	WHITE	2744 m.r	SECOND	BEDROOM 1	Negative	7.8	1	0.05	0.18
1866	5/21/13	mg/cm ²	WINDOW t	DRYWALL	A	INTACT	WHITE	2744 m.r	SECOND	BEDROOM 1	Negative	1.74	1	0.01	0.05
1867	5/21/13	mg/cm ²	WINDOW s	DRYWALL	A	INTACT	WHITE	2744 m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.02
1868	5/21/13	mg/cm ²	DOOR	WOOD	A	INTACT	WHITE	2744 m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.02
1869	5/21/13	mg/cm ²	DOOR t	WOOD	A	INTACT	WHITE	2744 m.r	SECOND	BEDROOM 1	Negative	4.62	1	0.05	0.17
1870	5/21/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2744 m.r	SECOND	BEDROOM 2	Negative	3.05	1	0.01	0.05
1871	5/21/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2744 m.r	SECOND	BEDROOM 2	Negative	2.69	1	0.01	0.06
1872	5/21/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2744 m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.02
1873	5/21/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2744 m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.02
1874	5/21/13	mg/cm ²	CEILING	DRYWALL	D	INTACT	WHITE	2744 m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.02
1875	5/21/13	mg/cm ²	BASEBOARD	WOOD	A	INTACT	WHITE	2744 m.r	SECOND	BEDROOM 2	Negative	1.44	1	0.01	0.03
1876	5/21/13	mg/cm ²	DOOR	WOOD	A	INTACT	WHITE	2744 m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.02
1877	5/21/13	mg/cm ²	DOOR t	WOOD	A	INTACT	WHITE	2744 m.r	SECOND	BEDROOM 2	Negative	1.5	1	0.01	0.04
1878	5/21/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2744 m.r	SECOND	BATHROOM	Negative	2.9	1	0.02	0.08
1879	5/21/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2744 m.r	SECOND	BATHROOM	Negative	4.86	1	0.05	0.18
1880	5/21/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2744 m.r	SECOND	BATHROOM	Negative	1.89	1	0.01	0.03
1881	5/21/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2744 m.r	SECOND	BATHROOM	Negative	7.27	1	0.04	0.15
1882	5/21/13	mg/cm ²	DOOR	WOOD	B	INTACT	WHITE	2744 m.r	SECOND	BATHROOM	Negative	1	1	0	0.02
1883	5/21/13	mg/cm ²	DOOR t	WOOD	B	INTACT	WHITE	2744 m.r	SECOND	BATHROOM	Negative	2.57	1	0.02	0.11
1884	5/21/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2744 m.r	SECOND	BEDROOM 3	Negative	1.45	1	0	0.02
1885	5/21/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2744 m.r	SECOND	BEDROOM 3	Negative	1	1	0	0.02
1886	5/21/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2744 m.r	SECOND	BEDROOM 3	Negative	5.4	1	0.03	0.13
1887	5/21/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2744 m.r	SECOND	BEDROOM 3	Negative	1	1	0	0.02
1888	5/21/13	mg/cm ²	CEILING	DRYWALL	A	INTACT	WHITE	2744 m.r	SECOND	BEDROOM 3	Negative	5.37	1	0.03	0.12
1889	5/21/13	mg/cm ²	BASEBOARD	WOOD	A	INTACT	WHITE	2744 m.r	SECOND	BEDROOM 3	Negative	1	1	0	0.02
1890	5/21/13	mg/cm ²	WINDOW t	WOOD	C	INTACT	WHITE	2744 m.r	SECOND	BEDROOM 3	Negative	1	1	0	0.02
1891	5/21/13	mg/cm ²	WINDOW s	WOOD	C	INTACT	WHITE	2744 m.r	SECOND	BEDROOM 3	Negative	1.13	1	0	0.03
1892	5/21/13	mg/cm ²	DOOR	WOOD	A	INTACT	WHITE	2744 m.r	SECOND	BEDROOM 3	Negative	1	1	0	0.03
1893	5/21/13	mg/cm ²	DOOR t	WOOD	A	INTACT	WHITE	2744 m.r	SECOND	BEDROOM 3	Negative	1.99	1	0.01	0.06
1894	5/21/13	mg/cm ²	WALL	WOOD	A	INTACT	WHITE	2744 m.r	SECOND	BEDROOM 4	Negative	1	1	0	0.02
1895	5/21/13	mg/cm ²	WALL	WOOD	B	INTACT	WHITE	2744 m.r	SECOND	BEDROOM 4	Negative	1	1	0	0.02
1896	5/21/13	mg/cm ²	WALL	WOOD	C	INTACT	WHITE	2744 m.r	SECOND	BEDROOM 4	Negative	2.13	1	0.01	0.04
1897	5/21/13	mg/cm ²	WALL	WOOD	D	INTACT	WHITE	2744 m.r	SECOND	BEDROOM 4	Negative	1	1	0	0.02
1898	5/21/13	mg/cm ²	CEILING	WOOD	A	INTACT	WHITE	2744 m.r	SECOND	BEDROOM 4	Negative	1.12	1	0.01	0.03

1899	5/21/13	mg/cm ²	WINDOW	WOOD	A	INTACT	WHITE	2744	m.r	SECOND	BEDROOM 4	Negative	1	1	0	0.02
1900	5/21/13	mg/cm ²	WINDOW	WOOD	A	INTACT	WHITE	2744	m.r	SECOND	BEDROOM 4	Negative	1	1	0	0.02
1901	5/21/13	mg/cm ²	DOOR	WOOD	A	INTACT	WHITE	2744	m.r	SECOND	BEDROOM 4	Negative	1	1	0	0.02
1902	5/21/13	mg/cm ²	DOOR	WOOD	A	INTACT	WHITE	2744	m.r	SECOND	BEDROOM 4	Negative	1	1	0	0.02
1903	5/21/13	mg/cm ²	cal									Positive	1.1	1	1	0.1
1904	5/21/13	mg/cm ²	cal									Positive	1.14	1	1.1	0.1
1905	5/21/13	mg/cm ²	cal									Negative	1.03	1	0.9	0.1

Reading #	Time	Units	Component	Substrate	Side	Condition	Color	Site	Inspector	Floor	Room	Results	Depth	Action	PbC	PbC Error
1	5/22/13	mg/cm ²	cal									Positive	1.05	1	1	0.1
2	5/22/13	mg/cm ²	cal									Negative	1.06	1	0.9	0.1
3	5/22/13	mg/cm ²	cal									Negative	1.02	1	0.9	0.1
4	5/22/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2760 m.r		FIRST	KITCHEN	Negative	1	1	0	0.02
5	5/22/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2760 m.r		FIRST	KITCHEN	Negative	1	1	0	0.02
6	5/22/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2760 m.r		FIRST	KITCHEN	Negative	1	1	0	0.02
7	5/22/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2760 m.r		FIRST	KITCHEN	Negative	1	1	0	0.02
8	5/22/13	mg/cm ²	CEILING	DRYWALL	D	INTACT	WHITE	2760 m.r		FIRST	KITCHEN	Negative	1	1	0	0.02
9	5/22/13	mg/cm ²	BASEBOARD	DRYWALL	A	INTACT	WHITE	2760 m.r		FIRST	KITCHEN	Negative	1	1	0	0.02
10	5/22/13	mg/cm ²	WINDOW t	WOOD	A	INTACT	WHITE	2760 m.r		FIRST	KITCHEN	Negative	1	1	0	0.02
11	5/22/13	mg/cm ²	WINDOW s	WOOD	A	INTACT	WHITE	2760 m.r		FIRST	KITCHEN	Negative	1	1	0	0.02
12	5/22/13	mg/cm ²	DOOR	WOOD	A	INTACT	BEIGE	2760 m.r		FIRST	KITCHEN	Negative	1	1	0	0.02
13	5/22/13	mg/cm ²	DOOR j	WOOD	A	INTACT	BEIGE	2760 m.r		FIRST	KITCHEN	Negative	1.42	1	0.07	0.14
14	5/22/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2760 m.r		FIRST	LIVING ROOM	Negative	1	1	0	0.02
15	5/22/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2760 m.r		FIRST	LIVING ROOM	Negative	1.28	1	0	0.02
16	5/22/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2760 m.r		FIRST	LIVING ROOM	Negative	1	1	0	0.02
17	5/22/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2760 m.r		FIRST	LIVING ROOM	Negative	1	1	0	0.02
18	5/22/13	mg/cm ²	BASEBOARD	DRYWALL	D	INTACT	WHITE	2760 m.r		FIRST	LIVING ROOM	Negative	1	1	0	0.02
19	5/22/13	mg/cm ²	WINDOW t	WOOD	C	INTACT	WHITE	2760 m.r		FIRST	LIVING ROOM	Negative	1	1	0	0.02
20	5/22/13	mg/cm ²	WINDOW s	WOOD	C	INTACT	WHITE	2760 m.r		FIRST	LIVING ROOM	Negative	1	1	0	0.02
21	5/22/13	mg/cm ²	DOOR	WOOD	A	INTACT	WHITE	2760 m.r		FIRST	LIVING ROOM	Negative	1.13	1	0	0.04
22	5/22/13	mg/cm ²	DOOR t	WOOD	A	INTACT	WHITE	2760 m.r		FIRST	LIVING ROOM	Negative	1.09	1	0.12	0.11
23	5/22/13	mg/cm ²	WALL	CONCRETE	A	INTACT	WHITE	2760 m.r		BASEMENT	room	Negative	1	1	0	0.02
24	5/22/13	mg/cm ²	WALL	CONCRETE	B	INTACT	WHITE	2760 m.r		BASEMENT	room	Negative	1	1	0	0.02
25	5/22/13	mg/cm ²	WALL	CONCRETE	B	INTACT	WHITE	2760 m.r		BASEMENT	room	Negative	1	1	0	0.02
26	5/22/13	mg/cm ²	WALL	CONCRETE	C	INTACT	WHITE	2760 m.r		BASEMENT	room	Negative	1	1	0	0.02
27	5/22/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2760 m.r		SECOND	BEDROOM 1	Negative	1	1	0	0.02
28	5/22/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2760 m.r		SECOND	BEDROOM 1	Negative	1	1	0	0.02
29	5/22/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2760 m.r		SECOND	BEDROOM 1	Negative	1	1	0	0.02
30	5/22/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2760 m.r		SECOND	BEDROOM 1	Negative	1	1	0	0.02
31	5/22/13	mg/cm ²	CEILING	DRYWALL	D	INTACT	WHITE	2760 m.r		SECOND	BEDROOM 1	Negative	2.64	1	0.01	0.05
32	5/22/13	mg/cm ²	BASEBOARD	DRYWALL	A	INTACT	WHITE	2760 m.r		SECOND	BEDROOM 1	Negative	1	1	0	0.02
33	5/22/13	mg/cm ²	WINDOW t	WOOD	A	INTACT	WHITE	2760 m.r		SECOND	BEDROOM 1	Negative	1	1	0	0.02
34	5/22/13	mg/cm ²	DOOR	WOOD	C	INTACT	WHITE	2760 m.r		SECOND	BEDROOM 1	Negative	1	1	0	0.02
35	5/22/13	mg/cm ²	DOOR t	WOOD	C	INTACT	WHITE	2760 m.r		SECOND	BEDROOM 1	Negative	1	1	0	0.02
36	5/22/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2760 m.r		SECOND	BEDROOM 1	Negative	1	1	0	0.02
37	5/22/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2760 m.r		SECOND	BEDROOM 2	Negative	1	1	0	0.02
38	5/22/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2760 m.r		SECOND	BEDROOM 2	Negative	1	1	0	0.02
39	5/22/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2760 m.r		SECOND	BEDROOM 2	Negative	1	1	0	0.02
40	5/22/13	mg/cm ²	CEILING	DRYWALL	D	INTACT	WHITE	2760 m.r		SECOND	BEDROOM 2	Negative	1	1	0	0.02
41	5/22/13	mg/cm ²	BASEBOARD	PLASTER	A	INTACT	WHITE	2760 m.r		SECOND	BEDROOM 2	Negative	1	1	0	0.02
42	5/22/13	mg/cm ²	WINDOW t	WOOD	A	INTACT	WHITE	2760 m.r		SECOND	BEDROOM 2	Negative	1	1	0	0.02
43	5/22/13	mg/cm ²	WINDOW s	WOOD	A	INTACT	WHITE	2760 m.r		SECOND	BEDROOM 2	Negative	1	1	0	0.03
44	5/22/13	mg/cm ²	DOOR	WOOD	B	INTACT	WHITE	2760 m.r		SECOND	BEDROOM 2	Negative	1	1	0	0.02
45	5/22/13	mg/cm ²	DOOR t	WOOD	B	INTACT	WHITE	2760 m.r		SECOND	BEDROOM 2	Negative	1	1	0	0.03

46	5/22/13	mg/cm^2	WALL	DRYWALL	A	INTACT	WHITE	2760 m.r	SECOND	BEDROOM 3	Negative	1.02	1	0	0.02
47	5/22/13	mg/cm^2	WALL	DRYWALL	B	INTACT	WHITE	2760 m.r	SECOND	BEDROOM 3	Negative	1	1	0	0.02
48	5/22/13	mg/cm^2	WALL	DRYWALL	C	INTACT	WHITE	2760 m.r	SECOND	BEDROOM 3	Negative	1	1	0	0.02
49	5/22/13	mg/cm^2	WALL	DRYWALL	D	INTACT	WHITE	2760 m.r	SECOND	BEDROOM 3	Negative	1	1	0	0.02
50	5/22/13	mg/cm^2	CEILING	DRYWALL	D	INTACT	WHITE	2760 m.r	SECOND	BEDROOM 3	Negative	1	1	0	0.02
51	5/22/13	mg/cm^2	WINDOW t	DRYWALL	D	INTACT	WHITE	2760 m.r	SECOND	BEDROOM 3	Negative	1	1	0	0.02
52	5/22/13	mg/cm^2	WINDOW s	DRYWALL	D	INTACT	WHITE	2760 m.r	SECOND	BEDROOM 3	Negative	1	1	0	0.03
53	5/22/13	mg/cm^2	DOOR	DRYWALL	D	INTACT	WHITE	2760 m.r	SECOND	BEDROOM 3	Negative	1	1	0	0.02
54	5/22/13	mg/cm^2	DOOR t	DRYWALL	D	INTACT	WHITE	2760 m.r	SECOND	BEDROOM 3	Negative	1.45	1	0.01	0.04
55	5/22/13	mg/cm^2	WALL	DRYWALL	A	INTACT	WHITE	2760 m.r	SECOND	BEDROOM 3	Negative	1	1	0	0.02
56	5/22/13	mg/cm^2	WALL	DRYWALL	B	INTACT	WHITE	2760 m.r	SECOND	BATHROOM	Negative	1	1	0	0.02
57	5/22/13	mg/cm^2	WALL	DRYWALL	C	INTACT	WHITE	2760 m.r	SECOND	BATHROOM	Negative	1	1	0	0.02
58	5/22/13	mg/cm^2	WALL	DRYWALL	D	INTACT	WHITE	2760 m.r	SECOND	BATHROOM	Negative	1	1	0	0.02
59	5/22/13	mg/cm^2	CEILING	DRYWALL	D	INTACT	WHITE	2760 m.r	SECOND	BATHROOM	Negative	1.31	1	0.01	0.03
60	5/22/13	mg/cm^2	DOOR	WOOD	B	INTACT	WHITE	2760 m.r	SECOND	BATHROOM	Negative	1	1	0	0.02
61	5/22/13	mg/cm^2	DOOR t	WOOD	B	INTACT	WHITE	2760 m.r	SECOND	BATHROOM	Negative	1	1	0	0.02
62	5/22/13	mg/cm^2	WALL	DRYWALL	A	INTACT	WHITE	2756 m.r	FIRST	BATHROOM	Negative	1	1	0	0.02
63	5/22/13	mg/cm^2	WALL	DRYWALL	B	INTACT	WHITE	2756 m.r	FIRST	LIVING ROOM	Negative	4.69	1	0.07	0.14
64	5/22/13	mg/cm^2	WALL	DRYWALL	C	INTACT	WHITE	2756 m.r	FIRST	LIVING ROOM	Negative	2.86	1	0.01	0.03
65	5/22/13	mg/cm^2	WALL	DRYWALL	D	INTACT	WHITE	2756 m.r	FIRST	LIVING ROOM	Negative	7.42	1	0.13	0.13
66	5/22/13	mg/cm^2	CEILING	DRYWALL	A	INTACT	WHITE	2756 m.r	FIRST	LIVING ROOM	Negative	4.31	1	0.03	0.09
67	5/22/13	mg/cm^2	BASEBOARD	WOOD	A	INTACT	WHITE	2756 m.r	FIRST	LIVING ROOM	Negative	8.43	1	0.3	0.63
68	5/22/13	mg/cm^2	WINDOW t	WOOD	A	INTACT	WHITE	2756 m.r	FIRST	LIVING ROOM	Negative	5.31	1	0.05	0.18
69	5/22/13	mg/cm^2	WINDOW s	WOOD	A	INTACT	WHITE	2756 m.r	FIRST	LIVING ROOM	Negative	5.02	1	0.05	0.14
70	5/22/13	mg/cm^2	DOOR	WOOD	C	INTACT	WHITE	2756 m.r	FIRST	LIVING ROOM	Negative	2.52	1	0	0.69
71	5/22/13	mg/cm^2	DOOR j	WOOD	C	INTACT	WHITE	2756 m.r	FIRST	LIVING ROOM	Negative	5.41	1	0.09	0.21
72	5/22/13	mg/cm^2	WALL	DRYWALL	A	INTACT	WHITE	2756 m.r	FIRST	LIVING ROOM	Negative	1.76	1	0.02	0.05
73	5/22/13	mg/cm^2	WALL	DRYWALL	B	INTACT	WHITE	2756 m.r	FIRST	KITCHEN	Negative	1	1	0	0.02
74	5/22/13	mg/cm^2	WALL	DRYWALL	C	INTACT	WHITE	2756 m.r	FIRST	KITCHEN	Negative	1.55	1	0.01	0.02
75	5/22/13	mg/cm^2	WALL	DRYWALL	D	INTACT	WHITE	2756 m.r	FIRST	KITCHEN	Negative	1	1	0	0.02
76	5/22/13	mg/cm^2	CEILING	DRYWALL	A	INTACT	WHITE	2756 m.r	FIRST	KITCHEN	Negative	2.06	1	0	0.02
77	5/22/13	mg/cm^2	BASEBOARD	WOOD	A	INTACT	WHITE	2756 m.r	FIRST	KITCHEN	Negative	1	1	0	0.02
78	5/22/13	mg/cm^2	WINDOW t	WOOD	A	INTACT	WHITE	2756 m.r	FIRST	KITCHEN	Negative	1	1	0	0.02
79	5/22/13	mg/cm^2	WINDOW s	WOOD	A	INTACT	WHITE	2756 m.r	FIRST	KITCHEN	Negative	1	1	0	0.02
80	5/22/13	mg/cm^2	DOOR	WOOD	A	INTACT	WHITE	2756 m.r	FIRST	KITCHEN	Negative	1	1	0	0.02
81	5/22/13	mg/cm^2	DOOR t	WOOD	A	INTACT	WHITE	2756 m.r	FIRST	KITCHEN	Negative	1	1	0	0.02
82	5/22/13	mg/cm^2	WALL	CONCRETE	A	INTACT	WHITE	2756 m.r	BASEMENT	room	Negative	1	1	0	0.02
83	5/22/13	mg/cm^2	WALL	CONCRETE	B	INTACT	WHITE	2756 m.r	BASEMENT	room	Negative	1.26	1	0	0.02
84	5/22/13	mg/cm^2	WALL	CONCRETE	C	INTACT	WHITE	2756 m.r	BASEMENT	room	Negative	1.03	1	0	0.02
85	5/22/13	mg/cm^2	WALL	CONCRETE	D	INTACT	WHITE	2756 m.r	BASEMENT	room	Negative	1	1	0	0.02
86	5/22/13	mg/cm^2	FLOOR	CONCRETE	A	INTACT	WHITE	2756 m.r	BASEMENT	room	Negative	1	1	0	0.02
87	5/22/13	mg/cm^2	TREAD	WOOD	A	INTACT	WHITE	2756 m.r	BASEMENT	room	Negative	3.97	1	0.01	0.03
88	5/22/13	mg/cm^2	RISER	WOOD	A	INTACT	WHITE	2756 m.r	BASEMENT	room	Negative	2.69	1	0.12	0.28
89	5/22/13	mg/cm^2	stringr	WOOD	A	INTACT	WHITE	2756 m.r	BASEMENT	room	Negative	2.07	1	0.14	0.25
90	5/22/13	mg/cm^2	WALL	WOOD	A	INTACT	WHITE	2756 m.r	BASEMENT	room	Negative	1	1	0.04	0.09
91	5/22/13	mg/cm^2	WALL	WOOD	B	INTACT	WHITE	2756 m.r	SECOND	BEDROOM 1	Negative	1.4	1	0	0.03
						INTACT	WHITE	2756 m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.02

92	5/22/13	mg/cm ²	WALL	WOOD	C	INTACT	WHITE	2756 m.r	SECOND	BEDROOM 1	Negative	1.97	1	0.01	0.04
93	5/22/13	mg/cm ²	WALL	WOOD	D	INTACT	WHITE	2756 m.r	SECOND	BEDROOM 1	Negative	1.29	1	0	0.02
94	5/22/13	mg/cm ²	CEILING	DRYWALL	D	INTACT	WHITE	2756 m.r	SECOND	BEDROOM 1	Negative	1.13	1	0.01	0.03
95	5/22/13	mg/cm ²	BASEBOARD	WOOD	A	INTACT	WHITE	2756 m.r	SECOND	BEDROOM 1	Negative	1.45	1	0.01	0.03
96	5/22/13	mg/cm ²	WINDOW t	WOOD	A	INTACT	WHITE	2756 m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.02
97	5/22/13	mg/cm ²	WINDOWS	WOOD	A	INTACT	WHITE	2756 m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.02
98	5/22/13	mg/cm ²	DOOR	WOOD	A	INTACT	WHITE	2756 m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.02
99	5/22/13	mg/cm ²	DOOR j	WOOD	A	INTACT	WHITE	2756 m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.03
100	5/22/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2756 m.r	SECOND	BEDROOM 1	Negative	1.18	1	0.01	0.02
101	5/22/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2756 m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.03
102	5/22/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2756 m.r	SECOND	BEDROOM 2	Negative	5.54	1	0.04	0.12
103	5/22/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2756 m.r	SECOND	BEDROOM 2	Negative	2.56	1	0.01	0.04
104	5/22/13	mg/cm ²	CEILING	DRYWALL	A	INTACT	WHITE	2756 m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.02
105	5/22/13	mg/cm ²	BASEBOARD	WOOD	A	INTACT	BEIGE	2756 m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.02
106	5/22/13	mg/cm ²	WINDOW t	WOOD	A	INTACT	BEIGE	2756 m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.02
107	5/22/13	mg/cm ²	WINDOWS	WOOD	A	INTACT	BEIGE	2756 m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.02
108	5/22/13	mg/cm ²	DOOR	WOOD	B	INTACT	BEIGE	2756 m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.02
109	5/22/13	mg/cm ²	DOOR j	WOOD	B	INTACT	BEIGE	2756 m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.02
110	5/22/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2756 m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.02
111	5/22/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2756 m.r	SECOND	BATHROOM	Negative	1	1	0	0.02
112	5/22/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2756 m.r	SECOND	BATHROOM	Negative	1	1	0	0.02
113	5/22/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2756 m.r	SECOND	BATHROOM	Negative	1.29	1	0	0.02
114	5/22/13	mg/cm ²	DOOR	WOOD	B	INTACT	WHITE	2756 m.r	SECOND	BATHROOM	Negative	1	1	0	0.02
115	5/22/13	mg/cm ²	DOOR t	WOOD	B	INTACT	WHITE	2756 m.r	SECOND	BATHROOM	Negative	1	1	0	0.02
116	5/22/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2756 m.r	SECOND	BATHROOM	Negative	1	1	0	0.02
117	5/22/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2756 m.r	SECOND	BEDROOM 3	Negative	1	1	0	0.02
118	5/22/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2756 m.r	SECOND	BEDROOM 3	Negative	1	1	0	0.02
119	5/22/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2756 m.r	SECOND	BEDROOM 3	Negative	1	1	0	0.02
120	5/22/13	mg/cm ²	CEILING	DRYWALL	D	INTACT	WHITE	2756 m.r	SECOND	BEDROOM 3	Negative	1	1	0	0.02
121	5/22/13	mg/cm ²	BASEBOARD	WOOD	A	INTACT	WHITE	2756 m.r	SECOND	BEDROOM 3	Negative	1	1	0	0.02
122	5/22/13	mg/cm ²	WINDOW t	WOOD	A	INTACT	WHITE	2756 m.r	SECOND	BEDROOM 3	Negative	1	1	0	0.02
123	5/22/13	mg/cm ²	WINDOWS	WOOD	A	INTACT	WHITE	2756 m.r	SECOND	BEDROOM 3	Negative	1	1	0	0.02
124	5/22/13	mg/cm ²	DOOR	WOOD	A	INTACT	WHITE	2756 m.r	SECOND	BEDROOM 3	Negative	1	1	0	0.02
125	5/22/13	mg/cm ²	CAL								Positive	1.08	1	1	0.1
126	5/22/13	mg/cm ²	CAL								Negative	1	1	0.9	0.1
127	5/22/13	mg/cm ²	CAL								Positive	1.05	1	1	0.1
128	5/22/13	mg/cm ²	DOOR j	WOOD	A	INTACT	WHITE	2756 m.r	SECOND	BEDROOM 3	Negative	1	1	0.01	0.02
129	5/22/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2750 m.r	FIRST	KITCHEN	Negative	1.24	1	0.01	0.02
130	5/22/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2750 m.r	FIRST	KITCHEN	Negative	2	1	0	0.03
131	5/22/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2750 m.r	FIRST	KITCHEN	Negative	1	1	0	0.02
132	5/22/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2750 m.r	FIRST	KITCHEN	Negative	2.6	1	0.01	0.03
133	5/22/13	mg/cm ²	CEILING	DRYWALL	A	INTACT	WHITE	2750 m.r	FIRST	KITCHEN	Negative	1	1	0	0.02
134	5/22/13	mg/cm ²	BASEBOARD	WOOD	A	INTACT	WHITE	2750 m.r	FIRST	KITCHEN	Negative	1	1	0	0.02
135	5/22/13	mg/cm ²	DOOR	WOOD	A	INTACT	WHITE	2750 m.r	FIRST	KITCHEN	Negative	1	1	0.16	0.18
136	5/22/13	mg/cm ²	DOOR j	WOOD	A	INTACT	WHITE	2750 m.r	FIRST	KITCHEN	Negative	1	1	0	0.02
137	5/22/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2750 m.r	FIRST	LIVING ROOM	Negative	1	1	0	0.02

138	5/22/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2750 m.r	FIRST	LIVING ROOM	Negative	1	1	0	0.02
139	5/22/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2750 m.r	FIRST	LIVING ROOM	Negative	7.74	1	0.03	0.11
140	5/22/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2750 m.r	FIRST	LIVING ROOM	Negative	1	1	0	0.02
141	5/22/13	mg/cm ²	CEILING	DRYWALL	D	INTACT	WHITE	2750 m.r	FIRST	LIVING ROOM	Negative	1	1	0	0.02
142	5/22/13	mg/cm ²	BASEBOARD	WOOD	A	INTACT	WHITE	2750 m.r	FIRST	LIVING ROOM	Negative	1	1	0	0.02
143	5/22/13	mg/cm ²	WINDOW t	WOOD	A	INTACT	WHITE	2750 m.r	FIRST	LIVING ROOM	Negative	1.58	1	0.01	0.04
144	5/22/13	mg/cm ²	WINDOW s	WOOD	A	INTACT	WHITE	2750 m.r	FIRST	LIVING ROOM	Negative	1	1	0	0.02
145	5/22/13	mg/cm ²	WALL	CONCRETE	A	INTACT	WHITE	2750 m.r	BASEMENT	room	Negative	1	1	0	0.02
146	5/22/13	mg/cm ²	WALL	CONCRETE	B	INTACT	WHITE	2750 m.r	BASEMENT	room	Negative	1.25	1	0	0.02
147	5/22/13	mg/cm ²	WALL	CONCRETE	C	INTACT	WHITE	2750 m.r	BASEMENT	room	Negative	1	1	0	0.02
148	5/22/13	mg/cm ²	WALL	CONCRETE	D	INTACT	WHITE	2750 m.r	BASEMENT	room	Negative	1.06	1	0	0.02
149	5/22/13	mg/cm ²	FLOOR	CONCRETE	D	INTACT	WHITE	2750 m.r	BASEMENT	room	Negative	1	1	0	0.02
150	5/22/13	mg/cm ²	TREAD	WOOD	A	INTACT	WHITE	2750 m.r	BASEMENT	STAIR	Negative	5.35	1	0.25	0.36
151	5/22/13	mg/cm ²	RISER	WOOD	A	INTACT	WHITE	2750 m.r	BASEMENT	STAIR	Negative	1.32	1	0.09	0.15
152	5/22/13	mg/cm ²	stringer	WOOD	A	INTACT	WHITE	2750 m.r	BASEMENT	STAIR	Negative	1	1	0.06	0.1
153	5/22/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2750 m.r	SECOND	BEDROOM 1	Negative	3.65	1	0.02	0.08
154	5/22/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2750 m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.02
155	5/22/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2750 m.r	SECOND	BEDROOM 1	Negative	3.26	1	0.01	0.03
156	5/22/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2750 m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.02
157	5/22/13	mg/cm ²	CEILING	DRYWALL	D	INTACT	WHITE	2750 m.r	SECOND	BEDROOM 1	Negative	1.71	1	0	0.02
158	5/22/13	mg/cm ²	WINDOW t	DRYWALL	D	INTACT	WHITE	2750 m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.02
159	5/22/13	mg/cm ²	WINDOW s	DRYWALL	D	INTACT	WHITE	2750 m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.02
160	5/22/13	mg/cm ²	DOOR	WOOD	A	INTACT	WHITE	2750 m.r	SECOND	BEDROOM 1	Negative	5.71	1	0.03	0.15
161	5/22/13	mg/cm ²	DOOR t	WOOD	A	INTACT	WHITE	2750 m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.02
162	5/22/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2750 m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.03
163	5/22/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2750 m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.03
164	5/22/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2750 m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.02
165	5/22/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2750 m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.02
166	5/22/13	mg/cm ²	CEILING	DRYWALL	A	INTACT	WHITE	2750 m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.02
167	5/22/13	mg/cm ²	BASEBOARD	DRYWALL	A	INTACT	WHITE	2750 m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.02
168	5/22/13	mg/cm ²	DOOR	WOOD	B	INTACT	WHITE	2750 m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.03
169	5/22/13	mg/cm ²	DOOR t	WOOD	B	INTACT	WHITE	2750 m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.03
170	5/22/13	mg/cm ²	WALL	WOOD	A	INTACT	WHITE	2750 m.r	SECOND	BEDROOM 2	Negative	1	1	0.01	0.03
171	5/22/13	mg/cm ²	WALL	WOOD	B	INTACT	WHITE	2750 m.r	SECOND	BEDROOM 3	Negative	1	1	0	0.02
172	5/22/13	mg/cm ²	WALL	WOOD	C	INTACT	WHITE	2750 m.r	SECOND	BEDROOM 3	Negative	1.28	1	0.01	0.03
173	5/22/13	mg/cm ²	WALL	WOOD	D	INTACT	WHITE	2750 m.r	SECOND	BEDROOM 3	Negative	2.82	1	0.01	0.04
174	5/22/13	mg/cm ²	CEILING	WOOD	A	INTACT	WHITE	2750 m.r	SECOND	BEDROOM 3	Negative	1	1	0	0.02
175	5/22/13	mg/cm ²	WINDOW t	WOOD	C	INTACT	WHITE	2750 m.r	SECOND	BEDROOM 3	Negative	3.56	1	0.02	0.08
176	5/22/13	mg/cm ²	WINDOW s	WOOD	C	INTACT	WHITE	2750 m.r	SECOND	BEDROOM 3	Negative	1	1	0	0.02
177	5/22/13	mg/cm ²	DOOR	WOOD	A	INTACT	WHITE	2750 m.r	SECOND	BEDROOM 3	Negative	1	1	0	0.02
178	5/22/13	mg/cm ²	DOOR t	WOOD	A	INTACT	WHITE	2750 m.r	SECOND	BEDROOM 3	Negative	1	1	0	0.03
179	5/22/13	mg/cm ²	WALL	DRYWALL	A	INTACT	YELLOW	2750 m.r	SECOND	BEDROOM 3	Negative	1	1	0	0.03
180	5/22/13	mg/cm ²	WALL	DRYWALL	B	INTACT	YELLOW	2750 m.r	SECOND	BATHROOM	Negative	1	1	0	0.02
181	5/22/13	mg/cm ²	WALL	DRYWALL	C	INTACT	YELLOW	2750 m.r	SECOND	BATHROOM	Negative	1	1	0	0.02
182	5/22/13	mg/cm ²	WALL	DRYWALL	D	INTACT	YELLOW	2750 m.r	SECOND	BATHROOM	Negative	1	1	0	0.02
183	5/22/13	mg/cm ²	DOOR	WOOD	B	INTACT	WHITE	2750 m.r	SECOND	BATHROOM	Negative	1.08	1	0	0.02
												1	1	0	0.02

184	5/22/13	mg/cm ²	DOOR t	WOOD	B	INTACT	WHITE	2750 m.r	SECOND	BATHROOM	Negative	1	1	0	0.02
185	5/22/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2750 m.r	SECOND	STAIR	Negative	1.44	1	0	0.03
186	5/22/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2750 m.r	SECOND	STAIR	Negative	1.97	1	0.01	0.03
187	5/22/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2750 m.r	SECOND	STAIR	Negative	1	1	0	0.02
188	5/22/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2750 m.r	SECOND	STAIR	Negative	1.09	1	0	0.02
189	5/22/13	mg/cm ²	RISER	WOOD	B	INTACT	YELLOW	2750 m.r	SECOND	STAIR	Negative	1	1	0	0.02
190	5/22/13	mg/cm ²	TREAD	WOOD	B	INTACT	YELLOW	2750 m.r	SECOND	STAIR	Negative	1	1	0	0.02
191	5/22/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2752 m.r	FIRST	KITCHEN	Negative	1	1	0	0.02
192	5/22/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2752 m.r	FIRST	KITCHEN	Negative	2.29	1	0.01	0.04
193	5/22/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2752 m.r	FIRST	KITCHEN	Negative	1	1	0	0.02
194	5/22/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2752 m.r	FIRST	KITCHEN	Negative	5.17	1	0.04	0.13
195	5/22/13	mg/cm ²	CEILING	DRYWALL	D	INTACT	WHITE	2752 m.r	FIRST	KITCHEN	Negative	1	1	0	0.02
196	5/22/13	mg/cm ²	BASEBOARD	WOOD	A	INTACT	WHITE	2752 m.r	FIRST	KITCHEN	Negative	1	1	0	0.02
197	5/22/13	mg/cm ²	DOOR	WOOD	A	INTACT	WHITE	2752 m.r	FIRST	KITCHEN	Negative	1.8	1	0.1	0.14
198	5/22/13	mg/cm ²	DOOR t	WOOD	A	INTACT	WHITE	2752 m.r	FIRST	KITCHEN	Negative	1	1	0	0.02
199	5/22/13	mg/cm ²	WINDOW t	WOOD	A	INTACT	WHITE	2752 m.r	FIRST	KITCHEN	Negative	1	1	0	0.02
200	5/22/13	mg/cm ²	WINDOW s	WOOD	A	INTACT	WHITE	2752 m.r	FIRST	KITCHEN	Negative	1	1	0	0.02
201	5/22/13	mg/cm ²	DOOR	DRYWALL	A	INTACT	WHITE	2752 m.r	FIRST	KITCHEN	Negative	5.78	1	0.04	0.22
202	5/22/13	mg/cm ²	DOOR	DRYWALL	B	INTACT	WHITE	2752 m.r	FIRST	LIVING ROOM	Negative	4.62	1	0.02	0.09
203	5/22/13	mg/cm ²	DOOR	DRYWALL	C	INTACT	WHITE	2752 m.r	FIRST	LIVING ROOM	Negative	1.84	1	0	0.02
204	5/22/13	mg/cm ²	DOOR	DRYWALL	D	INTACT	WHITE	2752 m.r	FIRST	LIVING ROOM	Negative	3.48	1	0.02	0.06
205	5/22/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2752 m.r	FIRST	LIVING ROOM	Negative	1.09	1	0	0.02
206	5/22/13	mg/cm ²	CEILING	DRYWALL	D	INTACT	WHITE	2752 m.r	FIRST	LIVING ROOM	Negative	1	1	0	0.02
207	5/22/13	mg/cm ²	DOOR	WOOD	C	INTACT	WHITE	2752 m.r	FIRST	LIVING ROOM	Negative	1.19	1	0.01	0.03
208	5/22/13	mg/cm ²	DOOR t	WOOD	C	INTACT	WHITE	2752 m.r	FIRST	LIVING ROOM	Negative	3.91	1	0.24	0.35
209	5/22/13	mg/cm ²	WINDOW t	WOOD	C	INTACT	WHITE	2752 m.r	FIRST	LIVING ROOM	Negative	1	1	0	0.02
210	5/22/13	mg/cm ²	WINDOW s	WOOD	C	INTACT	WHITE	2752 m.r	FIRST	LIVING ROOM	Negative	2.58	1	0.01	0.09
211	5/22/13	mg/cm ²	DOOR	WOOD	C	INTACT	WHITE	2752 m.r	FIRST	LIVING ROOM	Negative	4.6	1	0.28	0.41
212	5/22/13	mg/cm ²	DOOR t	WOOD	C	INTACT	WHITE	2752 m.r	FIRST	LIVING ROOM	Negative	1	1	0	0.02
213	5/22/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2752 m.r	BASEMENT	room	Negative	1	1	0	0.02
214	5/22/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2752 m.r	BASEMENT	room	Negative	1	1	0	0.02
215	5/22/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2752 m.r	BASEMENT	room	Negative	1	1	0	0.02
216	5/22/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2752 m.r	BASEMENT	room	Negative	1	1	0	0.02
217	5/22/13	mg/cm ²	TREAD	WOOD	D	INTACT	WHITE	2752 m.r	BASEMENT	room	Negative	1	1	0	0.02
218	5/22/13	mg/cm ²	RISER	WOOD	D	INTACT	WHITE	2752 m.r	BASEMENT	room	Negative	1	1	0.03	0.08
219	5/22/13	mg/cm ²	stringer	WOOD	D	INTACT	WHITE	2752 m.r	BASEMENT	room	Negative	1	1	0.03	0.07
220	5/22/13	mg/cm ²	WALL	CONCRETE	A	INTACT	WHITE	2752 m.r	BASEMENT	room	Negative	1.78	1	0.07	0.16
221	5/22/13	mg/cm ²	WALL	CONCRETE	B	INTACT	WHITE	2752 m.r	BASEMENT	room	Negative	3.51	1	0.01	0.02
222	5/22/13	mg/cm ²	WALL	CONCRETE	C	INTACT	WHITE	2752 m.r	BASEMENT	room	Negative	1	1	0	0.02
223	5/22/13	mg/cm ²	WALL	CONCRETE	D	INTACT	WHITE	2752 m.r	BASEMENT	room	Negative	7.15	1	0.02	0.04
224	5/22/13	mg/cm ²	FLOOR	CONCRETE	A	INTACT	WHITE	2752 m.r	BASEMENT	room	Negative	1.95	1	0	0.02
225	5/22/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2752 m.r	BASEMENT	room	Negative	4.28	1	0	0.02
226	5/22/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2752 m.r	SECOND	BEDROOM 1	Negative	1	1	0.03	0.1
227	5/22/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2752 m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.02
228	5/22/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2752 m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.02
229	5/22/13	mg/cm ²	CEILING	DRYWALL	D	INTACT	WHITE	2752 m.r	SECOND	BEDROOM 1	Negative	1.26	1	0	0.02
											Negative	1	1	0	0.02

230	5/22/13	mg/cm ²	BASEBOARD	WOOD	A	INTACT	WHITE	2752 m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.02
231	5/22/13	mg/cm ²	WINDOW t	WOOD	A	INTACT	WHITE	2752 m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.03
232	5/22/13	mg/cm ²	WINDOW s	WOOD	A	INTACT	WHITE	2752 m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.02
233	5/22/13	mg/cm ²	DOOR	WOOD	C	INTACT	WHITE	2752 m.r	SECOND	BEDROOM 1	Negative	1	1	0	0.03
234	5/22/13	mg/cm ²	DOOR t	WOOD	C	INTACT	WHITE	2752 m.r	SECOND	BEDROOM 1	Negative	2.03	1	0.01	0.06
235	5/22/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2752 m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.02
236	5/22/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2752 m.r	SECOND	BEDROOM 2	Negative	1.94	1	0.01	0.04
237	5/22/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2752 m.r	SECOND	BEDROOM 2	Negative	1.9	1	0.01	0.05
238	5/22/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2752 m.r	SECOND	BEDROOM 2	Negative	3.29	1	0.02	0.07
239	5/22/13	mg/cm ²	BASEBOARD	WOOD	A	INTACT	WHITE	2752 m.r	SECOND	BEDROOM 2	Negative	1.54	1	0.01	0.04
240	5/22/13	mg/cm ²	WINDOW t	WOOD	A	INTACT	WHITE	2752 m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.03
241	5/22/13	mg/cm ²	WINDOW s	WOOD	A	INTACT	WHITE	2752 m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.02
242	5/22/13	mg/cm ²	DOOR	WOOD	A	INTACT	WHITE	2752 m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.03
243	5/22/13	mg/cm ²	DOOR j	WOOD	A	INTACT	WHITE	2752 m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.02
244	5/22/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2752 m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.03
245	5/22/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2752 m.r	SECOND	BEDROOM 2	Negative	1	1	0	0.03
246	5/22/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2752 m.r	SECOND	BATHROOM	Negative	6.29	1	0.05	0.18
247	5/22/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2752 m.r	SECOND	BATHROOM	Negative	1.12	1	0	0.02
248	5/22/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2752 m.r	SECOND	BATHROOM	Negative	2.06	1	0.01	0.06
249	5/22/13	mg/cm ²	CEILING	DRYWALL	D	INTACT	WHITE	2752 m.r	SECOND	BATHROOM	Negative	1	1	0	0.02
250	5/22/13	mg/cm ²	TRIM	WOOD	A	INTACT	WHITE	2752 m.r	SECOND	BATHROOM	Negative	1	1	0	0.02
251	5/22/13	mg/cm ²	DOOR	WOOD	A	INTACT	WHITE	2752 m.r	SECOND	BATHROOM	Negative	1	1	0	0.02
252	5/22/13	mg/cm ²	DOOR t	WOOD	A	INTACT	WHITE	2752 m.r	SECOND	BATHROOM	Negative	1	1	0	0.02
253	5/22/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2752 m.r	SECOND	BATHROOM	Negative	1	1	0	0.02
254	5/22/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2752 m.r	SECOND	BATHROOM	Negative	1	1	0	0.02
255	5/22/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2752 m.r	SECOND	BATHROOM	Negative	1	1	0.01	0.03
256	5/22/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2752 m.r	SECOND	BATHROOM	Negative	1.4	1	0	0.04
257	5/22/13	mg/cm ²	CEILING	DRYWALL	A	INTACT	WHITE	2752 m.r	SECOND	BATHROOM	Negative	1	1	0	0.02
258	5/22/13	mg/cm ²	TREAD	WOOD	A	INTACT	WHITE	2754 m.r	FIRST	STAIR	Negative	2.08	1	0.01	0.03
259	5/22/13	mg/cm ²	RISER	WOOD	A	INTACT	WHITE	2754 m.r	FIRST	STAIR	Negative	1	1	0	0.02
260	5/22/13	mg/cm ²	stringer	WOOD	A	INTACT	WHITE	2754 m.r	FIRST	STAIR	Negative	1	1	0	0.02
261	5/22/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2754 m.r	FIRST	STAIR	Negative	1	1	0	0.02
262	5/22/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2754 m.r	FIRST	KITCHEN	Negative	1	1	0	0.02
263	5/22/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2754 m.r	FIRST	KITCHEN	Negative	1	1	0	0.02
264	5/22/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2754 m.r	FIRST	KITCHEN	Negative	1.36	1	0	0.02
265	5/22/13	mg/cm ²	CEILING	DRYWALL	A	INTACT	WHITE	2754 m.r	FIRST	KITCHEN	Negative	1.36	1	0	0.02
266	5/22/13	mg/cm ²	BASEBOARD	WOOD	A	INTACT	WHITE	2754 m.r	FIRST	KITCHEN	Negative	1	1	0	0.02
267	5/22/13	mg/cm ²	DOOR	WOOD	A	INTACT	WHITE	2754 m.r	FIRST	KITCHEN	Negative	1.1	1	0	0.02
268	5/22/13	mg/cm ²	DOOR j	WOOD	A	INTACT	WHITE	2754 m.r	FIRST	KITCHEN	Negative	1.42	1	0.22	0.19
269	5/22/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2754 m.r	FIRST	LIVING ROOM	Negative	1	1	0	0.02
270	5/22/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2754 m.r	FIRST	LIVING ROOM	Negative	1	1	0	0.02
271	5/22/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2754 m.r	FIRST	LIVING ROOM	Negative	1	1	0	0.02
272	5/22/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2754 m.r	FIRST	LIVING ROOM	Negative	1	1	0	0.02
273	5/22/13	mg/cm ²	CEILING	DRYWALL	D	INTACT	WHITE	2754 m.r	FIRST	LIVING ROOM	Negative	1.75	1	0.01	0.03
274	5/22/13	mg/cm ²	BASEBOARD	WOOD	A	INTACT	WHITE	2754 m.r	FIRST	LIVING ROOM	Negative	1	1	0	0.02
275	5/22/13	mg/cm ²	WINDOW t	WOOD	A	INTACT	WHITE	2754 m.r	FIRST	LIVING ROOM	Negative	1	1	0	0.02
												2.31	1	0.01	0.06

276	5/22/13	mg/cm ²	WINDOW s	WOOD	A	INTACT	WHITE	2754 m.r	FIRST	LIVING ROOM	Negative	1	1	0	0.02
277	5/22/13	mg/cm ²	DOOR	WOOD	C	INTACT	WHITE	2754 m.r	FIRST	LIVING ROOM	Negative	1.44	1	0.12	0.13
278	5/22/13	mg/cm ²	DOOR t	WOOD	C	INTACT	WHITE	2754 m.r	FIRST	LIVING ROOM	Negative	1.38	1	0	0.04
279	5/22/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2754 m.r	FIRST	BEDROOM	Negative	1	1	0	0.02
280	5/22/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2754 m.r	FIRST	BEDROOM	Negative	2.65	1	0.01	0.04
281	5/22/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2754 m.r	FIRST	BEDROOM	Negative	1	1	0	0.02
282	5/22/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2754 m.r	FIRST	BEDROOM	Negative	1	1	0	0.02
283	5/22/13	mg/cm ²	CEILING	DRYWALL	D	INTACT	WHITE	2754 m.r	FIRST	BEDROOM	Negative	1	1	0	0.02
284	5/22/13	mg/cm ²	TRIM	WOOD	D	INTACT	WHITE	2754 m.r	FIRST	BEDROOM	Negative	1	1	0	0.02
285	5/22/13	mg/cm ²	DOOR	WOOD	A	INTACT	WHITE	2754 m.r	FIRST	BEDROOM	Negative	1	1	0	0.02
286	5/22/13	mg/cm ²	DOOR t	WOOD	A	INTACT	WHITE	2754 m.r	FIRST	BEDROOM	Negative	1	1	0	0.03
287	5/22/13	mg/cm ²	WALL	CONCRETE	A	INTACT	WHITE	2754 m.r	FIRST	BEDROOM	Negative	2.28	1	0.02	0.03
288	5/22/13	mg/cm ²	WALL	CONCRETE	B	INTACT	WHITE	2754 m.r	BASEMENT	room	Negative	1.13	1	0	0.07
289	5/22/13	mg/cm ²	WALL	CONCRETE	C	INTACT	WHITE	2754 m.r	BASEMENT	room	Negative	1	1	0	0.02
290	5/22/13	mg/cm ²	WALL	CONCRETE	D	INTACT	WHITE	2754 m.r	BASEMENT	room	Negative	1	1	0	0.02
291	5/22/13	mg/cm ²	FLOOR	CONCRETE	A	INTACT	WHITE	2754 m.r	BASEMENT	room	Negative	2.26	1	0.01	0.02
292	5/22/13	mg/cm ²	TREAD	WOOD	A	INTACT	WHITE	2754 m.r	BASEMENT	room	Negative	1	1	0	0.02
293	5/22/13	mg/cm ²	RISER	WOOD	A	INTACT	BLUE	2754 m.r	BASEMENT	room	Negative	1	1	0	0.02
294	5/22/13	mg/cm ²	stringer	WOOD	A	INTACT	BLUE	2754 m.r	BASEMENT	room	Negative	1.86	1	0.06	0.15
295	5/22/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2754 m.r	FIRST	STAIR	Negative	1.29	1	0.04	0.11
296	5/22/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2754 m.r	FIRST	STAIR	Negative	1.05	1	0	0.02
297	5/22/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2754 m.r	FIRST	STAIR	Negative	1	1	0	0.02
298	5/22/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2754 m.r	FIRST	STAIR	Negative	2.7	1	0.01	0.04
299	5/22/13	mg/cm ²	CEILING	DRYWALL	D	INTACT	WHITE	2754 m.r	FIRST	STAIR	Negative	3.53	1	0.03	0.1
300	5/22/13	mg/cm ²	TREAD	WOOD	A	INTACT	WHITE	2754 m.r	FIRST	STAIR	Negative	1.7	1	0.01	0.03
301	5/22/13	mg/cm ²	RISER	WOOD	A	INTACT	WHITE	2754 m.r	FIRST	STAIR	Negative	1	1	0	0.02
302	5/22/13	mg/cm ²	stringer	WOOD	A	INTACT	WHITE	2754 m.r	FIRST	STAIR	Negative	3.91	1	0.02	0.11
303	5/22/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2754 m.r	FIRST	STAIR	Negative	1	1	0	0.03
304	5/22/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2754 m.r	FIRST	BEDROOM 1	Negative	1	1	0	0.02
305	5/22/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2754 m.r	FIRST	BEDROOM 1	Negative	1	1	0	0.02
306	5/22/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2754 m.r	FIRST	BEDROOM 1	Negative	1	1	0	0.02
307	5/22/13	mg/cm ²	CEILING	DRYWALL	A	INTACT	WHITE	2754 m.r	FIRST	BEDROOM 1	Negative	1	1	0	0.02
308	5/22/13	mg/cm ²	BASEBOARD	WOOD	A	INTACT	WHITE	2754 m.r	FIRST	BEDROOM 1	Negative	1	1	0	0.02
309	5/22/13	mg/cm ²	WINDOW t	WOOD	A	INTACT	WHITE	2754 m.r	FIRST	BEDROOM 1	Negative	1	1	0	0.02
310	5/22/13	mg/cm ²	WINDOW s	WOOD	A	INTACT	WHITE	2754 m.r	FIRST	BEDROOM 1	Negative	1	1	0	0.02
311	5/22/13	mg/cm ²	DOOR	WOOD	A	INTACT	WHITE	2754 m.r	FIRST	BEDROOM 1	Negative	1	1	0	0.03
312	5/22/13	mg/cm ²	DOOR t	WOOD	A	INTACT	WHITE	2754 m.r	FIRST	BEDROOM 1	Negative	1	1	0	0.02
313	5/22/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2754 m.r	FIRST	BEDROOM 1	Negative	1	1	0	0.02
314	5/22/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2754 m.r	FIRST	BEDROOM 2	Negative	1	1	0	0.02
315	5/22/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2754 m.r	FIRST	BEDROOM 2	Negative	1	1	0	0.02
316	5/22/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2754 m.r	FIRST	BEDROOM 2	Negative	1	1	0	0.02
317	5/22/13	mg/cm ²	BASEBOARD	WOOD	A	INTACT	WHITE	2754 m.r	FIRST	BEDROOM 2	Negative	1	1	0	0.02
318	5/22/13	mg/cm ²	WINDOW t	WOOD	A	INTACT	WHITE	2754 m.r	FIRST	BEDROOM 2	Negative	1	1	0	0.02
319	5/22/13	mg/cm ²	WINDOW s	WOOD	A	INTACT	WHITE	2754 m.r	FIRST	BEDROOM 2	Negative	1	1	0	0.02
320	5/22/13	mg/cm ²	DOOR	WOOD	A	INTACT	WHITE	2754 m.r	FIRST	BEDROOM 2	Negative	1.98	1	0	0.04
321	5/22/13	mg/cm ²	DOOR t	WOOD	A	INTACT	WHITE	2754 m.r	FIRST	BEDROOM 2	Negative	1.14	1	0	0.04
322	5/22/13	mg/cm ²	DOOR t	WOOD	A	INTACT	WHITE	2754 m.r	FIRST	BEDROOM 2	Negative	1	1	0	0.02

322	5/22/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2754 m.r	FIRST	BATHROOM	Negative	1	1	0	0.02
323	5/22/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2754 m.r	FIRST	BATHROOM	Negative	5.05	1	0.03	0.13
324	5/22/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2754 m.r	FIRST	BATHROOM	Negative	1	1	0	0.02
325	5/22/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2754 m.r	FIRST	BATHROOM	Negative	1	1	0	0.02
326	5/22/13	mg/cm ²	TRIM	WOOD	A	INTACT	WHITE	2754 m.r	FIRST	BATHROOM	Negative	1	1	0	0.02
327	5/22/13	mg/cm ²	DOOR	WOOD	D	INTACT	WHITE	2754 m.r	FIRST	BATHROOM	Negative	1	1	0	0.02
328	5/22/13	mg/cm ²	DOOR t	WOOD	D	INTACT	WHITE	2754 m.r	FIRST	BATHROOM	Negative	1	1	0	0.02
329	5/22/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2754 m.r	FIRST	BEDROOM 3	Negative	1	1	0	0.02
330	5/22/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2754 m.r	FIRST	BEDROOM 3	Negative	3.06	1	0.01	0.05
331	5/22/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2754 m.r	FIRST	BEDROOM 3	Negative	1.14	1	0	0.02
332	5/22/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2754 m.r	FIRST	BEDROOM 3	Negative	1.65	1	0.01	0.03
333	5/22/13	mg/cm ²	CEILING	DRYWALL	D	INTACT	WHITE	2754 m.r	FIRST	BEDROOM 3	Negative	1	1	0	0.02
334	5/22/13	mg/cm ²	BASEBOARD	WOOD	A	INTACT	WHITE	2754 m.r	FIRST	BEDROOM 3	Negative	1	1	0	0.02
335	5/22/13	mg/cm ²	WINDOW t	WOOD	A	INTACT	WHITE	2754 m.r	FIRST	BEDROOM 3	Negative	1	1	0	0.02
336	5/22/13	mg/cm ²	WINDOW s	WOOD	A	INTACT	WHITE	2754 m.r	FIRST	BEDROOM 3	Negative	1	1	0	0.02
337	5/22/13	mg/cm ²	WALL	DRYWALL	A	INTACT	WHITE	2754 m.r	FIRST	BEDROOM 3	Negative	1	1	0	0.02
338	5/22/13	mg/cm ²	WALL	DRYWALL	B	INTACT	WHITE	2754 m.r	FIRST	BEDROOM 4	Negative	2.92	1	0.01	0.05
339	5/22/13	mg/cm ²	WALL	DRYWALL	C	INTACT	WHITE	2754 m.r	FIRST	BEDROOM 4	Negative	1	1	0	0.02
340	5/22/13	mg/cm ²	WALL	DRYWALL	D	INTACT	WHITE	2754 m.r	FIRST	BEDROOM 4	Negative	1	1	0	0.02
341	5/22/13	mg/cm ²	CEILING	DRYWALL	D	INTACT	WHITE	2754 m.r	FIRST	BEDROOM 4	Negative	1	1	0	0.02
342	5/22/13	mg/cm ²	BASEBOARD	WOOD	D	INTACT	WHITE	2754 m.r	FIRST	BEDROOM 4	Negative	1	1	0	0.02
343	5/22/13	mg/cm ²	DOOR	WOOD	A	INTACT	WHITE	2754 m.r	FIRST	BEDROOM 4	Negative	1	1	0	0.02

APPENDIX D

PAINT CHIP LABORATORY RESULTS

NO PAINT CHIP SAMPLES TAKEN

APPENDIX E

OTHER SAMPLE LABORATORY RESULTS



12950 Haggerty Road
 Belleville, MI 48111
 Ph: (734) 699-labs; Fax: (734) 699-8407

Certificate of Analysis: Lead In Dust Wipe by NIOSH Method 7082

Client : American Environmental Consultants, LLC
 12838 Gavel
 Detroit, MI 48232

Attn : Jeff Fox
Phone : 313-491-2600

Email : jfox@aecmi.net
Fax : 313-491-2601

AAT Project : 154925
Sampling Date : 05/20/2013
Date Received : 06/04/2013
Date Analyzed : 06/07/2013
Date Reported : 06/10/2013
Analyst : Nathan Ditty

Project Location : 2706 HIKONE
Client Project : 2706 HIKONE

Lab Sample ID	Client Code	Sample Description	Length (inch)	Width (inch)	Area (Sq ft)	Results Lead $\mu\text{g}/\text{ft}^2$ *
1549630	1	L FL	12	12	1.00	<10.00
1549631	2	L WS	4	24	0.67	<15.00
1549632	3	K FL	12	12	1.00	<10.00
1549633	4	K WT	4	24	0.67	<15.00
1549634	5	B1 FL	12	12	1.00	<10.00
1549635	6	B1 WS	4	24	0.67	<15.00
1549636	7	B2 FL	12	12	1.00	<10.00
1549637	8	B2 WT	4	24	0.67	<15.00
1549638	9	B3 FL	12	12	1.00	<10.00
1549639	10	B3 WS	4	24	0.67	<15.00
1549640	11	BATH FL	12	12	1.00	<10.00
1549641	12	BASE FL	12	12	1.00	<10.00
1549642	FB	FIELD BLANK	N/A	N/A	N/A	N/D

Nathan Ditty
 Analyst Signature

(ND=Not Detected, N/A Not Available, RL Reporting Limit, Analytical Reporting Limit is 10 ug/sample) * For true values assume (2) significant figures. The method and batch QC is acceptable unless otherwise stated. EPA HUD Regulatory Limits: 40 ug/ft2 (Floors Carpeted/uncarpeted), 250ug/ft2 (Window Sill/Stools), 400 ug/ft2 (Window Trough /Well/Ext Concrete Surfaces) The laboratory operates in accord with ISO 17025 guidelines and holds limited scopes of accreditation under AIHA and NY State DOH ELAP programs. These results are submitted pursuant to AAT LLC current terms and conditions of sale, including the company's standard warranty and limitation of liability provisions. Analytical results relate to the samples as



AIHA ELLAP- Lab ID #100986, NY State DOH ELAP -Lab ID #11864, State of Ohio- Lab ID # 10042

Date Printed: 06/10/2013 7:35AM

AAT Project: 154925

To : American Environmental Consultants, LLC
 12838 Gavel
 Detroit, MI 48232

Attn : Jeff Fox

Email : jfox@aecmi.net
Phone : 313-491-2600

AAT Project : 154925
Client Project : 2706 HIKONE
Date Reported : 06/10/2013

Project Location : 2706 HIKONE

Sample	Client Code	Analysis Requested	Completed
1549630	1	Dust Wipe	06/07/2013
1549631	2	Dust Wipe	06/07/2013
1549632	3	Dust Wipe	06/07/2013
1549633	4	Dust Wipe	06/07/2013
1549634	5	Dust Wipe	06/07/2013
1549635	6	Dust Wipe	06/07/2013
1549636	7	Dust Wipe	06/07/2013
1549637	8	Dust Wipe	06/07/2013
1549638	9	Dust Wipe	06/07/2013
1549639	10	Dust Wipe	06/07/2013
1549640	11	Dust Wipe	06/07/2013
1549641	12	Dust Wipe	06/07/2013
1549642	FB	Dust Wipe	06/07/2013



Reviewed By

Quality Assurance Coordinator - Robert A Theys

This report is intended for use solely by the individual or entity to which it is addressed. It may contain information that is privileged, confidential and otherwise exempt by law from disclosure. If the reader of this information is not the intended recipient or an employee of its intended recipient, you are herewith notified that any dissemination, distribution or copying of this information is strictly prohibited. If you have received this information in error, please notify AAT immediately. Thank you.

AIHA ELLAP- Lab ID #100986, NY State DOH ELAP -Lab ID #11864, State of Ohio- Lab ID # 10042



Date Printed: 06/10/2013 7:35AM

AAT Project: 154925



12950 Haggerty Road
 Belleville, MI 48111
 Ph: (734) 699-labs; Fax: (734) 699-8407

Certificate of Analysis: Lead In Dust Wipe by NIOSH Method 7082

Client : American Environmental Consultants, LLC
 12838 Gavel
 Detroit, MI 48232

Attn : Jeff Fox
Phone : 313-491-2600

Email : jfox@aecmi.net
Fax : 313-491-2601

AAT Project : 154914
Sampling Date : 05/20/2013
Date Received : 06/04/2013
Date Analyzed : 06/07/2013
Date Reported : 06/10/2013
Analyst : Nathan Ditty

Project Location : 2708 Hikone
Client Project : 2708 Hikone

Lab Sample ID	Client Code	Sample Description	Length (inch)	Width (inch)	Area (Sq ft)	Results Lead µg/ft2 *
1549517	1	L FL	12	12	1.00	<10.00
1549518	2	L WS	4	24	0.67	<15.00
1549519	3	K FL	12	12	1.00	<10.00
1549520	4	K WT	4	24	0.67	<15.00
1549521	5	B1 FL	12	12	1.00	<10.00
1549522	6	B1 WS	4	24	0.67	<15.00
1549523	7	B2 FL	12	12	1.00	<10.00
1549524	8	B2 WT	4	24	0.67	<15.00
1549525	9	B3 FL	12	12	1.00	<10.00
1549526	10	B3 WS	4	24	0.67	<15.00
1549527	11	B4 FL	12	12	1.00	<10.00
1549528	12	B4 WS	4	24	0.67	<15.00
1549529	FB	FIELD BLANK	N/A	N/A	N/A	N/D

Nathan Ditty
 Analyst Signature

(ND=Not Detected, N/A Not Available, RL Reporting Limit, Analytical Reporting Limit is 10 ug/sample) * For true values assume (2) significant figures. The method and batch QC is acceptable unless otherwise stated. EPA HUD Regulatory Limits: 40 ug/ft2 (Floors Carpeted/uncarpeted), 250ug/ft2 (Window Sill/Stools), 400 ug/ft2 (Window Trough /Well/Ext Concrete Surfaces) The laboratory operates in accord with ISO 17025 guidelines and holds limited scopes of accreditation under AIHA and NY State DOH ELAP programs. These results are submitted pursuant to AAT LLC current terms and conditions of sale, including the company's standard warranty and limitation of liability provisions. Analytical results relate to the samples as



AIHA ELLAP- Lab ID #100986, NY State DOH ELAP -Lab ID #11864, State of Ohio- Lab ID # 10042

Date Printed: 06/10/2013 7:12AM

AAT Project: 154914

To : American Environmental Consultants, LLC
 12838 Gavel
 Detroit, MI 48232

AAT Project : 154914
Client Project : 2708 Hikone
Date Reported : 06/10/2013

Attn : Jeff Fox
Email : jfox@aecmi.net
Phone : 313-491-2600

Project Location : 2708 Hikone

Sample	Client Code	Analysis Requested	Completed
1549517	1	Dust Wipe	06/07/2013
1549518	2	Dust Wipe	06/07/2013
1549519	3	Dust Wipe	06/07/2013
1549520	4	Dust Wipe	06/07/2013
1549521	5	Dust Wipe	06/07/2013
1549522	6	Dust Wipe	06/07/2013
1549523	7	Dust Wipe	06/07/2013
1549524	8	Dust Wipe	06/07/2013
1549525	9	Dust Wipe	06/07/2013
1549526	10	Dust Wipe	06/07/2013
1549527	11	Dust Wipe	06/07/2013
1549528	12	Dust Wipe	06/07/2013
1549529	FB	Dust Wipe	06/07/2013



Reviewed By Quality Assurance Coordinator - Robert A Theys

This report is intended for use solely by the individual or entity to which it is addressed. It may contain information that is privileged, confidential and otherwise exempt by law from disclosure. If the reader of this information is not the intended recipient or an employee of its intended recipient, you are herewith notified that any dissemination, distribution or copying of this information is strictly prohibited. If you have received this information in error, please notify AAT immediately. Thank you.

AIHA ELLAP- Lab ID #100986, NY State DOH ELAP -Lab ID #11864, State of Ohio- Lab ID # 10042

Date Printed: 06/10/2013 7:12AM

AAT Project: 154914





12950 Haggerty Road
 Belleville, MI 48111
 Ph: (734) 699-labs; Fax: (734) 699-8407

Certificate of Analysis: Lead In Dust Wipe by NIOSH Method 7082

Client : American Environmental Consultants, LLC
 12838 Gavel
 Detroit, MI 48232

Attn : Jeff Fox
Phone : 313-491-2600

Email : jfox@aecmi.net
Fax : 313-491-2601

AAT Project : 154900
Sampling Date : 05/20/2013
Date Received : 06/04/2013
Date Analyzed : 06/10/2013
Date Reported : 06/10/2013
Analyst : Ralph Horvat

Project Location : 2710 HIKONE

Client Project : 2710 HIKONE

Lab Sample ID	Client Code	Sample Description	Length (inch)	Width (inch)	Area (Sq ft)	Results Lead µg/ft2 *
1549365	1	RM L FL	12	12	1.00	<10.00
1549366	2	RM L WS	4	24	0.67	<15.00
1549367	3	RM K FL	12	12	1.00	<10.00
1549368	4	RM K WT	4	24	0.67	<15.00
1549369	5	RM B1 FL	12	12	1.00	<10.00
1549370	6	RM B1 WS	4	24	0.67	<15.00
1549371	7	RM B2 FL	12	12	1.00	<10.00
1549372	8	RM B2 WT	4	24	0.67	<15.00
1549373	9	2ND FL HALL FL	12	12	1.00	<10.00
1549374	10	2ND STAIR FL	12	12	1.00	<10.00
1549375	11	RM BASE FL	12	12	1.00	<10.00
1549376	12	RM BATH FL	12	12	1.00	<10.00
1549377	FB	FIELD BLANK	N/A	N/A	N/A	N/D

Analyst Signature

(ND=Not Detected, N/A Not Available, RL Reporting Limit, Analytical Reporting Limit is 10 ug/sample) * For true values assume (2) significant figures. The method and batch QC is acceptable unless otherwise stated. EPA HUD Regulatory Limits: 40 ug/ft2 (Floors Carpeted/uncarpeted), 250ug/ft2 (Window Sill/Stools), 400 ug/ft2 (Window Trough /Well/Ext Concrete Surfaces) The laboratory operates in accord with ISO 17025 guidelines and holds limited scopes of accreditation under AIHA and NY State DOH ELAP programs. These results are submitted pursuant to AAT LLC current terms and conditions of sale, including the company's standard warranty and limitation of liability provisions. Analytical results relate to the samples as



AIHA ELLAP- Lab ID #100986, NY State DOH ELAP -Lab ID #11864, State of Ohio- Lab ID # 10042

Date Printed: 06/10/2013 8:45AM

AAT Project: 154900

To : American Environmental Consultants, LLC
 12838 Gavel
 Detroit, MI 48232

AAT Project : 154900
 Client Project : 2710 HIKONE
 Date Reported : 06/10/2013

Attn : Jeff Fox
 Email : jfox@aecmi.net
 Phone : 313-491-2600

Project Location : 2710 HIKONE

Sample	Client Code	Analysis Requested	Completed
1549365	1	Dust Wipe	06/10/2013
1549366	2	Dust Wipe	06/10/2013
1549367	3	Dust Wipe	06/10/2013
1549368	4	Dust Wipe	06/10/2013
1549369	5	Dust Wipe	06/10/2013
1549370	6	Dust Wipe	06/10/2013
1549371	7	Dust Wipe	06/10/2013
1549372	8	Dust Wipe	06/10/2013
1549373	9	Dust Wipe	06/10/2013
1549374	10	Dust Wipe	06/10/2013
1549375	11	Dust Wipe	06/10/2013
1549376	12	Dust Wipe	06/10/2013
1549377	FB	Dust Wipe	06/10/2013



Reviewed By Quality Assurance Coordinator - Robert A Theys

This report is intended for use solely by the individual or entity to which it is addressed. It may contain information that is privileged, confidential and otherwise exempt by law from disclosure. If the reader of this information is not the intended recipient or an employee of its intended recipient, you are herewith notified that any dissemination, distribution or copying of this information is strictly prohibited. If you have received this information in error, please notify AAT immediately. Thank you.

AIHA ELLAP- Lab ID #100986, NY State DOH ELAP -Lab ID #11864, State of Ohio- Lab ID # 10042



Date Printed: 06/10/2013 8:45AM

AAT Project: 154900



12950 Haggerty Road
 Belleville, MI 48111
 Ph: (734) 699-labs; Fax: (734) 699-8407

Certificate of Analysis: Lead In Dust Wipe by NIOSH Method 7082

Client : American Environmental Consultants, LLC
 12838 Gavel
 Detroit, MI 48232

Attn : Jeff Fox
Phone : 313-491-2600

Email : jfox@aecmi.net
Fax : 313-491-2601

AAT Project : 154915
Sampling Date : 05/20/2013
Date Received : 06/04/2013
Date Analyzed : 06/07/2013
Date Reported : 06/07/2013
Analyst : Nathan Ditty

Project Location : 2718 HIKONE

Client Project : 2718 HIKONE

Lab Sample ID	Client Code	Sample Description	Length (inch)	Width (inch)	Area (Sq ft)	Results Lead µg/ft2 *
1549530	1	RM L FL	12	12	1.00	<10.00
1549531	2	RM L WS	4	24	0.67	<15.00
1549532	3	RM K FL	12	12	1.00	<10.00
1549533	4	RM K WT	4	24	0.67	<15.00
1549534	5	RM B1 FL	12	12	1.00	<10.00
1549535	6	RM B1 WS	4	24	0.67	<15.00
1549536	7	RM B2 FL	12	12	1.00	<10.00
1549537	8	RM B2 WT	4	24	0.67	<15.00
1549538	9	RM B3 FL	12	12	1.00	<10.00
1549539	10	RM B3 WS	4	24	0.67	<15.00
1549540	11	RM B4 FL	12	12	1.00	<10.00
1549541	12	RM B4 WS	4	24	0.67	<15.00
1549542	FB	FIELD BLANK	N/A	N/A	N/A	N/D

Nathan Ditty
 Analyst Signature

(ND=Not Detected, N/A Not Available, RL Reporting Limit, Analytical Reporting Limit is 10 ug/sample) * For true values assume (2) significant figures. The method and batch QC is acceptable unless otherwise stated. EPA HUD Regulatory Limits: 40 ug/ft2 (Floors Carpeted/uncarpeted), 250ug/ft2 (Window Sill/Stools), 400 ug/ft2 (Window Trough /Well/Ext Concrete Surfaces) The laboratory operates in accord with ISO 17025 guidelines and holds limited scopes of accreditation under AIHA and NY State DOH ELAP programs. These results are submitted pursuant to AAT LLC current terms and conditions of sale, including the company's standard warranty and limitation of liability provisions. Analytical results relate to the samples as



AIHA ELLAP- Lab ID #100986, NY State DOH ELAP -Lab ID #11864, State of Ohio- Lab ID # 10042

Date Printed: 06/07/2013 6:24PM

AAT Project: 154915

To : American Environmental Consultants, LLC
 12838 Gavel
 Detroit, MI 48232

Attn : Jeff Fox

Email : jfox@aecmi.net
 Phone : 313-491-2600

AAT Project : 154915
 Client Project : 2718 HIKONE
 Date Reported : 06/07/2013

Project Location : 2718 HIKONE

Sample	Client Code	Analysis Requested	Completed
1549530	1	Dust Wipe	06/07/2013
1549531	2	Dust Wipe	06/07/2013
1549532	3	Dust Wipe	06/07/2013
1549533	4	Dust Wipe	06/07/2013
1549534	5	Dust Wipe	06/07/2013
1549535	6	Dust Wipe	06/07/2013
1549536	7	Dust Wipe	06/07/2013
1549537	8	Dust Wipe	06/07/2013
1549538	9	Dust Wipe	06/07/2013
1549539	10	Dust Wipe	06/07/2013
1549540	11	Dust Wipe	06/07/2013
1549541	12	Dust Wipe	06/07/2013
1549542	FB	Dust Wipe	06/07/2013



Reviewed By Quality Assurance Coordinator - Robert A Theys

This report is intended for use solely by the individual or entity to which it is addressed. It may contain information that is privileged, confidential and otherwise exempt by law from disclosure. If the reader of this information is not the intended recipient or an employee of its intended recipient, you are herewith notified that any dissemination, distribution or copying of this information is strictly prohibited. If you have received this information in error, please notify AAT immediately. Thank you.

AIHA ELLAP- Lab ID #100986, NY State DOH ELAP -Lab ID #11864, State of Ohio- Lab ID # 10042

Date Printed: 06/07/2013 6:24PM

AAT Project: 154915





12950 Haggerty Road
 Belleville, MI 48111
 Ph: (734) 699-labs; Fax: (734) 699-8407

Certificate of Analysis: Lead In Dust Wipe by NIOSH Method 7082

Client : American Environmental Consultants, LLC
 12838 Gavel
 Detroit, MI 48232

Attn : Jeff Fox
Phone : 313-491-2600

Email : jfox@aecmi.net
Fax : 313-491-2601

AAT Project : 154917
Sampling Date : 05/20/2013
Date Received : 06/04/2013
Date Analyzed : 06/07/2013
Date Reported : 06/07/2013
Analyst : Nathan Ditty

Project Location : 2720 HIKONE
Client Project : 2720 HIKONE

Lab Sample ID	Client Code	Sample Description	Length (inch)	Width (inch)	Area (Sq ft)	Results Lead µg/ft2 *
1549553	1	RM L FL	12	12	1.00	<10.00
1549554	2	RM L WS	4	24	0.67	<15.00
1549555	3	RM K FL	12	12	1.00	<10.00
1549556	4	RM K WT	4	24	0.67	<15.00
1549557	5	RM B1 FL	12	12	1.00	<10.00
1549558	6	RM B1 WS	4	24	0.67	<15.00
1549559	7	RM B2 FL	12	12	1.00	<10.00
1549560	8	RM B2 WT	4	24	0.67	<15.00
1549561	9	RM B3 FL	12	12	1.00	<10.00
1549562	10	RM B3 WS	4	24	0.67	<15.00
1549563	11	RM BATH FL	12	12	1.00	<10.00
1549564	12	RM BASE FL	12	12	1.00	<10.00
1549565	FB	FIELD BLANK	N/A	N/A	N/A	N/D

Nathan Ditty
 Analyst Signature

(ND=Not Detected, N/A Not Available, RL Reporting Limit, Analytical Reporting Limit is 10 ug/sample) * For true values assume (2) significant figures. The method and batch QC is acceptable unless otherwise stated. EPA HUD Regulatory Limits: 40 ug/ft2 (Floors Carpeted/uncarpeted), 250ug/ft2 (Window Sill/Stools), 400 ug/ft2 (Window Trough /Well/Ext Concrete Surfaces) The laboratory operates in accord with ISO 17025 guidelines and holds limited scopes of accreditation under AIHA and NY State DOH ELAP programs. These results are submitted pursuant to AAT LLC current terms and conditions of sale, including the company's standard warranty and limitation of liability provisions. Analytical results relate to the samples as



AIHA ELLAP- Lab ID #100986, NY State DOH ELAP -Lab ID #11864, State of Ohio- Lab ID # 10042

Date Printed: 06/07/2013 6:24PM

AAT Project: 154917

To : American Environmental Consultants, LLC
 12838 Gavel
 Detroit, MI 48232

Attn : Jeff Fox

Email : jfox@aecmi.net
 Phone : 313-491-2600

AAT Project : 154917
 Client Project : 2720 HIKONE
 Date Reported : 06/07/2013

Project Location : 2720 HIKONE

Sample	Client Code	Analysis Requested	Completed
1549553	1	Dust Wipe	06/07/2013
1549554	2	Dust Wipe	06/07/2013
1549555	3	Dust Wipe	06/07/2013
1549556	4	Dust Wipe	06/07/2013
1549557	5	Dust Wipe	06/07/2013
1549558	6	Dust Wipe	06/07/2013
1549559	7	Dust Wipe	06/07/2013
1549560	8	Dust Wipe	06/07/2013
1549561	9	Dust Wipe	06/07/2013
1549562	10	Dust Wipe	06/07/2013
1549563	11	Dust Wipe	06/07/2013
1549564	12	Dust Wipe	06/07/2013
1549565	FB	Dust Wipe	06/07/2013



Reviewed By Quality Assurance Coordinator - Robert A Theys

This report is intended for use solely by the individual or entity to which it is addressed. It may contain information that is privileged, confidential and otherwise exempt by law from disclosure. If the reader of this information is not the intended recipient or an employee of its intended recipient, you are herewith notified that any dissemination, distribution or copying of this information is strictly prohibited. If you have received this information in error, please notify AAT immediately. Thank you.

AIHA ELLAP- Lab ID #100986, NY State DOH ELAP -Lab ID #11864, State of Ohio- Lab ID # 10042

Date Printed: 06/07/2013 6:24PM

AAT Project: 154917





12950 Haggerty Road
 Belleville, MI 48111
 Ph: (734) 699-labs; Fax: (734) 699-8407

Certificate of Analysis: Lead In Dust Wipe by NIOSH Method 7082

Client : American Environmental Consultants, LLC
 12838 Gavel
 Detroit, MI 48232

Attn : Jeff Fox
Phone : 313-491-2600

Email : jfox@aecmi.net
Fax : 313-491-2601

AAT Project : 154902
Sampling Date : 05/21/2013
Date Received : 06/04/2013
Date Analyzed : 06/07/2013
Date Reported : 06/10/2013
Analyst : Nathan Ditty

Project Location : 2726 HIKONE
Client Project : 2726 HIKONE

Lab Sample ID	Client Code	Sample Description	Length (inch)	Width (inch)	Area (Sq ft)	Results Lead µg/ft2 *
1549395	1	RM L FL	12	12	1.00	<10.00
1549396	2	RM L WS	4	24	0.67	<15.00
1549397	3	RM K FL	12	12	1.00	<10.00
1549398	4	RM K WT	4	24	0.67	<15.00
1549399	5	RM B1 FL	12	12	1.00	<10.00
1549400	6	RM B1 WT	4	24	0.67	<15.00
1549401	7	RM B2 FL	12	12	1.00	<10.00
1549402	8	RM B2 WT	4	24	0.67	<15.00
1549403	9	RM B3 FL	12	12	1.00	<10.00
1549404	10	RM B3 WS	4	24	0.67	<15.00
1549405	11	RM BATH FL	12	12	1.00	<10.00
1549406	12	RM BASE FL	12	12	1.00	<10.00
1549407	FB	FIELD BLANK	N/A	N/A	N/A	N/D

Nathan Ditty
 Analyst Signature

(ND=Not Detected, N/A Not Available, RL Reporting Limit, Analytical Reporting Limit is 10 ug/sample) * For true values assume (2) significant figures. The method and batch QC is acceptable unless otherwise stated. EPA HUD Regulatory Limits: 40 ug/ft2 (Floors Carpeted/uncarpeted), 250ug/ft2 (Window Sill/Stools), 400 ug/ft2 (Window Trough /Well/Ext Concrete Surfaces) The laboratory operates in accord with ISO 17025 guidelines and holds limited scopes of accreditation under AIHA and NY State DOH ELAP programs. These results are submitted pursuant to AAT LLC current terms and conditions of sale, including the company's standard warranty and limitation of liability provisions. Analytical results relate to the samples as



AIHA ELLAP- Lab ID #100986, NY State DOH ELAP -Lab ID #11864, State of Ohio- Lab ID # 10042

Date Printed: 06/10/2013 8:01AM

AAT Project: 154902

To : American Environmental Consultants, LLC
 12838 Gavel
 Detroit, MI 48232

Attn : Jeff Fox

Email : jfox@aecmi.net

Phone : 313-491-2600

AAT Project : 154902

Client Project : 2726 HIKONE

Date Reported : 06/10/2013

Project Location : 2726 HIKONE

Sample	Client Code	Analysis Requested	Completed
1549395	1	Dust Wipe	06/07/2013
1549396	2	Dust Wipe	06/07/2013
1549397	3	Dust Wipe	06/07/2013
1549398	4	Dust Wipe	06/07/2013
1549399	5	Dust Wipe	06/07/2013
1549400	6	Dust Wipe	06/07/2013
1549401	7	Dust Wipe	06/07/2013
1549402	8	Dust Wipe	06/07/2013
1549403	9	Dust Wipe	06/07/2013
1549404	10	Dust Wipe	06/07/2013
1549405	11	Dust Wipe	06/07/2013
1549406	12	Dust Wipe	06/07/2013
1549407	FB	Dust Wipe	06/07/2013



Reviewed By

Quality Assurance Coordinator - Robert A Theys

This report is intended for use solely by the individual or entity to which it is addressed. It may contain information that is privileged, confidential and otherwise exempt by law from disclosure. If the reader of this information is not the intended recipient or an employee of its intended recipient, you are herewith notified that any dissemination, distribution or copying of this information is strictly prohibited. If you have received this information in error, please notify AAT immediately. Thank you.

AIHA ELLAP- Lab ID #100986, NY State DOH ELAP -Lab ID #11864, State of Ohio- Lab ID # 10042

Date Printed: 06/10/2013 8:01AM

AAT Project: 154902



Certificate of Analysis: Lead In Dust Wipe by NIOSH Method 7082

 Client : American Environmental Consultants, LLC
 12838 Gavel
 Detroit, MI 48232

 Attn : Jeff Fox
 Phone : 313-491-2600


 Email : jfox@aecmi.net
 Fax : 313-491-2601

 AAT Project : 154904
 Sampling Date : 05/21/2013
 Date Received : 06/04/2013
 Date Analyzed : 06/07/2013
 Date Reported : 06/10/2013
 Analyst : Nathan Ditty

Project Location : 2728 HIKONE

Client Project : 2728 HIKONE

Lab Sample ID	Client Code	Sample Description	Length (inch)	Width (inch)	Area (Sq ft)	Results Lead µg/ft2 *
1549421	1	RM L FL	12	12	1.00	<10.00
1549422	2	RM L WS	4	24	0.67	<15.00
1549423	3	RM K FL	12	12	1.00	<10.00
1549424	4	RM K WT	4	24	0.67	<15.00
1549425	5	RM B1 FL	12	12	1.00	<10.00
1549426	6	RM B1 WS	4	24	0.67	<15.00
1549427	7	RM B2 FL	12	12	1.00	<10.00
1549428	8	RM B2 WT	4	24	0.67	<15.00
1549429	9	2ND FL HALL FL	12	12	1.00	<10.00
1549430	10	2ND FL STAIR FL	12	12	1.00	<10.00
1549431	11	RM BASE FL	12	12	1.00	<10.00
1549432	12	RM BATH FL	12	12	1.00	<10.00
1549433	FB	FIELD BLANK	N/A	N/A	N/A	N/D



Analyst Signature

(ND=Not Detected, N/A Not Available, RL Reporting Limit, Analytical Reporting Limit is 10 ug/sample) * For true values assume (2) significant figures. The method and batch QC is acceptable unless otherwise stated. EPA HUD Regulatory Limits: 40 ug/ft2 (Floors Carpeted/uncarpeted), 250ug/ft2 (Window Sill/Stools), 400 ug/ft2 (Window Trough /Well/Ext Concrete Surfaces) The laboratory operates in accord with ISO 17025 guidelines and holds limited scopes of accreditation under AIHA and NY State DOH ELAP programs. These results are submitted pursuant to AAT LLC current terms and conditions of sale, including the company's standard warranty and limitation of liability provisions. Analytical results relate to the samples as



AIHA ELLAP- Lab ID #100986, NY State DOH ELAP -Lab ID #11864, State of Ohio- Lab ID # 10042

Date Printed: 06/10/2013 8:02AM

AAT Project: 154904

To : American Environmental Consultants, LLC
 12838 Gavel
 Detroit, MI 48232

Attn : Jeff Fox

Email : jfox@aecmi.net
 Phone : 313-491-2600

AAT Project : 154904
 Client Project : 2728 HIKONE
 Date Reported : 06/10/2013

Project Location : 2728 HIKONE

Sample	Client Code	Analysis Requested	Completed
1549421	1	Dust Wipe	06/07/2013
1549422	2	Dust Wipe	06/07/2013
1549423	3	Dust Wipe	06/07/2013
1549424	4	Dust Wipe	06/07/2013
1549425	5	Dust Wipe	06/07/2013
1549426	6	Dust Wipe	06/07/2013
1549427	7	Dust Wipe	06/07/2013
1549428	8	Dust Wipe	06/07/2013
1549429	9	Dust Wipe	06/07/2013
1549430	10	Dust Wipe	06/07/2013
1549431	11	Dust Wipe	06/07/2013
1549432	12	Dust Wipe	06/07/2013
1549433	FB	Dust Wipe	06/07/2013



Reviewed By Quality Assurance Coordinator - Robert A Theys

This report is intended for use solely by the individual or entity to which it is addressed. It may contain information that is privileged, confidential and otherwise exempt by law from disclosure. If the reader of this information is not the intended recipient or an employee of its intended recipient, you are herewith notified that any dissemination, distribution or copying of this information is strictly prohibited. If you have received this information in error, please notify AAT immediately. Thank you.

AIHA ELLAP- Lab ID #100986, NY State DOH ELAP -Lab ID #11864, State of Ohio- Lab ID # 10042



Date Printed: 06/10/2013 8:02AM

AAT Project: 154904



12950 Haggerty Road
 Belleville, MI 48111
 Ph: (734) 699-labs; Fax: (734) 699-8407

Certificate of Analysis: Lead In Dust Wipe by NIOSH Method 7082

Client : American Environmental Consultants, LLC
 12838 Gavel
 Detroit, MI 48232

Attn : Jeff Fox
Phone : 313-491-2600

Email : jfox@aecmi.net
Fax : 313-491-2601

AAT Project : 154920
Sampling Date : 05/21/2013
Date Received : 06/04/2013
Date Analyzed : 06/07/2013
Date Reported : 06/07/2013
Analyst : Nathan Ditty

Project Location : 2730 HIKONE

Client Project : 2730 HIKONE

Lab Sample ID	Client Code	Sample Description	Length (inch)	Width (inch)	Area (Sq ft)	Results Lead µg/ft ² *
1549578	1	RM L FL	12	12	1.00	<10.00
1549579	2	RM L WS	4	24	0.67	<15.00
1549580	3	RM K FL	12	12	1.00	<10.00
1549581	4	RM K WT	4	24	0.67	<15.00
1549582	5	RM B1 FL	12	12	1.00	<10.00
1549583	6	RM B1 WS	4	24	0.67	<15.00
1549584	7	RM B2 FL	12	12	1.00	<10.00
1549585	8	RM B2 WT	4	24	0.67	<15.00
1549586	9	RM B3 FL	12	12	1.00	<10.00
1549587	10	RM B3 WS	4	24	0.67	<15.00
1549588	11	RM B4 FL	12	12	1.00	<10.00
1549589	12	RM B4 WS	4	24	0.67	<15.00
1549590	FB	FIELD BLANK	N/A	N/A	N/A	N/D

Nathan Ditty
 Analyst Signature

(ND=Not Detected, N/A Not Available, RL Reporting Limit, Analytical Reporting Limit is 10 ug/sample) * For true values assume (2) significant figures. The method and batch QC is acceptable unless otherwise stated. EPA HUD Regulatory Limits: 40 ug/ft² (Floors Carpeted/un-carpeted), 250ug/ft² (Window Sill/Stools), 400 ug/ft² (Window Trough /Well/Ext Concrete Surfaces) The laboratory operates in accord with ISO 17025 guidelines and holds limited scopes of accreditation under AIHA and NY State DOH ELAP programs. These results are submitted pursuant to AAT LLC current terms and conditions of sale, including the company's standard warranty and limitation of liability provisions. Analytical results relate to the samples as



AIHA ELLAP- Lab ID #100986, NY State DOH ELAP -Lab ID #11864, State of Ohio- Lab ID # 10042

Date Printed: 06/07/2013 6:23PM

AAT Project: 154920

To : American Environmental Consultants, LLC
 12838 Gavel
 Detroit, MI 48232

Attn : Jeff Fox

Email : jfox@aecmi.net

Phone : 313-491-2600

AAT Project : 154920

Client Project : 2730 HIKONE

Date Reported : 06/07/2013

Project Location : 2730 HIKONE

Sample	Client Code	Analysis Requested	Completed
1549578	1	Dust Wipe	06/07/2013
1549579	2	Dust Wipe	06/07/2013
1549580	3	Dust Wipe	06/07/2013
1549581	4	Dust Wipe	06/07/2013
1549582	5	Dust Wipe	06/07/2013
1549583	6	Dust Wipe	06/07/2013
1549584	7	Dust Wipe	06/07/2013
1549585	8	Dust Wipe	06/07/2013
1549586	9	Dust Wipe	06/07/2013
1549587	10	Dust Wipe	06/07/2013
1549588	11	Dust Wipe	06/07/2013
1549589	12	Dust Wipe	06/07/2013
1549590	FB	Dust Wipe	06/07/2013



Reviewed By

Quality Assurance Coordinator - Robert A Theys

This report is intended for use solely by the individual or entity to which it is addressed. It may contain information that is privileged, confidential and otherwise exempt by law from disclosure. If the reader of this information is not the intended recipient or an employee of its intended recipient, you are herewith notified that any dissemination, distribution or copying of this information is strictly prohibited. If you have received this information in error, please notify AAT immediately. Thank you.

AIHA ELLAP- Lab ID #100986, NY State DOH ELAP -Lab ID #11864, State of Ohio- Lab ID # 10042

Date Printed: 06/07/2013 6:23PM

AAT Project: 154920





12950 Haggerty Road
 Belleville, MI 48111
 Ph: (734) 699-labs; Fax: (734) 699-8407

Certificate of Analysis: Lead In Dust Wipe by NIOSH Method 7082

Client : American Environmental Consultants, LLC
 12838 Gavel
 Detroit, MI 48232

Attn : Jeff Fox
Phone : 313-491-2600

Email : jfox@aecmi.net
Fax : 313-491-2601

AAT Project : 154898
Sampling Date : 05/21/2013
Date Received : 06/04/2013
Date Analyzed : 06/07/2013
Date Reported : 06/10/2013
Analyst : Nathan Ditty

Project Location : 2732 HIKONE

Client Project : 2732 HIKONE

Lab Sample ID	Client Code	Sample Description	Length (inch)	Width (inch)	Area (Sq ft)	Results Lead $\mu\text{g}/\text{ft}^2$ *
1549336	1	RM L FL	12	12	1.00	<10.00
1549337	2	RM L WS	4	24	0.67	<15.00
1549338	3	RM K FL	12	12	1.00	<10.00
1549339	4	RM K WT	4	24	0.67	<15.00
1549340	5	RM B1 FL	12	12	1.00	<10.00
1549341	6	RM B1 WS	4	24	0.67	<15.00
1549342	7	RM B2 FL	12	12	1.00	<10.00
1549343	8	RM B2 WT	4	24	0.67	<15.00
1549344	9	RM B3 FL	12	12	1.00	<10.00
1549345	10	RM B3 WS	4	24	0.67	<15.00
1549346	11	RM BATH FL	12	12	1.00	<10.00
1549347	12	RM BASE FL	12	12	1.00	<10.00

Analyst Signature

(ND=Not Detected, N/A Not Available, RL Reporting Limit, Analytical Reporting Limit is 10 ug/sample) * For true values assume (2) significant figures. The method and batch QC is acceptable unless otherwise stated. EPA HUD Regulatory Limits: 40 ug/ft2 (Floors Carpeted/uncarpeted), 250ug/ft2 (Window Sill/Stools), 400 ug/ft2 (Window Trough /Well/Ext Concrete Surfaces) The laboratory operates in accord with ISO 17025 guidelines and holds limited scopes of accreditation under AIHA and NY State DOH ELAP programs. These results are submitted pursuant to AAT LLC current terms and conditions of sale, including the company's standard warranty and limitation of liability provisions. Analytical results relate to the samples as



AIHA ELLAP- Lab ID #100986, NY State DOH ELAP -Lab ID #11864, State of Ohio- Lab ID # 10042

Date Printed: 06/10/2013 7:58AM

AAT Project: 154898

To : American Environmental Consultants, LLC
 12838 Gavel
 Detroit, MI 48232

Attn : Jeff Fox

Email : jfox@aecmi.net
 Phone : 313-491-2600

AAT Project : 154898
 Client Project : 2732 HIKONE
 Date Reported : 06/10/2013

Project Location : 2732 HIKONE

Sample	Client Code	Analysis Requested	Completed
1549336	1	Dust Wipe	06/07/2013
1549337	2	Dust Wipe	06/07/2013
1549338	3	Dust Wipe	06/07/2013
1549339	4	Dust Wipe	06/07/2013
1549340	5	Dust Wipe	06/07/2013
1549341	6	Dust Wipe	06/07/2013
1549342	7	Dust Wipe	06/07/2013
1549343	8	Dust Wipe	06/07/2013
1549344	9	Dust Wipe	06/07/2013
1549345	10	Dust Wipe	06/07/2013
1549346	11	Dust Wipe	06/07/2013
1549347	12	Dust Wipe	06/07/2013



Reviewed By Quality Assurance Coordinator - Robert A Theys

This report is intended for use solely by the individual or entity to which it is addressed. It may contain information that is privileged, confidential and otherwise exempt by law from disclosure. If the reader of this information is not the intended recipient or an employee of its intended recipient, you are herewith notified that any dissemination, distribution or copying of this information is strictly prohibited. If you have received this information in error, please notify AAT immediately. Thank you.

AIHA ELLAP- Lab ID #100986, NY State DOH ELAP -Lab ID #11864, State of Ohio- Lab ID # 10042



Date Printed: 06/10/2013 7:58AM

AAT Project: 154898



12950 Haggerty Road
 Belleville, MI 48111
 Ph: (734) 699-labs; Fax: (734) 699-8407

Certificate of Analysis: Lead In Dust Wipe by NIOSH Method 7082

Client : American Environmental Consultants, LLC
 12838 Gavel
 Detroit, MI 48232

Attn : Jeff Fox
Phone : 313-491-2600

Email : jfox@aecmi.net
Fax : 313-491-2601

AAT Project : 154924
Sampling Date : 05/21/2013
Date Received : 06/04/2013
Date Analyzed : 06/07/2013
Date Reported : 06/10/2013
Analyst : Nathan Ditty

Project Location : 2742 HIKONE

Client Project : 2742 HIKONE

Lab Sample ID	Client Code	Sample Description	Length (inch)	Width (inch)	Area (Sq ft)	Results Lead µg/ft ² *
1549617	1	RM L FL	12	12	1.00	<10.00
1549618	2	RM L WS	4	24	0.67	<15.00
1549619	3	RM K FL	12	12	1.00	<10.00
1549620	4	RM K WT	4	24	0.67	<15.00
1549621	5	RM B1 FL	12	12	1.00	<10.00
1549622	6	RM B1 WS	4	24	0.67	<15.00
1549623	7	RM B2 FL	12	12	1.00	<10.00
1549624	8	RM B2 WT	4	24	0.67	<15.00
1549625	9	RM B3 FL	12	12	1.00	<10.00
1549626	10	RM B3 WS	4	24	0.67	<15.00
1549627	11	RM BATH FL	12	12	1.00	<10.00
1549628	12	RM BASE FL	12	12	1.00	<10.00
1549629	FB	FIELD BLANK	N/A	N/A	N/A	N/D

Nathan Ditty
 Analyst Signature

(ND=Not Detected, N/A Not Available, RL Reporting Limit, Analytical Reporting Limit is 10 ug/sample) * For true values assume (2) significant figures. The method and batch QC is acceptable unless otherwise stated. EPA HUD Regulatory Limits: 40 ug/ft² (Floors Carpeted/uncarpeted), 250ug/ft² (Window Sill/Stools), 400 ug/ft² (Window Trough /Well/Ext Concrete Surfaces) The laboratory operates in accord with ISO 17025 guidelines and holds limited scopes of accreditation under AIHA and NY State DOH ELAP programs. These results are submitted pursuant to AAT LLC current terms and conditions of sale, including the company's standard warranty and limitation of liability provisions. Analytical results relate to the samples as



AIHA ELLAP- Lab ID #100986, NY State DOH ELAP -Lab ID #11864, State of Ohio- Lab ID # 10042

Date Printed: 06/10/2013 7:08AM

AAT Project: 154924



12950 Haggerty Road
 Belleville, MI 48111
 Ph: (734) 699-labs; Fax: (734) 699-8407

Certificate of Analysis: Lead In Dust Wipe by NIOSH Method 7082

Client : American Environmental Consultants, LLC
 12838 Gavel
 Detroit, MI 48232

Attn : Jeff Fox
Phone : 313-491-2600

Email : jfox@aecmi.net
Fax : 313-491-2601

AAT Project : 154903
Sampling Date : 05/21/2013
Date Received : 06/04/2013
Date Analyzed : 06/07/2013
Date Reported : 06/10/2013
Analyst : Nathan Ditty

Project Location : 2748 HIKONE

Client Project : 2748 HIKONE

Lab Sample ID	Client Code	Sample Description	Length (inch)	Width (inch)	Area (Sq ft)	Results Lead ug/ft2 *
1549408	1	RM L FL	12	12	1.00	<10.00
1549409	2	RM L WS	4	24	0.67	<15.00
1549410	3	RM K FL	12	12	1.00	<10.00
1549411	4	RM K WT	4	24	0.67	<15.00
1549412	5	RM B1 FL	12	12	1.00	<10.00
1549413	6	RM B1 WS	4	24	0.67	<15.00
1549414	7	RM B2 FL	12	12	1.00	<10.00
1549415	8	RM B2 WT	4	24	0.67	<15.00
1549416	9	RM B3 FL	12	12	1.00	<10.00
1549417	10	RM B3 WS	4	24	0.67	<15.00
1549418	11	RM BATH FL	12	12	1.00	<10.00
1549419	12	RM BASE FL	12	12	1.00	<10.00
1549420	FB	FIELD BLANK	N/A	N/A	N/A	N/D

Nathan Ditty
 Analyst Signature

(ND=Not Detected, N/A Not Available, RL Reporting Limit, Analytical Reporting Limit is 10 ug/sample) * For true values assume (2) significant figures. The method and batch QC is acceptable unless otherwise stated. EPA HUD Regulatory Limits: 40 ug/ft2 (Floors Carpeted/uncarpeted), 250ug/ft2 (Window Sill/Stools), 400 ug/ft2 (Window Trough /Well/Ext Concrete Surfaces) The laboratory operates in accord with ISO 17025 guidelines and holds limited scopes of accreditation under AIHA and NY State DOH ELAP programs. These results are submitted pursuant to AAT LLC current terms and conditions of sale, including the company's standard warranty and limitation of liability provisions. Analytical results relate to the samples as



AIHA ELLAP- Lab ID #100986, NY State DOH ELAP -Lab ID #11864, State of Ohio- Lab ID # 10042

Date Printed: 06/10/2013 7:59AM

AAT Project: 154903

To : American Environmental Consultants, LLC
 12838 Gavel
 Detroit, MI 48232

Attn : Jeff Fox

Email : jfox@aecmi.net
 Phone : 313-491-2600

AAT Project : 154903
 Client Project : 2748 HIKONE
 Date Reported : 06/10/2013

Project Location : 2748 HIKONE

Sample	Client Code	Analysis Requested	Completed
1549408	1	Dust Wipe	06/07/2013
1549409	2	Dust Wipe	06/07/2013
1549410	3	Dust Wipe	06/07/2013
1549411	4	Dust Wipe	06/07/2013
1549412	5	Dust Wipe	06/07/2013
1549413	6	Dust Wipe	06/07/2013
1549414	7	Dust Wipe	06/07/2013
1549415	8	Dust Wipe	06/07/2013
1549416	9	Dust Wipe	06/07/2013
1549417	10	Dust Wipe	06/07/2013
1549418	11	Dust Wipe	06/07/2013
1549419	12	Dust Wipe	06/07/2013
1549420	FB	Dust Wipe	06/07/2013



Reviewed By Quality Assurance Coordinator - Robert A Theys

This report is intended for use solely by the individual or entity to which it is addressed. It may contain information that is privileged, confidential and otherwise exempt by law from disclosure. If the reader of this information is not the intended recipient or an employee of its intended recipient, you are herewith notified that any dissemination, distribution or copying of this information is strictly prohibited. If you have received this information in error, please notify AAT immediately. Thank you.

AIHA ELLAP - Lab ID #100986, NY State DOH ELAP -Lab ID #11864, State of Ohio - Lab ID # 10042





12950 Haggerty Road
 Belleville, MI 48111
 Ph: (734) 699-labs; Fax: (734) 699-8407

Certificate of Analysis: Lead In Dust Wipe by NIOSH Method 7082

Client : American Environmental Consultants, LLC
 12838 Gavel
 Detroit, MI 48232

Attn : Jeff Fox
Phone : 313-491-2600

Email : jfox@aecmi.net
Fax : 313-491-2601

AAT Project : 154929
Sampling Date : 05/22/2013
Date Received : 06/04/2013
Date Analyzed : 06/07/2013
Date Reported : 06/10/2013
Analyst : Nathan Ditty

Project Location : 2750 HIKONE

Client Project : 2750 HIKONE

Lab Sample ID	Client Code	Sample Description	Length (inch)	Width (inch)	Area (Sq ft)	Results Lead $\mu\text{g}/\text{ft}^2$ *
1549668	1	L FL	12	12	1.00	<10.00
1549669	2	L WS	4	24	0.67	<15.00
1549670	3	K FL	12	12	1.00	<10.00
1549671	4	K WT	4	24	0.67	<15.00
1549672	5	B1 FL	12	12	1.00	<10.00
1549673	6	B1 WS	4	24	0.67	<15.00
1549674	7	B2 FL	12	12	1.00	<10.00
1549675	8	B2 WT	4	24	0.67	<15.00
1549676	9	B3 FL	12	12	1.00	<10.00
1549677	10	B3 WS	4	24	0.67	<15.00
1549678	11	BATH FL	12	12	1.00	<10.00
1549679	12	BASE FL	12	12	1.00	<10.00
1549680	FB	FIELD BLANK	N/A	N/A	N/A	N/D

Nathan Ditty
 Analyst Signature

(ND=Not Detected, N/A Not Available, RL Reporting Limit, Analytical Reporting Limit is 10 ug/sample) * For true values assume (2) significant figures. The method and batch QC is acceptable unless otherwise stated. EPA HUD Regulatory Limits: 40 ug/ft2 (Floors Carpeted/uncarpeted), 250ug/ft2 (Window Sill/Stools), 400 ug/ft2 (Window Trough /Well/Ext Concrete Surfaces) The laboratory operates in accord with ISO 17025 guidelines and holds limited scopes of accreditation under AIHA and NY State DOH ELAP programs. These results are submitted pursuant to AAT LLC current terms and conditions of sale, including the company's standard warranty and limitation of liability provisions. Analytical results relate to the samples as



AIHA ELLAP- Lab ID #100986, NY State DOH ELAP -Lab ID #11864, State of Ohio- Lab ID # 10042

Date Printed: 06/10/2013 7:28AM

AAT Project: 154929

To : American Environmental Consultants, LLC
 12838 Gavel
 Detroit, MI 48232

Attn : Jeff Fox

Email : jfox@aecmi.net
 Phone : 313-491-2600

AAT Project : 154929
 Client Project : 2750 HIKONE
 Date Reported : 06/10/2013

Project Location : 2750 HIKONE

Sample	Client Code	Analysis Requested	Completed
1549668	1	Dust Wipe	06/07/2013
1549669	2	Dust Wipe	06/07/2013
1549670	3	Dust Wipe	06/07/2013
1549671	4	Dust Wipe	06/07/2013
1549672	5	Dust Wipe	06/07/2013
1549673	6	Dust Wipe	06/07/2013
1549674	7	Dust Wipe	06/07/2013
1549675	8	Dust Wipe	06/07/2013
1549676	9	Dust Wipe	06/07/2013
1549677	10	Dust Wipe	06/07/2013
1549678	11	Dust Wipe	06/07/2013
1549679	12	Dust Wipe	06/07/2013
1549680	FB	Dust Wipe	06/07/2013



Reviewed By Quality Assurance Coordinator - Robert A Theys

This report is intended for use solely by the individual or entity to which it is addressed. It may contain information that is privileged, confidential and otherwise exempt by law from disclosure. If the reader of this information is not the intended recipient or an employee of its intended recipient, you are herewith notified that any dissemination, distribution or copying of this information is strictly prohibited. If you have received this information in error, please notify AAT immediately. Thank you.

AIHA ELLAP- Lab ID #100986, NY State DOH ELAP -Lab ID #11864, State of Ohio- Lab ID # 10042



Date Printed: 06/10/2013 7:28AM

AAT Project: 154929



12950 Haggerty Road
 Belleville, MI 48111
 Ph: (734) 699-labs; Fax: (734) 699-8407

Certificate of Analysis: Lead In Dust Wipe by NIOSH Method 7082

Client : American Environmental Consultants, LLC
 12838 Gavel
 Detroit, MI 48232

Attn : Jeff Fox
Phone : 313-491-2600

Email : jfox@aecmi.net
Fax : 313-491-2601

AAT Project : 154911
Sampling Date : 05/22/2013
Date Received : 06/04/2013
Date Analyzed : 06/07/2013
Date Reported : 06/10/2013
Analyst : Nathan Ditty

Project Location : 2752 Hikone

Client Project : 2752 Hikone

Lab Sample ID	Client Code	Sample Description	Length (inch)	Width (inch)	Area (Sq ft)	Results Lead µg/ft ² *
1549478	1	L FL	12	12	1.00	<10.00
1549479	2	L WS	4	24	0.67	<15.00
1549480	3	K FL	12	12	1.00	<10.00
1549481	4	K WT	4	24	0.67	<15.00
1549482	5	B1 FL	12	12	1.00	<10.00
1549483	6	B1 WS	4	24	0.67	<15.00
1549484	7	B2 FL	12	12	1.00	<10.00
1549485	8	B2 WT	4	24	0.67	<15.00
1549486	9	2ND FL HALL FL	12	12	1.00	<10.00
1549487	10	2ND FL STAIRS FL	12	12	1.00	<10.00
1549488	11	BASE FL	12	12	1.00	<10.00
1549489	12	BATH FL	12	12	1.00	<10.00
1549490	FB	FIELD BLANK	N/A	N/A	N/A	N/D

Nathan Ditty
 Analyst Signature

(ND=Not Detected, N/A Not Available, RL Reporting Limit, Analytical Reporting Limit is 10 ug/sample) * For true values assume (2) significant figures. The method and batch QC is acceptable unless otherwise stated. EPA HUD Regulatory Limits: 40 ug/ft² (Floors Carpeted/uncarpeted), 250ug/ft² (Window Sill/Stools), 400 ug/ft² (Window Trough /Well/Ext Concrete Surfaces) The laboratory operates in accord with ISO 17025 guidelines and holds limited scopes of accreditation under AIHA and NY State DOH ELAP programs. These results are submitted pursuant to AAT LLC current terms and conditions of sale, including the company's standard warranty and limitation of liability provisions. Analytical results relate to the samples as



AIHA ELLAP- Lab ID #100986, NY State DOH ELAP -Lab ID #11864, State of Ohio- Lab ID # 10042

Date Printed: 06/10/2013 7:55AM

AAT Project: 154911

To : American Environmental Consultants, LLC
 12838 Gavel
 Detroit, MI 48232

Attn : Jeff Fox

Email : jfox@aecmi.net
 Phone : 313-491-2600

AAT Project : 154911
 Client Project : 2752 Hikone
 Date Reported : 06/10/2013

Project Location : 2752 Hikone

Sample	Client Code	Analysis Requested	Completed
1549478	1	Dust Wipe	06/07/2013
1549479	2	Dust Wipe	06/07/2013
1549480	3	Dust Wipe	06/07/2013
1549481	4	Dust Wipe	06/07/2013
1549482	5	Dust Wipe	06/07/2013
1549483	6	Dust Wipe	06/07/2013
1549484	7	Dust Wipe	06/07/2013
1549485	8	Dust Wipe	06/07/2013
1549486	9	Dust Wipe	06/07/2013
1549487	10	Dust Wipe	06/07/2013
1549488	11	Dust Wipe	06/07/2013
1549489	12	Dust Wipe	06/07/2013
1549490	FB	Dust Wipe	06/07/2013



Reviewed By Quality Assurance Coordinator - Robert A Theys

This report is intended for use solely by the individual or entity to which it is addressed. It may contain information that is privileged, confidential and otherwise exempt by law from disclosure. If the reader of this information is not the intended recipient or an employee of its intended recipient, you are herewith notified that any dissemination, distribution or copying of this information is strictly prohibited. If you have received this information in error, please notify AAT immediately. Thank you.

AIHA ELLAP- Lab ID #100986, NY State DOH ELAP -Lab ID #11864, State of Ohio- Lab ID # 10042





12950 Haggerty Road
Belleville, MI 48111
Ph: (734) 699-labs; Fax: (734) 699-8407

Certificate of Analysis: Lead In Dust Wipe by NIOSH Method 7082

Client : American Environmental Consultants, LLC
12838 Gavel
Detroit, MI 48232

Attn : Jeff Fox
Phone : 313-491-2600

Email : jfox@aecmi.net
Fax : 313-491-2601

AAT Project : 154912
Sampling Date : 05/22/2013
Date Received : 06/04/2013
Date Analyzed : 06/07/2013
Date Reported : 06/10/2013
Analyst : Nathan Ditty

Project Location : 2754 Hikone

Client Project : 2754 Hikone

Lab Sample ID	Client Code	Sample Description	Length (inch)	Width (inch)	Area (Sq ft)	Results Lead µg/ft ² *
1549491	1	L FL	12	12	1.00	<10.00
1549492	2	L WS	4	24	0.67	<15.00
1549493	3	K FL	12	12	1.00	<10.00
1549494	4	K WT	4	24	0.67	<15.00
1549495	5	B1 FL	12	12	1.00	<10.00
1549496	6	B1 WS	4	24	0.67	<15.00
1549497	7	B2 FL	12	12	1.00	<10.00
1549498	8	B2 WT	4	24	0.67	<15.00
1549499	9	B3 FL	12	12	1.00	<10.00
1549500	10	B3 WS	4	24	0.67	<15.00
1549501	11	B4 FL	12	12	1.00	<10.00
1549502	12	B4 WS	4	24	0.67	<15.00
1549503	FB	FIELD BLANK	N/A	N/A	N/A	N/D

Analyst Signature

(ND=Not Detected, N/A Not Available, RL Reporting Limit, Analytical Reporting Limit is 10 ug/sample) * For true values assume (2) significant figures. The method and batch QC is acceptable unless otherwise stated. EPA HUD Regulatory Limits: 40 ug/ft² (Floors Carpeted/uncarpeted), 250ug/ft² (Window Sill/Stools), 400 ug/ft² (Window Trough /Well/Ext Concrete Surfaces) The laboratory operates in accord with ISO 17025 guidelines and holds limited scopes of accreditation under AIHA and NY State DOH ELAP programs. These results are submitted pursuant to AAT LLC current terms and conditions of sale, including the company's standard warranty and limitation of liability provisions. Analytical results relate to the samples as



AIHA ELLAP- Lab ID #100986, NY State DOH ELAP -Lab ID #11864, State of Ohio- Lab ID # 10042

Date Printed: 06/10/2013 7:08AM

AAT Project: 154912

To : American Environmental Consultants, LLC
 12838 Gavel
 Detroit, MI 48232

AAT Project : 154912
 Client Project : 2754 Hikone
 Date Reported : 06/10/2013

Attn : Jeff Fox Email : jfox@aecmi.net
 Phone : 313-491-2600

Project Location : 2754 Hikone

Sample	Client Code	Analysis Requested	Completed
1549491	1	Dust Wipe	06/07/2013
1549492	2	Dust Wipe	06/07/2013
1549493	3	Dust Wipe	06/07/2013
1549494	4	Dust Wipe	06/07/2013
1549495	5	Dust Wipe	06/07/2013
1549496	6	Dust Wipe	06/07/2013
1549497	7	Dust Wipe	06/07/2013
1549498	8	Dust Wipe	06/07/2013
1549499	9	Dust Wipe	06/07/2013
1549500	10	Dust Wipe	06/07/2013
1549501	11	Dust Wipe	06/07/2013
1549502	12	Dust Wipe	06/07/2013
1549503	FB	Dust Wipe	06/07/2013



Reviewed By Quality Assurance Coordinator - Robert A Theys

This report is intended for use solely by the individual or entity to which it is addressed. It may contain information that is privileged, confidential and otherwise exempt by law from disclosure. If the reader of this information is not the intended recipient or an employee of its intended recipient, you are herewith notified that any dissemination, distribution or copying of this information is strictly prohibited. If you have received this information in error, please notify AAT immediately. Thank you.

AIHA ELLAP- Lab ID #100986, NY State DOH ELAP -Lab ID #11864, State of Ohio- Lab ID # 10042





12950 Haggerty Road
 Belleville, MI 48111
 Ph: (734) 699-labs; Fax: (734) 699-8407

Certificate of Analysis: Lead In Dust Wipe by NIOSH Method 7082

Client : American Environmental Consultants, LLC
 12838 Gavel
 Detroit, MI 48232

Attn : Jeff Fox
Phone : 313-491-2600

Email : jfox@aecmi.net
Fax : 313-491-2601

AAT Project : 154931
Sampling Date : 05/22/2013
Date Received : 06/04/2013
Date Analyzed : 06/07/2013
Date Reported : 06/07/2013
Analyst : Nathan Ditty

Project Location : 2756 HIKONE

Client Project : 2756 HIKONE

Lab Sample ID	Client Code	Sample Description	Length (inch)	Width (inch)	Area (Sq ft)	Results Lead ug/ft2 *
1549696	1	RM L FL	12	12	1.00	<10.00
1549697	2	RM L WS	4	24	0.67	<15.00
1549698	3	RM K FL	12	12	1.00	<10.00
1549699	4	RM K WT	4	24	0.67	<15.00
1549700	5	RM B1 FL	12	12	1.00	<10.00
1549701	6	RM B1 WS	4	24	0.67	<15.00
1549702	7	RM B2 FL	12	12	1.00	<10.00
1549703	8	RM B2 WT	4	24	0.67	<15.00
1549704	9	RM B3 FL	12	12	1.00	<10.00
1549705	10	RM B3 WS	4	24	0.67	<15.00
1549706	11	RM BATH FL	12	12	1.00	<10.00
1549707	12	RM BASE FL	12	12	1.00	<10.00
1549708	FB	FIELD BLANK	N/A	N/A	N/A	N/D

Nathan Ditty
 Analyst Signature

(ND=Not Detected, N/A Not Available, RL Reporting Limit, Analytical Reporting Limit is 10 ug/sample) * For true values assume (2) significant figures. The method and batch QC is acceptable unless otherwise stated. EPA HUD Regulatory Limits: 40 ug/ft2 (Floors Carpeted/uncarpeted), 250ug/ft2 (Window Sill/Stools), 400 ug/ft2 (Window Trough /Well/Ext Concrete Surfaces) The laboratory operates in accord with ISO 17025 guidelines and holds limited scopes of accreditation under AIHA and NY State DOH ELAP programs. These results are submitted pursuant to AAT LLC current terms and conditions of sale, including the company's standard warranty and limitation of liability provisions. Analytical results relate to the samples as



AIHA ELLAP- Lab ID #100986, NY State DOH ELAP -Lab ID #11864, State of Ohio- Lab ID # 10042

Date Printed: 06/07/2013 6:26PM

AAT Project: 154931



12950 Haggerty Road
Belleville, MI 48111
Ph:(734) 699-labs; Fax:(734) 699-8407

To : American Environmental Consultants, LLC
12838 Gavel
Detroit, MI 48232

Attn : Jeff Fox

Email : jfox@aecmi.net
Phone : 313-491-2600

AAT Project : 154931
Client Project : 2756 HIKONE
Date Reported : 06/07/2013

Project Location : 2756 HIKONE

Sample	Client Code	Analysis Requested	Completed
1549696	1	Dust Wipe	06/07/2013
1549697	2	Dust Wipe	06/07/2013
1549698	3	Dust Wipe	06/07/2013
1549699	4	Dust Wipe	06/07/2013
1549700	5	Dust Wipe	06/07/2013
1549701	6	Dust Wipe	06/07/2013
1549702	7	Dust Wipe	06/07/2013
1549703	8	Dust Wipe	06/07/2013
1549704	9	Dust Wipe	06/07/2013
1549705	10	Dust Wipe	06/07/2013
1549706	11	Dust Wipe	06/07/2013
1549707	12	Dust Wipe	06/07/2013
1549708	FB	Dust Wipe	06/07/2013

Reviewed By

Quality Assurance Coordinator - Robert A Theys

This report is intended for use solely by the individual or entity to which it is addressed. It may contain information that is privileged, confidential and otherwise exempt by law from disclosure. If the reader of this information is not the intended recipient or an employee of its intended recipient, you are herewith notified that any dissemination, distribution or copying of this information is strictly prohibited. If you have received this information in error, please notify AAT immediately. Thank you.

AIHA ELLAP- Lab ID #100986, NY State DOH ELAP -Lab ID #11864, State of Ohio- Lab ID # 10042



Date Printed: 06/07/2013 6:26PM

AAT Project: 154931



12950 Haggerty Road
 Belleville, MI 48111
 Ph: (734) 699-labs; Fax: (734) 699-8407

Certificate of Analysis: Lead In Dust Wipe by NIOSH Method 7082

Client : American Environmental Consultants, LLC
 12838 Gavel
 Detroit, MI 48232

Attn : Jeff Fox
Phone : 313-491-2600

Email : jfox@aecmi.net
Fax : 313-491-2601

AAT Project : 154928
Sampling Date : 05/22/2013
Date Received : 06/04/2013
Date Analyzed : 06/07/2013
Date Reported : 06/10/2013
Analyst : Nathan Ditty

Project Location : 2760 HIKONE
Client Project : 2760 HIKONE

Lab Sample ID	Client Code	Sample Description	Length (inch)	Width (inch)	Area (Sq ft)	Results Lead µg/ft2 *
1549655	1	L FL	12	12	1.00	<10.00
1549656	2	L WS	4	24	0.67	<15.00
1549657	3	K FL	12	12	1.00	<10.00
1549658	4	K WT	4	24	0.67	<15.00
1549659	5	B1 FL	12	12	1.00	<10.00
1549660	6	B1 WS	4	24	0.67	<15.00
1549661	7	B2 FL	12	12	1.00	<10.00
1549662	8	B2 WT	4	24	0.67	<15.00
1549663	9	B3 FL	12	12	1.00	<10.00
1549664	10	B3 WS	4	24	0.67	<15.00
1549665	11	BATH FL	12	12	1.00	<10.00
1549666	12	BASE FL	12	12	1.00	<10.00
1549667	FB	FIELD BLANK	N/A	N/A	N/A	N/D

Nathan Ditty
 Analyst Signature

(ND=Not Detected, N/A Not Available, RL Reporting Limit, Analytical Reporting Limit is 10 ug/sample) * For true values assume (2) significant figures. The method and batch QC is acceptable unless otherwise stated. EPA HUD Regulatory Limits: 40 ug/ft2 (Floors Carpeted/uncarpeted), 250ug/ft2 (Window Sill/Stools), 400 ug/ft2 (Window Trough /Well/Ext Concrete Surfaces) The laboratory operates in accord with ISO 17025 guidelines and holds limited scopes of accreditation under AIHA and NY State DOH ELAP programs. These results are submitted pursuant to AAT LLC current terms and conditions of sale, including the company's standard warranty and limitation of liability provisions. Analytical results relate to the samples as



AIHA ELLAP- Lab ID #100986, NY State DOH ELAP -Lab ID #11864, State of Ohio- Lab ID # 10042

Date Printed: 06/10/2013 7:31AM

AAT Project: 154928

To : American Environmental Consultants, LLC
 12838 Gavel
 Detroit, MI 48232

Attn : Jeff Fox

Email : jfox@aecmi.net
 Phone : 313-491-2600

AAT Project : 154928
 Client Project : 2760 HIKONE
 Date Reported : 06/10/2013

Project Location : 2760 HIKONE

Sample	Client Code	Analysis Requested	Completed
1549655	1	Dust Wipe	06/07/2013
1549656	2	Dust Wipe	06/07/2013
1549657	3	Dust Wipe	06/07/2013
1549658	4	Dust Wipe	06/07/2013
1549659	5	Dust Wipe	06/07/2013
1549660	6	Dust Wipe	06/07/2013
1549661	7	Dust Wipe	06/07/2013
1549662	8	Dust Wipe	06/07/2013
1549663	9	Dust Wipe	06/07/2013
1549664	10	Dust Wipe	06/07/2013
1549665	11	Dust Wipe	06/07/2013
1549666	12	Dust Wipe	06/07/2013
1549667	FB	Dust Wipe	06/07/2013



Reviewed By

Quality Assurance Coordinator - Robert A Theys

This report is intended for use solely by the individual or entity to which it is addressed. It may contain information that is privileged, confidential and otherwise exempt by law from disclosure. If the reader of this information is not the intended recipient or an employee of its intended recipient, you are hereby notified that any dissemination, distribution or copying of this information is strictly prohibited. If you have received this information in error, please notify AAT immediately. Thank you.

AIHA ELLAP- Lab ID #100986, NY State DOH ELAP -Lab ID #11864, State of Ohio- Lab ID # 10042



Date Printed: 06/10/2013 7:31AM

AAT Project: 154928



12950 Haggerty Road
 Belleville, MI 48111
 Ph: (734) 699-labs; Fax: (734) 699-8407

Certificate of Analysis: Lead In Dust Wipe by NIOSH Method 7082

Client : American Environmental Consultants, LLC
 12838 Gavel
 Detroit, MI 48232

Attn : Jeff Fox
Phone : 313-491-2600

Email : jfox@aecmi.net
Fax : 313-491-2601

AAT Project : 154913
Sampling Date : 05/22/2013
Date Received : 06/04/2013
Date Analyzed : 06/07/2013
Date Reported : 06/10/2013
Analyst : Nathan Ditty

Project Location : Community Bld. Hikone

Client Project : Community Bld. Hikone

Lab Sample ID	Client Code	Sample Description	Length (inch)	Width (inch)	Area (Sq ft)	Results Lead µg/ft ² *
1549504	1	K FL	12	12	1.00	<10.00
1549505	2	K WS	4	24	0.67	<15.00
1549506	3	COMP FL	12	12	1.00	<10.00
1549507	4	COMP WT	4	24	0.67	<15.00
1549508	5	CLASS FL	12	12	1.00	<10.00
1549509	6	CLASS WS	4	24	0.67	<15.00
1549510	7	OFFICE FL	12	12	1.00	<10.00
1549511	8	OFFICE WT	4	24	0.67	<15.00
1549512	9	PANTRY FL	12	12	1.00	<10.00
1549513	10	2ND FL HALL FL	12	12	1.00	<10.00
1549514	11	2ND FL ROOM FL	12	12	1.00	<10.00
1549515	12	REAR ROOM FL	12	12	1.00	<10.00
1549516	FB	FIELD BLANK	N/A	N/A	N/A	N/D

Nathan Ditty
 Analyst Signature

(ND=Not Detected, N/A Not Available, RL Reporting Limit, Analytical Reporting Limit is 10 ug/sample) * For true values assume (2) significant figures. The method and batch QC is acceptable unless otherwise stated. EPA HUD Regulatory Limits: 40 ug/ft² (Floors Carpeted/uncarpeted), 250ug/ft² (Window Sill/Stools), 400 ug/ft² (Window Trough /Well/Ext Concrete Surfaces) The laboratory operates in accord with ISO 17025 guidelines and holds limited scopes of accreditation under AIHA and NY State DOH ELAP programs. These results are submitted pursuant to AAT LLC current terms and conditions of sale, including the company's standard warranty and limitation of liability provisions. Analytical results relate to the samples as



AIHA ELLAP- Lab ID #100986, NY State DOH ELAP -Lab ID #11864, State of Ohio- Lab ID # 10042

Date Printed: 06/10/2013 7:10AM

AAT Project: 154913



12950 Haggerty Road
Belleville, MI 48111
Ph:(734) 699-labs; Fax:(734) 699-8407

To : American Environmental Consultants, LLC
12838 Gavel
Detroit, MI 48232

Attn : Jeff Fox

Email : jfox@aecmi.net
Phone : 313-491-2600

AAT Project : 154913
Client Project : Community Bld. Hikone
Date Reported : 06/10/2013

Project Location : Community Bld. Hikone

Sample	Client Code	Analysis Requested	Completed
1549504	1	Dust Wipe	06/07/2013
1549505	2	Dust Wipe	06/07/2013
1549506	3	Dust Wipe	06/07/2013
1549507	4	Dust Wipe	06/07/2013
1549508	5	Dust Wipe	06/07/2013
1549509	6	Dust Wipe	06/07/2013
1549510	7	Dust Wipe	06/07/2013
1549511	8	Dust Wipe	06/07/2013
1549512	9	Dust Wipe	06/07/2013
1549513	10	Dust Wipe	06/07/2013
1549514	11	Dust Wipe	06/07/2013
1549515	12	Dust Wipe	06/07/2013
1549516	FB	Dust Wipe	06/07/2013

Reviewed By

Quality Assurance Coordinator - Robert A Theys

This report is intended for use solely by the individual or entity to which it is addressed. It may contain information that is privileged, confidential and otherwise exempt by law from disclosure. If the reader of this information is not the intended recipient or an employee of its intended recipient, you are herewith notified that any dissemination, distribution or copying of this information is strictly prohibited. If you have received this information in error, please notify AAT immediately. Thank you.

AIHA ELLAP- Lab ID #100986, NY State DOH ELAP -Lab ID #11864, State of Ohio- Lab ID # 10042



Date Printed: 06/10/2013 7:10AM

AAT Project: 154913



12950 Haggerty Road
 Belleville, MI 48111
 Ph: (734) 699-labs; Fax: (734) 699-8407

Certificate of Analysis: Lead In Soil by EPA SW-846 7420 and 3050B Method

Client : American Environmental Consultants, LLC
 12838 Gavel
 Detroit, MI 48232

Attn : Jeff Fox
 Phone : 313-491-2600

Email : jfox@aecmi.net
 Fax : 313-491-2601

AAT Project : 154692
 Sampling Date : 05/22/2013
 Date Received : 06/04/2013
 Date Analyzed : 06/07/2013
 Date Reported : 06/07/2013
 Analyst : Nathan Ditty

Project Location : Hikone

Client Project : Hikone

Lab Sample ID	Client Code	Sample Description	Results Lead µg/g (PPM)	Calculated RL µg/g *
1547285	1	B SIDE OF B-D - E OPEN	21.41	17.28
1547286	2	OPEN SOIL BETWEEN B-D E-D	17.37	14.99
1547287	3	OPEN SOIL ON D SIDE OF B-D - E	<19.00	19.00
1547288	4	OPEN SOIL NEAR BASKETBALL COURT	42.35	19.44
1547289	5	OPEN SOIL IN FRONT OF 2718	18.89	18.70
1547290	6	IN CHICKEN WIRE GARDEN	19.43	16.84
1547291	7	OPEN SOIL BETWEEN WOOD GARDEN BEDS	27.21	18.59

Analyst Signature

*RL= Reporting Limit * For true values assume (2) significant figures. The method and batch QC are acceptable unless otherwise stated. Current EPA/HUD Interim Standard for soil samples are: 400 PPM (parts per million) for play area's, 1200 PPM for building Perimeters and 1000 PPM for California Building Perimeters. AAT internal sop S204. The laboratory operates in accord with ISO 17025 guidelines and holds limited scopes of accreditation under AIHA and NY State DOH ELAP programs. These results are submitted pursuant to AAT LLC current terms and conditions of sale, including the company's standard warranty and limitation of liability provisions. Analytical results relate to the samples as received by the lab. AAT will not assume any liability or responsibility for the manner in which the results are used or interpreted. Reproduction of this document other than in its entirety is not permitted.

AIHA ELLAP- Lab ID #100986, NY State DOH ELAP -Lab ID #11864, State of Ohio- Lab ID # 10042

Date Printed: 06/07/2013 4:23PM

AAT Project: 154692

Revised



To : American Environmental Consultants, LLC
 12838 Gavel
 Detroit, MI 48232

Attn : Jeff Fox

Email : jfox@aecmi.net
 Phone : 313-491-2600

AAT Project : 154692
 Client Project : Hikone
 Date Reported : 06/07/2013

Project Location : Hikone

Sample	Client Code	Analysis Requested	Completed
1547285	1	Lead Soil	06/07/2013
1547286	2	Lead Soil	06/07/2013
1547287	3	Lead Soil	06/07/2013
1547288	4	Lead Soil	06/07/2013
1547289	5	Lead Soil	06/07/2013
1547290	6	Lead Soil	06/07/2013
1547291	7	Lead Soil	06/07/2013



Reviewed By

Quality Assurance Coordinator - Robert A Theys

This report is intended for use solely by the individual or entity to which it is addressed. It may contain information that is privileged, confidential and otherwise exempt by law from disclosure. If the reader of this information is not the intended recipient or an employee of its intended recipient, you are herewith notified that any dissemination, distribution or copying of this information is strictly prohibited. If you have received this information in error, please notify AAT immediately. Thank you.

AIHA ELLAP- Lab ID #100986, NY State DOH ELAP -Lab ID #11864, State of Ohio- Lab ID # 10042

Date Printed: 06/07/2013 4:24PM

AAT Project: 154692



APPENDIX F

RISK ASSESSMENT REPORT

American Environmental Consultants, LLC

Risk Assessment Report

Risk Assessor: Matthew Rodgers

Inspector Number: P-04247

Owner: Ann Arbor Housing Commission

Location: Hikone

2724 Hikone Rd. in Ann Arbor, Michigan

Inspection Date: 5/20-5/22/13

No further testing is needed due to no lead based paint or lead hazards being identified.

APPENDIX G

INTERIM CONTROLS

***LEAD IN YOUR HOME: A PARENTS REFERENCE
GUIDE***

CHAPTER 6

US EPA

Interim Controls

QUICK TIPS

- 1 There are ways you can temporarily control exposure to lead-based paint, dust, and soil. They are called interim controls.
- 2 Keep in mind interim controls will not get rid of lead hazards forever. They can, however, help cut down on the risk of exposure.
- 3 Lead dust in your home can be harmful to you and your family. It should be removed.

Safe Management of Lead-Based Paint in Your Home

Interim controls are actions you can take to reduce lead hazards in your home without hiring an abatement contractor. They are less expensive than abatement and a good alternative if you cannot afford abatement, but it is very important to remember that the results are only temporary. Nevertheless, if maintained properly, interim controls can protect you and your family for a long time. (See Chapter 7 and Appendix D for more information on performing an abatement to permanently contain or remove lead hazards.)

A list of interim controls follows. They can be used separately or together:

- ▶ Removing lead dust.
- ▶ Repainting lead-based painted surfaces.
- ▶ Repairing friction and impact surfaces.
- ▶ Preventing access to soil hazards.

Interim controls provide a useful alternative for homes that cannot be abated right away.

ADVANTAGES of Interim Controls

- 4 **Less expensive than abatement.**
- 4 **Can be implemented immediately.**

DISADVANTAGES of Interim Controls

- 8 **Lead-based paint remains in housing.**
- 8 **Continuing expense, if done regularly.**
- 8 **Requires ongoing monitoring of paint condition and dust levels.**

When Interim Controls Will NOT Work

Interim controls will not work if—

- ▶ The windows, doors, porches, or interior or exterior walls are seriously deteriorated or are subject to excessive moisture.
- ▶ The windows, doors, porches, or interior or exterior walls are not sound (which would cause the treatment to fail rapidly).

If any child in the home has an elevated blood-lead level, many states and localities require you to have the home abated by a certified contractor. Contact your state lead program contact (Appendix B) for more details.

Lead dust in your home can be hazardous to you and your family and should be removed.

Although interim controls will not rid your home of lead-based paint hazards forever, they can help you reduce the risk of exposure if you do them right and check your work often. To ensure success when you perform any type of interim control, it is recommended that you—

- ▶ Surround your work area with thick, plastic sheeting (mentioned on page 25) to avoid spreading lead dust to other parts of your home.
- ▶ Hire a certified contractor to conduct a clearance examination once you have finished your work. This is not required, but a contractor can determine if you successfully completed the interim control action.
- ▶ Check your interim control work once a year. For example, if you have performed an interim control of lead-based paint and see signs of peeling or flaking, you may need to redo the work.

Removing Dust

Dust removal is a continuing process. You begin with an initial treatment and then follow up with re-cleaning as needed. Dust removal is always a part of lead hazard control measures, whether done alone or as part of cleanup following other work.

Lead dust can be found on surfaces and in cracks throughout your home. Windows, worn floors, carpets, and upholstered furnishings seem to collect most of the lead dust. It is very hard to clean these surfaces thoroughly, and dust settles on them rapidly after they are cleaned.

Major Dust Collectors and Potential Dust Traps

Interior	Exterior
Window sills	Porch swings
Floors or steps	Window troughs
Cracks and crevices	Steps
Carpets and rugs	Exposed soil
Mats	Sandboxes
Upholstered furnishings	Window coverings
Radiators	Heating, ventilation, or air conditioners
Grates and registers	

Removing Lead Dust Inside Your Home

It is very hard to remove lead dust without specialized equipment. You will need to use a vacuum equipped with a HEPA filter combined with wet cleaning methods.

1. Vacuum the surface with a HEPA filter-equipped vacuum cleaner. This special type of vacuum will trap lead particles and prevent them from being released back into the air. A household vacuum will not do this. Remember—when you finish vacuuming—carefully empty the dust collected in the vacuum cleaner, being sure to dampen it with water first to control the spread of collected dust.
2. Wet clean exposed areas with a solution of water and an all-purpose cleaner or a cleaner made specifically for lead. Use one bucket for the cleaning solution and one bucket for rinsing. Change the rinse water frequently (at least once for each room being cleaned) and replace rags, sponges, and mops often. Clean the surface until no dust is visible. After cleaning, rinse the surface with clean water and a new sponge or cloth.



At the same time that you undertake a cleaning project, have all the drapes and curtains professionally cleaned, and replace the filters in heating and air-conditioning units. Have your rugs and carpets

Because removing lead dust from older carpets is difficult, it may be best to remove the carpets altogether.

professionally cleaned. If you cannot have them cleaned professionally at this time, clean your carpets in the following manner:

For rugs and carpets that can be folded over:

- ▶ HEPA vacuum the carpet.
- ▶ Fold the carpet over in half and HEPA vacuum the bottom side of the carpet.
- ▶ Vacuum the top side of the carpet again.
- ▶ If there is foam padding under the carpet, clean both sides of the padding.
- ▶ Vacuum the floor under the carpet.

For carpets that cannot be folded over (such as wall-to-wall carpeting):


- ▶ Vacuum the carpet in a side-to-side direction.
- ▶ Vacuum the carpet in a side-to-side direction, opposite the first direction.
- ▶ Steam clean the carpet using a solution containing detergent specifically made to reduce static between the carpet and lead dust.

For upholstered furnishings:

- ▶ HEPA vacuum each surface three to five times.

Removing Lead Dust From the Exterior of Your Home

Lead in exterior dust can be dangerous because it can be tracked inside your home. You need to remove as much dust and dirt as possible from all paved surfaces on your property (such as sidewalks, patios, driveways, and parking areas). Removing all lead dust outside your home may not be possible, but by following some simple steps you can reduce your family's exposure to exterior lead dust.



Remember—These measures need to be repeated often to maintain safe lead dust levels outside your home:

- ▶ Remove all large items, such as outdoor furniture, from the areas you are going to clean. Dampen the areas with water to control the spread of lead dust.
- ▶ Vacuum all hard surfaces with a HEPA filter-equipped vacuum cleaner. Clean all surfaces continuously until no visible dirt or dust is present.
- ▶ Carefully empty the dust collected in the vacuum cleaner, being sure to dampen it with water first to control the spread of the collected dust.

Repainting Lead-Painted Surfaces

Repainting is often used on painted surfaces that have begun to deteriorate due to problems such as structural defects or water damage. It is a good choice for walls and ceilings because they are not constantly bumped or rubbed. Repainting a surface with a lead-free paint will help to lessen lead hazards by reducing the amount of lead dust and paint chips.

It is very important that you check the surface regularly and maintain it. If properly maintained, you can expect your repainting effort to last from 4 to 10 years.


Recommendations for Repainting a Lead-Painted Surface

If you plan to repaint a lead-painted surface, take the following steps:

- ▶ Make sure that what is causing the paint to deteriorate is fixed or eliminated. This can include repairing water leaks, defective plaster, and damaged structural parts.
- ▶ Use a high-quality paint recommended by a manufacturer for the type of surface you are painting.
- ▶ Read and follow the manufacturer's instructions for applying paint.


Repairing Friction and Impact Surfaces

Friction surfaces are surfaces that are subject to abrasion, that is, rubbing or friction actions that cause wear on a surface. Common examples of friction surfaces are the parts of a window that rub when opened and closed, tight-fitting doors, cabinet doors and drawers, stairs and hand railings, and floors. When covered with lead-based paint, friction surfaces subject to abrasion can disturb lead-based paint. Friction surfaces may be treated by fixing the areas that rub together. For example, if you replace a tight-fitting door with a loose-fitting one, you will reduce the chances that the door will create lead dust.



Impact surfaces are surfaces that stick out and tend to be bumped or banged. The most common impact surfaces are doors and doorjamb, door trim, doorstops, outside corners of walls, baseboards, shoe moldings, chair rails, and stair risers. Repeated impacts can cause small chips of paint to fall to the floor and contaminate dust. You can reduce impact surface problems by placing barriers in front of the surfaces. For example, put a new chair rail on a lead-painted wall. This will lessen the damage done to the wall when a chair bumps against the rail.





How to Repair a Friction or Impact Surface


The following actions will help to reduce lead hazards from lead-painted friction and impact surfaces in your home. Remember—when performing any type of interim control—always cover work areas with thick, plastic sheeting and spray components with water to reduce dust.

- ▶ If you are repairing a window, remove the window. Wet scrape the deteriorated paint. If the window trough is badly weathered, cover with back-caulked, aluminum coil stock. Reinstall the window.
- ▶ If you are repairing a door, remove the doorstop and dispose of it properly. (See Chapter 8.) Remove the door by pulling out the hinge pins. Mist the door with water and plane the door to eliminate areas that might rub together. Reinstall the door and install a new doorstop.
- ▶ If you are repairing stairs, install a hard, cleanable covering, such as rubber tread guards. You can install carpeting on the stairs instead, but fasten it securely so that it does not cause abrasion. Repaint any railings that may have deteriorated lead-based paint. (For more information on repainting, see page 37.)



Other ways to repair friction and impact surfaces include—

- ▶ Removing and replacing shoe moldings around baseboards.
- ▶ Installing new plastic or wood corner beads to abraded outside corners.
- ▶ Removing and replacing cabinet doors, or having the paint stripped off at a professional paint stripping plant. Strip paint from drawers and drawer guides or plane impact points and repaint. Or, install rubber or felt bumpers at points of friction or impact.
- ▶ Repainting porches, decks, and interior floors.



Preventing Access to Soil Hazards

Whether the source is lead-based paint or leaded gasoline, soil that is contaminated by lead can be dangerous if children play in it or if it is tracked into your home by people and pets. If you think that your soil may be contaminated, have a risk assessor test it. A test will determine what action, if any, needs to be taken.

Never plant vegetable gardens in lead-contaminated soil. You can get lead poisoned from eating carrots and leafy vegetables grown in leaded soil.

What to Do After a Soil Lead Test

If the test results in parts per million (ppm) are . . .

It is recommended that you do the following . . .

Less than 400 ppm

Nothing

400–5,000 ppm

- Cover bare soil by planting grass, piling mulch or sand on top of it, or landscaping with sod and bushes. To keep children from playing in soil near your home (which may have higher concentrations of lead), plant bushes close to the house. In areas near children's playgrounds, cover soil with mulch and gravel piled at least 6 inches.
- Move play areas away from contaminated soil.
- Put doormats outside and inside all entryways. Remove your shoes before entering.

Higher than 5,000 ppm

Abatement (see Chapter 7 and Appendix D).

