

APPENDIX I
Photograph

Appendix I
Phase I ESA Photographs
721 North Main Street
Ann Arbor, MI



Looking west at the subject property



Looking southwest at the subject property

**Appendix I
Phase I ESA Photographs
721 North Main Street
Ann Arbor, MI**



Looking west at the southern end of the maintenance building



Looking northwest at the northern section of the maintenance building

**Appendix I
Phase I ESA Photographs
721 North Main Street
Ann Arbor, MI**



Looking north at the parking lot area



Looking southwest at former weigh scale

**Appendix I
Phase I ESA Photographs
721 North Main Street
Ann Arbor, MI**



A monitoring well located east of the maintenance building



Looking west at the former fuel dispenser island