

Appendix I
Phase I ESA Photographs
721 North Main Street
Ann Arbor, MI



Staining on concrete in paint booth of maintenance garage



Waste oil, hydraulic oil, and waste anti-freeze tanks located in the maintenance garage

**Appendix I
Phase I ESA Photographs
721 North Main Street
Ann Arbor, MI**



Looking east through the northern portion of the maintenance garage

**Appendix I
Phase I ESA Photographs
721 North Main Street
Ann Arbor, MI**



Location of waste oil UST and monitoring well east of maintenance garage

Appendix I
Phase I ESA Photographs
721 North Main Street
Ann Arbor, MI



Asbestos wrap on piping in maintenance garage



Asbestos wrap on piping in maintenance garage

**Appendix I
Phase I ESA Photographs
721 North Main Street
Ann Arbor, MI**



Miscellaneous buckets and drums in the south end of the maintenance garage



Asphalt storage area in the south end of the maintenance garage