

Appendix I
Phase I ESA Photographs
721 North Main Street
Ann Arbor, MI



Looking north through the southern portion of the maintenance garage

Appendix I
Phase I ESA Photographs
721 North Main Street
Ann Arbor, MI



Oil burning furnace on the north wall of the southern portion of the maintenance garage

**Appendix I
Phase I ESA Photographs
721 North Main Street
Ann Arbor, MI**



Looking east at the street maintenance garage (straight) and boiler/sump room (right).



Looking south along the AARR

**Appendix I
Phase I ESA Photographs
721 North Main Street
Ann Arbor, MI**



Looking north along the AARR at Summit St.



Looking east down Summit St.