

**Appendix I
Phase I ESA Photographs
721 North Main Street
Ann Arbor, MI**



Looking west at the former Standard Oil Company property



Miscellaneous paint cans and spray cans. Location of former chloride AST

Appendix I
Phase I ESA Photographs
721 North Main Street
Ann Arbor, MI



Looking south inside the wooden salt storage barn



Looking south inside the garbage barn

**Appendix I
Phase I ESA Photographs
721 North Main Street
Ann Arbor, MI**



55-gallon drum located inside the garbage barn. A label was not visible.



Empty ASTs located along the western side of the property.

**Appendix I
Phase I ESA Photographs
721 North Main Street
Ann Arbor, MI**



Miscellaneous bottles, cans, and fire extinguishers inside the maintenance building



Former chemical storage room inside the maintenance building

**Appendix I
Phase I ESA Photographs
721 North Main Street
Ann Arbor, MI**



Inside the offices of the maintenance building



Sump/skimmer for oil UST inside the maintenance garage