

**Appendix I
Phase I ESA Photographs
721 North Main Street
Ann Arbor, MI**



Looking south at the garbage barn (left) and the wooden barn (right)



Location of former fuel dispenser at fuel dispenser island

**Appendix I
Phase I ESA Photographs
721 North Main Street
Ann Arbor, MI**



Looking north, along the west side of the maintenance building and former location of 16,000 gallon AST



Looking northwest at the AARR railspur

**Appendix I
Phase I ESA Photographs
721 North Main Street
Ann Arbor, MI**



Looking southwest along the western property line and former location of former diesel fuel and gasoline ASTs



Looking north at the compressed natural gas compressor

**Appendix I
Phase I ESA Photographs
721 North Main Street
Ann Arbor, MI**



Compressed natural gas station located along Summit St.



Three 1-gallon milk cartons containing a dark liquid and soil staining

**Appendix I
Phase I ESA Photographs
721 North Main Street
Ann Arbor, MI**



Looking south along the western property line and area of former gasoline AST



Looking east at the garbage barn and wooden barn