

**Appendix I  
Phase I ESA Photographs  
721 North Main Street  
Ann Arbor, MI**



Storage room for paints and chemicals inside the maintenance garage

**Appendix I  
Phase I ESA Photographs  
721 North Main Street  
Ann Arbor, MI**



55-gallon drums of industrial cleaner

**Appendix I**  
**Phase I ESA Photographs**  
**721 North Main Street**  
**Ann Arbor, MI**



Staining on concrete in maintenance garage

Appendix I  
Phase I ESA Photographs  
721 North Main Street  
Ann Arbor, MI



Hoist system in maintenance garage



Hoist system and associated trenches in maintenance garage



**Appendix I  
Phase I ESA Photographs  
721 North Main Street  
Ann Arbor, MI**



Motor oil tanks in paint booth of maintenance garage